UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		5.	Lease Num	
		6.	SF-076958	, All. or
Type of Well	2578		Tribe Nam	-
GAS	A COLOR			
		7.	Unit Agre	ement Nam
Name of Operator	JAN 2			
BURI INGTON	nice:			
RESOURCES OIL	& GAS COMPANY CALCON			
	\&\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	8.		& Number
Address & Phone No. of Opera	tor	377 J	Albright API Well	
PO Box 4289, Farmington, NM 87499 (505) 326-9000		عملانسليد	30-045-25	
Trackies of Woll Pootage S	ec. T. R. M	10.	Field and	
Location of Well, Footage, Sec., T, R, M 790'FSL, 1615'FEL, Sec.15, T-29-N, R-10-W, NMPM				J/Basin DK
750 182, 2023 122, 200122,	•	11.	County ar	
			San Juan	Co, NM
. CHECK APPROPRIATE BOX TO IN	DICAME NAMEDE OF NOTICE	PRPORT OTHER	DATA	·
 CHECK APPROPRIATE BOX TO IN Type of Submission 	Type of Acti	on		
X Notice of Intent	Abandonment	Change of Pl		
	Recompletion	New Construc		
Subsequent Report	Plugging Back	Non-Routine		J
	Casing Repair Altering Casing	Water Shut of Conversion		an .
Final Abandonment				
			20 111,00010	711
	X_Other - Commingle			
	X Other - Commingle			
3. Describe Proposed or Comp	X_ Other - Commingle			
3. Describe Proposed or Comp	_X_ Other - Commingle			
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp	X_ Other - Commingle			rocedure.
3. Describe Proposed or Comp It is intended to comming	_X_ Other - Commingle pleted Operations gle the subject well accor	rding to the		rocedure.
3. Describe Proposed or Comp It is intended to comming	X_ Other - Commingle	rding to the		rocedure.
It is intended to comming	X Other - Commingle pleted Operations gle the subject well according to the subject well accordi	orrect.	attached pr	rocedure. 700 CCI 10 CCI 1: 53
It is intended to comming It is intended to comming 14. I hereby certify that the Signed May ale	X_ Other - Commingle pleted Operations gle the subject well according the foregoing is true and commingle Title Regulatory	orrect.	Date 10/9/0	rocedure.
3. Describe Proposed or Comp It is intended to comming	X_ Other - Commingle pleted Operations gle the subject well according the foregoing is true and commingle Title Regulatory	orrect. Supervisor I	Date 10/9/0	rocedure. 700 CCI 10 ECI 1: 58

Albright 8E

Mesa Verde/Dakota AIN: 163301 and 163302 790' FSL & 1615' FEL

Unit 0, Sec. 15, T29N, R10W Latitude / Longitude: 36° 43.29'/ 107° 52.09'

Recommended Commingle Procedure

Project Summary: The Albright 8E is a dual Mesa Verde/Dakota well drilled in 1982. Mesa Verde is currently producing 90 MCFD and has a cumulative production of 904 MMCF. The Dakota is producing 30 MCFD and has a cumulative production of 308 MMCF. This well tends to log off due to liquid loading. We plan to commingle this well in order to keep the well unloaded. This well has not been pulled since original completion. Estimated uplift is 40 MCFD for the Mesa Verde and 30 MCFD for the Dakota.

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 2% KCl water as necessary. ND wellhead and NU BOP. Test and record operation of BOP rams. Have wellhead and valves serviced at machine shop to convert to a single string wellhead (2-3/8"). Test secondary seal and replace/install as necessary.
- 3. Set a plug with wireline in the 1.78" ID SN (6422') on the Dakota tubing. Pick up 2-3/8" Mesa Verde tubing and RIH to the top of the Model R-3 packer to determine if any fill is present. If fill is present TOOH with MV tubing and remove perf'd tubing with bull plug from bottom of tubing. TIH with open end tubing and circulate any fill off the packer. TOOH laying down the 2-3/8", 4.7#, EUE Mesa Verde tubing (set at 4375').
- 4. Release Model R-3 packer with straight pickup (no rotation required). If packer will not come free, then cut 2-3/8" tubing above the packer and fish with overshot and jars. TOOH with 2-3/8", 4.7#, EUE Dakota tubing (set at 6454'). Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 5. TIH with 4-3/4" bit and a watermelon mill on 2-3/8" tubing and cleanout to PBTD at +/- 6666'. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing.
- 6. TIH with 2-3/8" tubing with an expendable check and a seating nipple on the bottom. Broach all tubing and land at approximately 6550'. ND BOP and NU single string wellhead (2-1/16" master valve). Pump off expendable check and blow well in. Return well to production.

7. Production Operations will install plunger lift.

Recommended:

Approval

Drilling Superintendent

Contacts:

Operations Engineer

Joe Michetti

Office - 326-9764

Pager - 564-7187

Sundry Required

Approved: Approved

(Regulatory Approva