

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3004525620
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Sanchez
8. Well No.	2
9. Pool name or Wildcat	Gallup
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

Gail M. Jefferson

3. Address of Operator

P.O. Box 800 Denver Colorado 80201 (303) 830-6157

4. Well Location

Unit Letter E : 1650 Feet From The North Line and 550 Feet From The West Line

Section 28 Township 29N Range 10W NMPM San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company requests permission to plug and abandon the above referenced well per the attached procedures.

If you have any technical questions please contact Carolanne Wyett at (303) 830-5578 or Gail Jefferson for any administrative concerns.

RECEIVED
AUG - 6 1996
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gail M. Jefferson TITLE Sr. Admin. Staff Asst. DATE 08-05-1996

TYPE OR PRINT NAME Gail M. Jefferson

TELEPHONE NO. (303) 830-6157

(This space for State Use)

APPROVED BY Johnny Robinson TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE AUG - 6 1996

CONDITIONS OF APPROVAL, IF ANY

* Note Pert. changes
Notify OCD in time to witness

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
3. POOH with 2 3/8" tbg. RIH with tbg and CIBP, set CIBP at 5230'. Test csg integrity to 500#. Spot 100' cement plug on top. (14 cuft cement) RIH with perf gun and shoot squeeze holes at 3420' and spot 100' cement plug inside and outside. (42 cuft cement) Pull up hole and shoot squeeze holes at ~~2392'~~ *1765-1665* and spot 100' cement plug inside and outside. (42 cuft cement) Pull up hole and spot 100' cement plugs inside at the following: 1410' to 1510' Fruitland Coal and 790' to surface. (208 cuft cement).
4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
5. Contact FMC and ship surface equipment to yard or other location per instructions.
6. Turn over to John Schwartz for reclamation.
7. Rehabilitate location according to BLM or State requirements.

Sanchez #2

Hole Size 12.250
 9 5/8" 36 lb/l K-55
 Cement 0.0 - 309.0
 Cement 0.0 - 800.0

Hole Size 8.750

7" 23 lb/l K-55 ST&C

Cement 1000.0 - 1925.0

2 3/8" lbg

Rods

Hole Size 7.075

4 1/2" liner

Cement 4710.0 - 5718.0

Perf 5288.0 - 5322.0

Frac Job 5288.0 - 5322.0

Perf 5510.0 - 5518.0

Frac Job 5510.0 - 5585.0

Acidized 5510.0 - 5585.0

PERFS

13XF 5288 - 5322

5510-18

5512-36

5550-56

5514-85

13XF

PERF

PBD = 5673'
 TD = 5718'

1650' FNL x 550' FWL, Sec 28, T29-N, R10-W

11/11 : Frac w/ 49 mgd @ 709 PM
 70 m w 8/10 TD
 @ 2000 psi, 2200 PSI
 11/11 : Frac w/ 51 mgd @ 709 PM
 70 m w 8/10 TD
 @ 2000 psi, 2200 PSI