Form 3160-5

or representations as to any matter within its jurisdiction...

UNITED STATES

FC	ORM AP	PRO'	VED	
Budget	Bureau	No.	1004-01	35

DEPART BUREAU SUNDRY NOT Do-not-use this form for propor Use "APPLICATION	5. Lease Designation and S NM-012711 6. If Indian, Allottee or Tribe	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-012711 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation			
1. Type of Well Oil Well X Well C	ther		8. Well Name and No. Lawson Gas Com	#1	
2. Name of Operator	Attention:		9. API Well No.		
Amoco Production Company	3004528344				
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area			
P.O. Box 800, Denver, Colorado 8020	Basin Fruitland Co	Basin Fruitland Coal			
4. Location of Well (Foolage, Sec., T., R., M., or Survey Des	11. County or Parish, State	11. County or Parish, State			
2435' FSL & 1080' FWL	Section 10 T30N	I R8W U	nit L San Juan, New	Mexico	
	X(S) TO INDICATE NATURE (PORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report	☐ Abandonment ☐ Recompletion ☐ Plugging Back ☐ Casing Repair		Change of Plans New Construction Non-Routine Fracturing Water Shut-off		
Final Abandonment Notice	☐ Altering Casing ☑ Other <u>Clean out</u>	Recompletion	Conversion to Injection Dispose Water results of multiple completion on Report and Log Form.)	•	
 Describe Proposed or Completed Operations (work. If well is directionally drilled, give subsu 					

Amoco Production Company requests permission to cleanout this open hole well per the attached procedure.

DECENTED OCT 2 5 1936

	** ***	
14. I hereby certify that the foregoing is true and correct Signed Patty Stalfelle	Title Staff Assistant	Date <u>10/10/96</u>
(This space for Federal or State office use)		
Approved by	Title	
Conditions of approval, if any:	A	PPROVED
Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and will	Ifully to make to any department or agency of the I	Inited States any false fictitious or fraudulent statemen

* See Instructions on Reverse Side

DISTRICT MANAGER

SJOET Well Work Procedure

Lawson GC 1

Version:

#1

Date:

October 10, 1996

Budget:

Expense/Well Repair

Repair Type:

Cleanout

Objectives:

- TOOH with existing 2 7/8" tubing and LD. 1.
- 2. TIH with work string to cleanout well to TD.
- Stabilize open hole, slightly surging the well if necessary, and flowtest. 3.
- TOOH with work string and TIH with 3 1/2" tubing and flowback. 4.
- Change tubing head and casing valves to full opening. 5.

Pertinent Information:

Location:

2435' FSL x 1080' FWL; 10-T30N, R08W

Horizon:

FT

County:

San Juan

API#:

30-045-28344

State: Lease: **New Mexico** NM-012711

Engr:

R. DeHerrera H-(303)439-7893

Well Flac:

703275

Phone:

W-(303)830-4946

Economic Information:

APC WI:

50%

Prod. Before Repair:

1750 MCFD

Estimated Cost:

\$75,000

Anticipated Prod.:

Payout:

2 Months

Prod. Before Repair

3500 MCFD

Max Cost -12 Mo. P.O.

\$502,724

Anticipated Prod.:

PV15:

Max Cost PV15:

Economics will be run on all projects that have a payout exceeding ONE year. Note:

Formation Tops: (Estimated formation tops)

Nacimento:

Ojo Alamo:

MesaVerde:

Point Lookout:

Kirtland Shale:

2743'

Mancos Shale:

Fruitland: Pictured Cliffs:

3090'

Gallup:

Lewis Shale:

Dakota:

Cliff House

Morrison:

Graneros:

Bradenhead Test Information:

BH

Test Date:

6/95

Tubing:

Casing:

INT

260

BH: 0

Time 5 min

10 min 15 min **CSG**

260

CSG

Comments:

Orig. Comp. 1/91 TD= 3084' Page 2 of 2

HIGH VOLUME WELL--DO NOT PROCEED UNTIL YOU ARE CERTAIN THAT ALL PRECAUTIONS HAVE BEEN TAKEN. CALL ME AT NUMBERS LISTED BELOW IF IN DOUBT.

- 1. MIRURT complete with 3.500" drill pipe, 4.750" drill collars and air-package.
- 2. ND tree, rig up BOP's w/cavitation capability complete with venturis on blooie lines. Test BOE. Set pump-through plug in cross nipple at 2865'. With additional joints of 2 7/8" tubing, tag fill depth. TOH with 2 7/8" tubing, laying it down. NOTE: SHOULD IT BECOME APPARENT THAT YOU CAN NOT SAFELY PULL THE TUBING WITHOUT ASSISTANCE FROM A SNUBBING UNIT; CALL ONE OUT AND RIG UP. Change pipe rams to permit running the 3.500" drill pipe.
- 3. Pick up a 6.250" mill tooth bit, 3.500" drill pipe, and 4.750" drill collars and clean out fill to total depth (3084') using air and foam. Rotate and reciprocate on bottom until hole is clean. POOH with drill pipe so bottom of tubing is above 7" casing shoe at 2822'.
- 4. Flow test well up both tubing and casing for 1 hour through 3/4" choke and record pressures every 10 minutes. Shut well in and wait for 4 hours, record pressures every 10 minutes for first hour then every hour following.
- 5. TIH with tubing and check to determine amount of fill and how difficult it is to clean up. Repeat clean out, flow test, and shut in if necessary and stabilize hole as quickly as possible to allow running tubing. Once hole is stabilized, proceed to next step. Slight surging of the well may be necessary to stabilize open hole.
- 6. Lay down drill string, change pipe rams as necessary to run the 3 1/2" tubing string. Pick up a 3 1/2" Closed End Half Mule shoe, 10' perforated sub, profile nipple and 3 1/2" tubing. Install profile nipple with retrievable plug in place and run in with the 3 1/2" tubing. Land tubing at 2990'. Profile nipple needs to be at the bottom of the tubing just above the perforated sub assembly.
- 7. ND BOE, NU tree and RDMORT. Tie well back into surface equipment, retrieve plug and bring well on line slowly in an attempt to minimize any cavitation effect. Turn over to production.

Dependent on speed of hole stabilization, I estimate this procedure to require approximately 5 days and to cost approximately \$75,000.

Tubing Head Replacement

This can be completed any time during the workover. Many of the high rate fruitland coal wells are produced through the tubing string and the tubing/casing annulus. The $7 \frac{1}{16}$ 3000# x 11" 3000# tubing heads on the wells were outfitted with flanged 2 1/8" casing valves. The threaded outlet in the head is 1 1/2" in diameter. We need an additional head with the outlets full opening and the ability to accommodate full opening casing valves. FMC is aware of our plans and is scrambling to accommodate this request.

If problems are encountered, please contact:

Robert DeHerrera (W) (303)830-4946 (H) (303)439-7893