UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry	Notices and Reports on	Wells	<i>F</i> ::1	····
		_/WLUU-12	- 191 [: 5 4	Lease Number
			٥.	SF-077092C
. Type of Well GAS		070 FARME	270N,6XM	If Indian, All. or Tribe Name
			7.	Unit Agreement Name
Name of Operator				
RESOURCES C	OIL & GAS COMPANY		0	Hall Name C Number
Dhara No of On			8.	Well Name & Number Lackey A #3R
. Address & Phone No. of Op PO Box 4289, Farmington,	NM 87499 (505) 326-9	700	9.	-
. Location of Well, Footage	Sec T. R. M		10.	Field and Pool
1730'FSL, 1455'FWL, Sec.1		M		Otero Chacra/
1,00 102, 2111 1 ,				Blanco Mesaverde
			11.	County and State
				San Juan Co, NM
2. CHECK APPROPRIATE BOX TO	INDICATE NATURE OF NO	TICE, REPOR	RT, OTHER	DATA
Type of Submission	Type	of Action		
X Notice of Intent	Abandonment		nge of Pla	ans
	X Recompletion	New	Construct	ans tion Fracturing Ef
a 3	Plugging Bacl	Non-	-Routine H	racturing
Subsequent Report		7.7 . L	ar Smir oi	L I
	Casing Repair	Wate	vorsion to	Triection
Subsequent Report Final Abandonment	Casing Repair Altering Casi	ing Con	version to	o Injection
	Casing Repair Altering Cas X Other - comm	ing Con	version to	o Injection
Final Abandonment 3. Describe Proposed or C It is intended to reco	Casing Repair Altering Cas X Other - comm	ingle Condingle	hacra form	mation and
Final Abandonment 3. Describe Proposed or C It is intended to reco	Casing Repair Altering Cas X Other - comm Completed Operations Complete the subject we	ingle Condingle	hacra form	mation and
Final Abandonment 3. Describe Proposed or C It is intended to recommingle the Mesav procedure 14. Thereby certify that Gigned May Ull	Casing Repair Altering Cas: X Other - comm: Completed Operations Omplete the subject we werde and Chacra formations Title Regu	and correct	hacra form ding to the control of th	mation and
Final Abandonment 3. Describe Proposed or C It is intended to recommingle the Mesav procedure A. Phereby certify that	Casing Repair Altering Cas: X Other - comm: Completed Operations Omplete the subject we werde and Chacra formations Title Regu	and correct	hacra form ding to the control of th	mation and he attached

O:strict I PO Box 1980, Hobbs. NM 88241-1980

District II PO Drawer DD. Artesia, NM 88211-0719

State of New Mexico Energy, Minerals & Natural Resources Departmen

Form C-102 Revised February 21, 1994 Instructions on back Submit to Appropriate District Office State Lease – 4 Copies Fee Lease – 3 Copies

OIL CONSERVATION DIVISION
PO Box 2088
Santa Fe. NM 87504-2088 12 PM 1: 54

District III 1000 Rio Brazos Rd., Azt	ec. NM 87410		San	ta Fe, NM 8	37504-2088	12 1	M 1:54	AMENDE	D REPORT
District IV PO Box 2088, Santa Fe, I	NM 87504-208	38		<u></u> .	070 50]	
	W	IELL L	OCATI	ON AND ACI	REAGE DEDIC		N PLAT		
'API Number		· F	Pool Code	B					
30-045-29528		8232	29/723	19	Otero Chacra	ı/Blan	co Mesave	rde	11 Number
'Property Code				Property					3R
7238									levation
'OGRID No. 14538	*Operator BURLINGTON RESOURCES					COMF		5808	
				¹⁰ Surface l	_ocation				County
UL or lot no. Section	Township	Range	Lot Ion	Feet from the	North/South line			st/West line	SAN JUAN
K 11	29N	10W		1730	South	14	55	West	SAN JUAN
	11 Bo	ttom H	Hole .	ocation I			Surface		County
UL or lot no. Section	Townshap	Range	Lat Idn	Feet from the	North/South line	Feet	from the E	ast/Hest line	
						<u> </u>			<u> </u>
Decicated Acres	13 Joint or Infil	11 M Consol	acation Cod	e ²⁵ Onder No.					
CH: SW/159.09 MV:S/313.55									
NO ALLOWABLE	WILL BE AS	SSIGNED	TO TH	HIS COMPLETI	ON UNTIL ALL EN APPROVED	INTER BY TH	RESTS HAVE NE DIVISIO	E BEEN CI	UNSUL IDA I ED
	OH A	NUN-517	ANDADD	UNIT TIAS DE	1		7 OPERAT		IFICATION
15		52	64.16	; *					ion contained herein is by knowledge and belief
					1		the an entre		
	İ	3	ı	2	1	Į			
4		3	i	156	1700				l
1.	1		1			02			
.62				A ST		— B	Dea	Un (ale
			-	MAR	المرابعة المرابعة	63(Signéture	19 2009	
56.	1		ı	E ALL	Jon I	56	Peggy C	ole	
1,0			1	OF OF			Printed Na		•
5	1	6	1	TEZ V	``		1	ory Supe	rvisor
				(25			Title	2-12-0	\sim
	l I						Date	1/2	
	_		_11.					YOR CEE	TIFICATION
			11				I hereby centif	y that the well	location shown on this pla actual servers made by ME
SF-C	77092-C		1,1					pervision and the best of my belia	T UE MAR 13 UVS 4-0
		11	-	10	9				
1455		11	11	10	1				4007
1			- 111			5	Date of	MBER 9	
36			{'\	SF-	077092	رم	· · · ·	Seel of Potesti	E PYYE
16			- 1,1-		7	7,07	11	186	EDWA AD
263					1.	ŭ.		12/4	METICO
l ko	1 8				į			12/2/	12/0/2
	17	12		13	1.	4		XXXX	CY / []
H	11		{'\		i		W//2/	XXX ^	TOHOU

<u>527</u>2'.08'

Lackey A #3R

Chacra Recompletion Procedure 1730' FSL, 1455' FWL K - 11 - 29N - 10W

San Juan County, New Mexico

LAT: 36 DEG 44.29'

LONG: 107 DEG 51.47'

Summary:

Lewis pay is going to be added to the existing Menefee and Point Lookout production. The Lewis will be hydraulically fracture stimulated in one stage with 200,000# 20/40 sand and a 75 quality 20# linear gel foam. Foam is used to limit the fluid damage to the Lewis by reducing liquid volumes and by aiding in the liquid recovery during the flowback.

- Comply with all BLM, NMOCD, and BR rules and regulations.
- Hold safety meetings.
- Place fire safety equipment in strategic locations.
- Inspect location and test rig anchors.
- Dig flowback pit or set flowback tank.
- Set and fill 3-400 BBL Frac tanks w/ 2% KCI water. Test and filter if necessary.

Equipment Needed:

3 -- Frac Tanks with 2% KCl water

2650 gals Acetic Acid (650 spot, 2000 breakdown)

- 1 -- 4-1/2" CIBP
- 1 4-1/2" Packer w/ Bypass
- 1 -- 4-1/2" RBP

PROCEDURE:

- 1. MIRU. Record and report SI pressures on tubing, casing, and bradenhead. Lay blowdown line and blow well down. Kill well with 2% KCl water. ND WH, NU BOP. Test and record operation of rams. NU blooie line and 2-7/8" relief line. Redress production wellhead as needed.
- 2. TOOH w/ 1-1/2" tubing set at +/- 4,561' lay down and send to the yard.
- 3. PU 4-1/2" CIBP and 2-3/8" tubing. TIH and set CIBP @ 3,600'. Load hole w/ 2% KCI water and spot to above the top perf. TOOH w/ tubing.

** All Acid to contain the following additives/ 1000 gal:

1000 gal 10% Acetic Acid
2 gal MSA II corrosion inhibitor
5% NH4CL clay control

- 5. Pressure test casing and CIPB to 3,400 psi from surface.
- 6. Correlate to CBL/CCL/GR and then perforate the Lower Lewis Shale interval with 3-1/8" HSC w/ 3125-306T charges. These are 12 gram charges with a 0.30" hole and 17.5" penetration. Shoot top down @ 1 shot per 2 feet at 120° Phase in Acetic Acid at the following depths:

2940-50, 3024-34, 3098-3108, 3182-92, 3288-98, 3354-64, 3387-97, 3428-38, 3472-82, 3538-48

RD wireline.

7. TIH with 4-1/2" RBP, on/off tool and 4-1/2" packer w/ a bypass on 2-3/8" tubiing. Set RBP at RBP setting depth.
PUH + 10 ft and set Packer. RU stimulation company and pressure test RBP and lines to 3,400 psi. Release

Lackey A #3R

Chacra Recompletion Procedure 1730' FSL, 1455' FWL K - 11 - 29N - 10W

San Juan County, New Mexico

LAT: 36 DEG 44.29'

LONG: 107 DEG 51.47'

packer, and reset packer at Packer Setting Depth. Open the bypass and circulate the acid to the top of the packer. Close the bypass. Breakdown perforations and establish an injection rate between 8 and 10 BPM with 333 gals of Acetic Acid + 5% NH4Cl **. Breakdown to the Max pressure of 3,400 psi. Release packer and RBP. Repeat for the remaining intervals.

RBP Setting		Perforation Interval
	Depth	
3,590'		3472-82, 3538-48
3,460'	3,375'	3387-97, 3428-38
3,375'	3,260'	3288-98, 3354-64
3,240'	3,060'	3098-3108, 3182-92
3,070'	2,900'	2940-50, 3024-34

- TOOH w/ RBP, Packer, and 2-3/8" tubing and stand back. 8.
- 4,400 psi. Fracture stimulate in NU appropriate wellhead isolation tool and stim co. pressure test lines to 9. 1.0 to 3.0 ppg stages @ 40 BPM constant downhole rate with 75Q N2 foamed 20# linear gel and 200,000 lbs. 20/40 mesh sand. When sand concentration begins to drop, call flush. Flush to 100' above top perf with 75Q foam. Frac is to be tagged with 3 RA Tracers. Refer to frac schedule enclosed. Maximum treating pressure is 3.400 psi.
- Record ISIP, 5, 10 and 15 min. shut-in pressure. Shut-in frac valve. RD stimulation company. Install flowback line above frac valve. Lay flowback line to dual-choke manifold and pit. Begin flowback after stimulation company has rigged down from frac valve. Open well to pit in accordance with the flowback schedule listed in the table below. Do not shut well in during flowback. When schedule dictates a larger choke size, open ball valve upstream of adjustable choke and open adjustable choke on manifold to pre-determined size listed in table and begin flowing through adjustable choke. Close ball valve upstream of positive flow bean and change out flow bean to next larger size in table. Open ball valve upstream of positive flow bean and begin flowing. Close ball valve upstream of adjustable choke and close adjustable choke.

10/64" Choke	Approximately 2 hrs.
12/64" Choke	Approximately 2 hrs.
14/64" Choke	Approximately 2 hrs.
16/64" Choke	Approximately 3 hrs.
18/64" Choke	Approximately 3 hrs.
20/64" Choke	Approximately 3 hrs.
22/64" Choke	Approximately 3 hrs.
24/64" Choke	Approximately 3 hrs.
32/64" Choke	Approximately 3 hrs.

NOTE: Follow this schedule to utilize a 24+ hour flowback. If well begins to slug or make large amounts of sand to surface, drop to next lower choke size. If well begins to taper off in liquid production (mostly N2), change to next larger choke size before time schedule dictates.

Lackey A #3R

Chacra Recompletion Procedure 1730' FSL, 1455' FWL K - 11 - 29N - 10W

San Juan County, New Mexico

LAT: 36 DEG 44.29'

LONG: 107 DEG 51.47'

air/mist. When well is sufficiently clean, gauge the Lewis interval for one hour. Obtain an accurate pitot gauge for the Lewis interval. DO CIBP @ +/- 3,600' w/ 3-7/8" flat mill on 2-3/8" tubing w/ air/mist and a minimum rate of 12 BPH mist.

- 13. CO to PBTD. TOOH w/ 3-7/8" mill and 2-3/8" 4.7# J-55 tubing.
- TIH w/ 2-3/8" 4.7# J-55 production tubing. Broach in tubing on sandline. TIH w/ one joint of 2-3/8" 4.7# J-55 tubing w/ expendable check, seating nipple, then remaining 2-3/8" production tubing. Land tubing @ +/- 4,600'
- 15. ND BOP's, NU wellhead. Pump off expendable check. Obtain a final pitot up tubing. If well will not flow on it's own, make swab run to seating nipple. If swab run is not necessary, RD and MOL.
- 16. RU Pro-Technics. Run After Frac Log across Lewis. RD Pro-Technics.

Approve: Ranc 11/13/2000	Approve: Bruce D. Bown 11-17-6	د2
Team Leader	Drilling Superintendent	

Recommend: Michael Course 11-13-2000 Approve: Many Calle Production Engineer Regulatory

Michele Quisel

Work:

324-6162

Pager:

326-8196

Home: 564-9097