

14-4010.004 P.04

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
**MERIDIAN OIL**

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1650' FSL, 990' FWL Sec. 32, T-30-N, R-8-W, NMPM, San Juan County

API # (assigned by OCD)

5. Lease Number  
B-1003

6. State Oil&Gas Lease  
B-1003

7. Lease Name/Unit Name  
Beaver Lodge Com

8. Well No.  
1

9. Pool Name or Wildcat  
Blanco Mesa Verde

10. Elevation:

Type of Submission

Notice of Intent  
 Subsequent Report  
 Final Abandonment

Type of Action

Abandonment  
 Recompletion  
 Plugging Back  
 Casing Repair  
 Altering Casing  
 Other - pay add

Change of Plans  
 New Construction  
 Non-Routine Fracturing  
 Water Shut off  
 Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to perforate and stimulate the Menefee and Lewis intervals and add to the existing Cliff House and Point Lookout.

RECEIVED

FEB 14 1994


OIL CON. DIV  
DIST. 3

RECEIVED

NOV 23 1993


OIL CON. DIV.  
DIST. 3

SIGNATURE

 (JAS) Regulatory Affairs

November 19, 1993

(This space for State Use)

Approved by 

TITLE DISTRICT OIL & GAS INSPECTOR, DIST. #3

Date DEC - 7 1993

Beaver Lodge Com #1  
 SW/4 Section 32, T-30-N, R-08-W  
 San Juan Basin, NM  
 Menefee/Lewis Pay-add

**RECEIVED**

FEB 14 1994

OIL CON. DIST.

☛ Contact BLM and NMOCDC prior to performing work on this well  
 Comply with all BLM, NMOCDC, and MOI rules and regulations.

1. Test location rig anchors and repair if necessary. Blow down tubing. MIRU. NU BOP, blooie line, and relief line. **Be prepared to call for 5200' 2-7/8" slimhole fracstring if casing does not test to 3000 psi in Step 8.**
2. Install 8 X 400 bbl tanks and fill with 2% KCl water for fracture stimulation. Add 5 #'s biocide/tank before filling. Place fire and safety equipment in strategic locations.
3. Pressure test BOP for 15 minutes. TOOH with 160 jts. of 2-3/8" tubing and stand back. Visually inspect and replace any bad joints. TIH with 3-7/8" bit and 4-1/2"-10.5# casing scraper on 2-3/8" workstring and clean out to PBTD @ 4979'. TOOH.
4. RU wireline. Set drillable BP above Cliffhouse @ 4140' (**\*check for fluid level when GIH and load as needed prior to running logs**). Run GR-CBL-CCL and CNL in 4-1/2" longstring from BP to 3000' (approximate top Lewis perf). Cement top is estimated to be @ 3450' by a temperature survey. Evaluate GR-CBL-CCL and CNL. Run copy of logs to office to evaluate.
5. PU 4-1/2" pkr on 2 jts tbg and set. Pressure test BP and csg to 3800 psi. If csg does not pressure test, hunt leaks. Squeeze procedure will be provided if needed. 4-1/2" csg may be pulled and replaced if needed.

**Squeeze Work to Cover Lewis if Needed**

6. Perforate 4 squeeze holes @ approximately 3400' (based on CBL) with short penetration tbg puncher, through 4-1/2" longstring but not through 7" intermediate casing.
7. Open intermediate valve and pump down 4-1/2" casing and establish rate through perms while monitoring flow or blow out intermediate valve. PU 4-1/2" cement ret. on workstring and set @ 3350', sting in, establish rate and flow out intermediate valve. Squeeze w/ 500 sx "Class H" (includes 50% excess) and additives until cement is observed out intermediate valve. Sting out, reverse out. TOOH.
8. PU 3-7/8" bit, collars, and 2-3/8" tbg and drill out cement and retainer. Push junk to BP @ 4140'. Close rams and pressure test csg. to 3000 psi for 15 minutes\*. Drill BP @ 4140' and clean out to PBTD @ 4979'. TOOH.  
*\*If casing does not test, notify office with leakoff and pressures, and prepare to locate leaks. Additional squeeze procedure may or may not be required. If, after confirming casing integrity with office, proceed.*
8. PU 3-7/8" bit, collars, and 2-3/8" tbg and drill out cement and retainer. Push junk to BP @ 4140'. Close rams and pressure test csg. to 1000 psi for 15 minutes\*. TOOH. PU pkr on 2 jts tbg and test csg to 3800 psi for 15 minutes. (Continued From Step 5) PU bit and collars and drill BP @ 4140' and clean out to PBTD @ 4979'. TOOH.
9. RU wireline. Set RBP @ 4700'. Spot 10' of sand on RBP. TIH w/4-1/2" pkr and set @ 4650'. Pressure test RBP to 3800 psi for 15 minutes. Unseat pkr and spot 200 gal. of inhibited 7-1/2% nCL w/ iron sequestering agent across perf zone. TOOH.

10. RU wireline. Perforate the following Menefee intervals, with a 3-1/8" @ 2 SPF (90 - 180 degree phasing).  
4360', 4386', 4406', 4432', 4438', 4445', 4464', 4488', 4498', 4503', 4508', 4515',  
4520', 4536', 4540', 4546', 4574', 4591', 4596', 4601', 4609', 4646', 4658', 4666',  
24 intervals - Total 48 holes
11. TIH with 2-3/8" workstring and 4-1/2" packer. Set packer @ 4340' (above Menefee, below Cliffhouse) and prepare to breakdown perforations.
12. RU stimulation company. Breakdown and balloff w/ 1200 gallons of 7-1/2% HCl @ 4-10 bbl/min. with 1gal/1000 gal clay control, 4/1000 silt suspender, 1/1000 inhibitor and 5/1000 sequestering agent. Drop a total of 48-7/8" RCN ball sealers spaced evenly throughout the job w/ 5 ball slugs every 10 balls dropped. Record injection rate and all breakdown pressures throughout job.
13. Release packer, TIH and knock off ball sealers to top of sand on RBP. Reset pkr @ 4340'.
14. RU Tefteller and run 48 hr pressure bomb with well SI to pkr SN. Leave well SI for 24 hrs and record surface pressures every 1/2 hr. TOOH w/ bomb.
15. PU 4-1/2" straddle packer (Isolation Liner) on 2-3/8" workstring and TIH. Set Straddle Packer to overlap Cliffhouse perms @ 4156' to 4296'. Bottom packer element set @ 4320' and top element @ 4130' +/- 10'. TOOH.
16. PU 4-1/2" pkr on 2 jts 2-7/8" N-80 tubing and set.
17. RU stimulation company. Hold safety meeting. Pressure test surface lines to 4800 psi (1000 psi over maximum allowable treating pressure but no greater than working pressure of surface lines). Maximum treating pressure is 3800 psi. Fracture stimulate well w/ 30 # X-Link Gel according to attached procedure.
18. TIH w/ straddle packer retriever on 2-3/8" workstring and retrieve straddle packer. TOOH & LD.
19. RU wireline. Set RBP above Cliffhouse @ 4100'. Spot approximately 10' of sand on top of RBP w/wireline bailer.
20. TIH w/ 4-1/2" packer and set @ 4000'. Pressure test BP to 3800 psi for 15 minutes. Release packer and spot 400 gallons of inhibited 7-1/2% HCL across Lewis interval. TOOH.
21. RU wireline. Perforate the following Lewis intervals, with a 3-3/8" HSC @ 2 SPF (90-180 degree phasing).

Approximate Perforations: 3200'-3800'.

Actual Perforations will be picked  
from CNL when run.

22. TIH with 2-3/8" workstring and 4-1/2" packer. Set packer @ approximately 3100' and prepare to breakdown perforations.
23. RU stimulation company. Hold safety meeting. Pressure test surface lines to 4800 psi (1000 psi over maximum allowable treating pressure but no greater than working pressure of surface lines). Maximum treating pressure is 3800 psi. Breakdown and balloff w/ 1200 gallons of 7-1/2% HCl @ 4 bbl/min. with 1gal/1000 gal clay control, 4/1000 silt suspender, 1/1000 inhibitor and 5/1000 sequestering agent. Drop a total of (2X # of perforations) 7/8" RCN ball sealers spaced evenly throughout the job w/ 5 ball slugs every 10 balls dropped. Displace w/ Frac fluid. Record injection rate and all breakdown pressures throughout job.


RECEIVED


FEB 14 1994

oil corp.

24. Release packer, TIH and knock off ball sealers to top of sand on RBP. TOOH w/ packer.
25. PU 4-1/2" pkr on 2 Jts 2-7/8" N-80 tubing and set.
26. RU stimulation company. Hold safety meeting. Pressure test surface lines to 4800 psi (1000 psi over maximum allowable treating pressure but no greater than working pressure of surface lines). Maximum treating pressure is 3800 psi. Fracture stimulate well w/ 30# XL and slick water according to attached procedure. Shut down during Pad stage to determine ISIP. If pressure is at 0 psi within 5 minutes, cut flush by 50%, else flush w/ 80%.
27. Immediately flow back well until returns diminish. Release packer TOOH.
28. TIH w/notched collar or retrieving tool w/ SN (do not run string float) on 2-3/8" workstring and reverse out to upper RBP until sand returns are clean and water production is minimal. Obtain pitot gauge. PU to top perf and SI well.
29. RU Tefteller and run 48 hr pressure bomb with well SI to pkr SN. Leave well SI for 24 hrs and record surface pressures every 1/2 hr. TOOH w/ bomb.
30. Clean well out to RBP. Obtain pitot gauge. Release RBP and TOOH.
31. TIH with retrieving head on workstring and reverse out to lower bridge plug. Obtain pitot gauge. Retrieve bridge plug. TOOH.
32. TIH with 2-3/8" production tubing and SN one joint off bottom of string. CO to PBTD @4978'. When fluid production becomes negligible, land tubing at 4945'. Obtain final pitot gauge.
33. ND BOP. NU wellhead. RDMO.

ORIGINAL SIGNED IN FILE

  
\_\_\_\_\_  
J. A. Howieson

  
\_\_\_\_\_  
A. Smith

Vendors:

Packer Rental & Bridge Plugs.  
Wireline Services:  
Stimulation:

(Schlumberger)  
(Schlumberger)  
(BJ)

DBJ  
JAS/jas 

c:\win\pro\beavr.doc

**RECEIVED**  
FEB 14 1994  
OIL CON. DIV  
DIST. 3