

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

078107

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico Federal "L"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Undesignated


11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 33, T-30-N, R-15-W

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back or to retest a well.
Use "APPLICATION FOR PERMIT—" for such proposals.)



1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Sunray DX Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 1416, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1980' FEL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5351 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Plug & Abandon

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Present PBDT 4255'.
2. Top of cmt behind 4 1/2" prod csg approx @ 3300' by calculation. 8 5/8" surface csg set @ 164' w/100 sxs cmt circulated to surface. 4 1/2" prod. csg. set @ 4331' w/225 sxs cmt Perfs @ 4136'-4238'.
3. Load hole w/mud.
4. Cut off 4 1/2" csg @ approx 3200'. Pull prod. csg. Keep hole loaded w/mud.
5. Place 20 sxs cmt plug (4010'-4255') to cover perfs.
6. Place 10 sxs cmt plug (3170'-3230') in & out of 4 1/2" stub.
7. Place 17 sxs cmt plug (134'-194') in & out of 8 5/8" csg.
8. Set 10 sx cmt plug @ surface.
9. Install dryhole marker.
10. Remove surface equipment & clean up location.

RECEIVED

NOV 17 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED B.F. Brawley

TITLE District Engineer

DATE 11-14-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NOV 17 1966
John R. Adams
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side