

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)\*Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 030362-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico Federal "P"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 30, T-30-N, R-15-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	14. PERMIT NO.
2. NAME OF OPERATOR Surray DX Oil Company	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5252 DF
3. ADDRESS OF OPERATOR P. O. Box 1416, Roswell, New Mexico	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2052' FNL & 756' FEL	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Plug &amp; Abandon

☐  
☐  
☐  
☐  
☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Present PBTD @ 4115'.
2. Top of cmt behind 5 1/2" prod. csg. @ 3400'. 8 5/8" surf. csg. @ 140' w/100 sx cmt circ. to surface. Open hole prod. zone @ 3960'-4115'.
3. Load hole w/mud.
4. Cut off 5 1/2" csg @ approx 3300'. Pull prod. csg. Keep hole loaded w/mud.
5. Place 50 sx cmt plug (3904'-4115') to cover perms.
6. Place 12 sx cmt plug in & out of 5 1/2" stub (3270'-3330').
7. Set 17 sx cmt plug in & out of 8 5/8" surf csg (110'-170').
8. Set 10 sx cmt plug @ surface.
9. Instal dryhole marker.
10. Remove surface equipment and clean up location.

18. I hereby certify that the foregoing is true and correct

SIGNED

*B. F. Brawley*

B. F. Brawley

District Engineer

DATE

11-14-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side