| NO. OF COPIES RECEIVED | 1, |
|---|--|
| DISTRIBUTION | Form C-103 Supersedes Old |
| SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION | C-102 and C-103 Effective 1-1-65 |
| FILE | |
| U.S.G.S. | 5a, Indicate Type of Lease |
| LAND OFFICE | State Fee X |
| OPERATOR 1913 | 5. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS OF COMMITTED THE STATE OF PROPOSALS TO DELLE OR TO DEEPEN OR PLUG BACK TO ANY FERENT ASSENVOIRE USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH AROPOSALS.) | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A THE FERENT RESERVOIR USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. OIL OIST. OIL DIST. 2. Name of Operator | 7. Unit Agreement Name 8. Farm or Lease Name |
| Consolidated Oil & Gas, Inc. | Clayton |
| 3. Address of Operator | 9. Well No. |
| 1860 Lincoln Street, Denver, Colorado 80203 | 1 - 2 |
| 4. Location of Well NI 000 South 1850 | 10. Field and Pool, or Wildcat Basin-Dakota & Flora |
| UNIT LETTER N 990 FEET FROM THE South LINE AND 1850 FEET FROM | Vista-Gallup Pools |
| THE West LINE, SECTION 2 TOWNSHIP 30N RANGE 12W NMPM | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| 5781 KB | San Juan |
| Check Appropriate Box To Indicate Nature of Notice, Report or Ot | her Data |
| NOTICE OF INTENTION TO: SUBSEQUEN | T REPORT OF: |
| PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK | |
| PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS: | ALTERING CASING PLUG AND ABANDONMENT |
| PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB | |
| OTHER | |
| OTHER | |
| 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including | g estimated date of starting any propose |
| work) SEE RULE 1903. T.D. 6701!. Production casing 5-1/2! 15.5# J-55 se | |
| with 320 sx around shoe, 340 sx through stage collar at 4731' and 150 s | sx through stage collar |
| | 4 1500 11001 1 |
| at 2201'. TOC for first stage was 4578'. Dual completion: Dakota pe | rfs 6580-6680' and |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and | rfs 6580-6680' and l Gallup produced |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 | rfs 6580-6680' and d Gallup produced 525'. A casing failure |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall | rfs 6580-6680' and d Gallup produced 525'. A casing failure |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 | rfs 6580-6680' and d Gallup produced 525'. A casing failure |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. | rfs 6580-6680' and defined and selection of the selection |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o | rfs 6580-6680' and defined and selection of the selection |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. | rfs 6580-6680' and defined and fallup produced 525'. A casing failure dup quit producing and ff as close to Model D |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. | rfs 6580-6680' and defended for the following failure and defended for the following and for the following and defended for |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entr Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to lo | rfs 6580-6680' and def Gallup produced 525'. A casing failure dup quit producing and ff as close to Model Desire of Gallup and cate leak. |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entr Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to lo 4. If feasible, set packer above casing leak and squeeze cement with 1 | rfs 6580-6680' and def Gallup produced 525'. A casing failure dup quit producing and ff as close to Model Desire of Gallup and cate leak. |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entr Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to lo 4. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. | rfs 6580-6680' and def Gallup produced 525'. A casing failure up quit producing and ff as close to Model D y into Gallup and cate leak. |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to log. 4. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. 5. Pull tools, run one string of tubing and return well to production with 1 it may be necessary to run a scab liner. | rfs 6580-6680' and def Gallup produced 525'. A casing failure up quit producing and ff as close to Model D y into Gallup and cate leak. |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. Run casing inspection log to determine condition of casing and to lode. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. Pull tools, run one string of tubing and return well to production with commingled. | rfs 6580-6680' and def Gallup produced 525'. A casing failure tup quit producing and ff as close to Model D y into Gallup and cate leak. 100 sx. If not feasible, th Gallup and Dakota |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to log. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. 5. Pull tools, run one string of tubing and return well to production with commingled. With approvals, plan to commence work immediately or by November | rfs 6580-6680' and def Gallup produced 525'. A casing failure tup quit producing and ff as close to Model D y into Gallup and cate leak. 100 sx. If not feasible, th Gallup and Dakota |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. Run casing inspection log to determine condition of casing and to lode. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. Pull tools, run one string of tubing and return well to production with commingled. | rfs 6580-6680' and def Gallup produced 525'. A casing failure tup quit producing and ff as close to Model D y into Gallup and cate leak. 100 sx. If not feasible, th Gallup and Dakota |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut of packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entry Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to log. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. 5. Pull tools, run one string of tubing and return well to production with commingled. With approvals, plan to commence work immediately or by November | rfs 6580-6680' and d Gallup produced 525'. A casing failure up quit producing and ff as close to Model D y into Gallup and cate leak. 100 sx. If not feasible, th Gallup and Dakota |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entr Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to lo 4. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. 5. Pull tools, run one string of tubing and return well to production wincommingled. With approvals, plan to commence work immediately or by November 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. | rfs 6580-6680' and d Gallup produced 525'. A casing failure up quit producing and ff as close to Model D y into Gallup and cate leak. 100 sx. If not feasible, th Gallup and Dakota |
| Gallup perfs 5954-5961'. In September, Dakota produced 1120 Mcf and 10,932 Mcf. Tubing: 1-1/2" IJ to 5932' and 1-1/2" IJ in Model D at 6 has probably occurred opposite Menefee (below 3818') because the Gall drilling mud was found in Gallup tubing. 1. Pull both tubing strings. If Dakota string is stuck from sand, cut o packer as possible to recover tubing. 2. Run retrievable bridge plug above Gallup perfs to prevent fluid entr Dakota zones from leak. 3. Run casing inspection log to determine condition of casing and to lo 4. If feasible, set packer above casing leak and squeeze cement with 1 it may be necessary to run a scab liner. 5. Pull tools, run one string of tubing and return well to production wincommingled. With approvals, plan to commence work immediately or by November 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. | rfs 6580-6680' and d Gallup produced 525'. A casing failure up quit producing and ff as close to Model D y into Gallup and cate leak. 00 sx. If not feasible, th Gallup and Dakota 15, 1973. |