Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

5.	Lease Serial No.
	NMSF - 078387-A

SUNDRY Do not use the abandoned we	NMSF - 078387-A 6. If Indian, Allottee or Tribe Name							
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well	8. Well Name and No. / KERNAGHAN 18 1							
Name of Operator AMOCO PRODUCTION COM		MARY CORLE E-Mail: corley			9. API Well No. 30-045-10042			
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (Ph: 281.366. Fx: 281.366.	include area code 4491 0700)	10. Field and Pool, or Exploratory BLANCO MESAVERDE				
4. Location of Well (Footage, Sec., 7			11. County or Parish, and State					
Sec 33 T31N R8W Mer SESV		SAN JUAN COUNTY, NM						
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE 1	NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	F ACTION							
Notice of Intent ■	☐ Acidize	☐ Deepe	en	☐ Production (Start/Resume)		■ Water Shut-Off		
_	☐ Alter Casing	☐ Fractu	re Treat	□ Reclama	tion	■ Well Integrity		
☐ Subsequent Report		☐ New (Construction	☐ Recomp	lete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐ T		☐ Tempora	rily Abandon			
	☐ Convert to Injection	ion		isposal				
If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f Amoco Production Company attached procedure and wellb	rk will be performed or provide operations. If the operation re- pandonment Notices shall be fil- inal inspection.) respectfully request permi	the Bond No. on f sults in a multiple ed only after all red	ile with BLM/BIA completion or rec quirements, include	A. Required sub ompletion in a n ding reclamation	sequent reports shall be ew interval, a Form 316 , have been completed,	filed within 30 days 0-4 shall be filed once and the operator has		
					THE BANKS AND SERVICE OF THE SERVICE	201 Derived		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission For AMOCO PRO Committed to AFMS	DUCTION COM	ANY, sent to t	he Farmingto	1	STEZE		
Namc (Printed/Typed) MARY CO	,	Title AUTHO	RIZED REPRE	SENTATIVE				
Signature		Date 07/31/2001						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By		Title		Date				
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conduct the applicant the app	Office		,					
m: 1 1011 0 0 0 : 1001 1 17:1 13	TT C C C .: 1010 1 '4	<u>C</u>	and have a series of the series	d	l	gaanay of the United		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Kernaghan B #1 Workover Procedure

Procedure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. Tag for fill, tally OH, & visually inspect 2-3/8" production tubing currently set at 5534'.
- 6. RU WL unit. Run GR log across MV interval from 4800' 5550'.
- 7. RIH with tubing-set CIBP. Set CIBP at 5075'. Load the hole with 2% KCL. POOH.
- 8. RU WL unit. Run CBL across the Cliffhouse interval from 4800' 5075'.
- 9. Perforate squeeze holes at 4980' (subject to change based on CBL results).
- 10. Set Cement retainer at 4950'. Sting into retainer and perform squeeze job as per Schlumberger design. Attempt to lift into the 7" casing.
- 11. TIH with tubing and mill. Drill out cement and cement retainer to 4990'. Pressure test squeeze holes to 500 psi.
- 12. RU WL unit. Run CBL from 4000' 5075' to locate the cement top.
- 13. Backoff the 4-1/2" casing at the top of the cement. TOH and LD 4-1/2" casing. Note: Remaining 4-1/2" casing will be left in the well as a production liner.
- 14. TIH with tubing & 7" packer. Set packer 50' above 4-1/2" liner top & pressure test 4- $\frac{1}{2}$ " liner top to 500 psi to verify the liner lap has pressure integrity. Unseat packer & TOH.
- 15. Set 7" CIBP 50' above 4-1/2" liner top. TIH with 7" packer and locate casing leak in the 7" casina
- 16. Squeeze 7" casing leak as per Schlumberger design.
- 17. TIH with tubing and 7" mill. Drill out cement and pressure test squeeze to 500 psi. Drill out 7" CIBP. TOH.
- 18. TIH with tubing and 4-1/2" mill. Drill out 4-1/2" CIBP at 5075'.
- 19. RU WL unit. RIH and set 4-1/2" CIBP above the Point Lookout at depth to be determined after analyzing GR log results.
- 20. Perforate Menefee formation with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge.

Menefee Perforations, 2 spf

To be determined after logging

- 21. RIH with $3-1/2" \times 2-3/8"$ tapered frac string and a 4-1/2" packer. Set packer at 5175'.
- 22. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with 70Q N2 foam fracture stimulation according to Schlumberger design.
- 23. Flowback frac immediately.
- 24. Release packer and TOH with packer and frac string.
- 25. RU WL unit. RIH and set 4-1/2" CIBP at 5090'.
- 26. Perforate unstimulated Cliffhouse formation (4990' \sim 5060') with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge.

Cliffhouse Perforations, 2 spf


To be determined after logging

27. RIH with $3-1/2" \times 2-3/8"$ tapered frac string and a 4-1/2" packer. Set packer at depth to be determined after logging.

- 28. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with 70Q N2 foam fracture stimulation according to Schlumberger design.
- 29. Flowback frac immediately.
- 30. Release packer at TOH with packer and frac string.
- 31. TIH with tubing and mill. Drill out 4-1/2" CIBP's and cleanout fill to the top of tubing fish at 5555'. Blow well dry.
- 32. Rabbit tubing and RIH with 2-3/8" production tubing. Land 2-3/8" production tubing at 5475'.
- 33. ND BOP's. NU WH. Test well for air. Return well to production.

Kernaghan B#1

Sec 33, T31N, R8W API#: 10-045-10042



NOTES:

```
1) Detailed perforations:
```

CH: 5116' - 5120' (4 spf), 5130' - 5134' (4 spf), 5144' - 5152' (2 spf) PL: 5490' - 5498' (2psf), 5530' - 5534' (4 spf), 5554' - 5558' (4 spf),

5579' - 5587' (2 spf)

2) Fish details:

9' cutoff jt of 2-3/8" tbg 28' jt of 2-3/8" tbg 3-7/8" bit and bit sub

updated: 1/11/01 jad