Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. APR 2002					SF-078336B	
					6 1 Indian, Allotted	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side No. CON. DIV					7. If Unit or CA/Ag	reement, Name and/or No.
1. Type of Well		Fig. Col	DIGIT. 3	8. Well Name and N		
Oil Well Gas Well Ot 2. Name of Operator	_\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			BARRETT LS 3		
BP AMERICA PRODUCTION	CHERRY HLAV E-Mail: hlavacl@l		9. API Well No. 30-045-10487			
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700			10. Field and Pool, or Exploratory BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., 1	n)			11. County or Parish	and State	
Sec 20 T31N R9W NESW 15				SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE N	ATURE OF	MOTICE, RE	PORT. OR OTHE	ER DATA
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent ■	☐ Acidize	☐ Deepen		☐ Producti	on (Start/Resume)	D West City Com
	☐ Alter Casing		re Treat Reclam		•	□ Water Shut-Off
☐ Subsequent Report	☐ Casing Repair	□ New Co	onstruction	☐ Recompl		□ Well Integrity☑ Other
☐ Final Abandonment Notice	□ Change Plans	□ Plug and Abandon			rily Abandon	Z Other
	☐ Convert to Injection	□ Plug Ba	☐ Plug Back		Water Disposal date of any proposed work and approximate duration thereof.	
BP America respectfully reque Menefee and Lewis Shale forn		erde Pooi as per	the attached	procedure.		
14. I hereby certify that the foregoing is	rue and correct.		 _	·		·
	For BP AMERICA PRO	10876 verified by 1 ODUCTION COMF	the BLM Well ANY, sent to	Information S	ystem on	
Name (Printed/Typed) CHERRY H	/ 1 /	Hypn Titl			ESENTATIVE	
0.	, – J				LOCITIVE L	
Signature (Electronic Su		Dat	00,21,20			
J. P. 90 . 15	THIS SPACE FO	R FEDERAL O	OR STATE (OFFICE USI	: 	
Approved By /s/ Jim I	Approval of this notice does		Title Pet	r. En	g Date	4/2/02
hich would entitle the applicant to conduct	able title to those rights in the s	subject lease	Office	BLM	FFO	,
tle 18 U.S.C. Section 1001 and Title 43 U	S.C. Section 1212, make it a cr	rime for any namon I	rnousia el 1			


Barrett LS #3 Payadd Procedure Sec 20, T31N, R9W

API#: 30-045-10487

- 1. Check anchors. MIRU workover rig.
- 2. If necessary, kill with 2% KCL water. Nipple down WH. NU BOPs.
- 3. Tag for fill and tally OH with 2-3/8" production tubing currently set at 5868'. Visually inspect tubing while POOH.
- 4. TIH with bit and scraper for 4 1/2" casing to 5600'.
- 5. TIH with tubing-set RBP. Set RBP at 5150'. Load hole with 2% KCL.
- 6. Pressure test casing to 1500 psi. Unset RBP and POH.
- 7. RIH with CIBP and 3-1/8" casing guns (2 SPF 120 deg phasing) with Schlumberger's Prospector, select-fire charge. Set CIBP at 5590'. Perforate Menefee and Lewis shale (correlate to GR log).
- 8. RIH with 2-7/8" frac string with retrievable packer. Set packer at 5275'.
- 9. RU frac equipment. Use 2% KCL-N2 foam in fracture stimulation.
- 10. Frac Menefee according to pump schedule.
- 11. Flowback frac fluid immediately.
- 12. Release packer and POOH with frac string.
- 13. RIH and set CIBP at 5150'.
- 14. Breakdown each Lewis perforation interval with hydrochloric acid.
- 15. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 16. Frac the Lewis Shale according pump schedule.
- 17. Flowback frac fluid immediately.
- 18. TIH with tubing and bit. Cleanout fill and drill bridge plugs set at 5150' and 5590'. Clean out fill to PBTD at 5931'. Blow well dry at PBTD.
- 19. RIH with 2-3/8" production tubing and land at 5870'.
- 20. Swab water from the tubing with the sandline.
- 21. ND BOP's. NU WH. Test well for air. Return well to production.

Barrett LS 3

Sec 20, T31N, R9W API #: 30-045-10487



TD: 5958'

updated: 03/05/02 az