Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED				
Budget Bur	eau No.	1004-0135		
		31, 1993		

SUNDRY I	NOTICES	AND	REPORTS	ON WELLS
----------	---------	-----	---------	----------

Do not use this form for proposals to o	drill or to deepen or reentry to a different reservoir. FOR PERMIT - " for such proposals	SF-076337 6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other		8. Well Name and No.
2. Name of Operator	Attention:	Heath Gas Com /P/ 1
Amoco Production Company	Patty Haefele	9. API Well No.
3. Address and Telephone No.		3004523941
P.O. Box 800, Denver, Colorado 80201	(303) 830-4988	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Desc	cription)	Basin Dakota Gas
870' FSL 790' FWL	Sec. 31 T 30N R 9W SE/4 SW/4	11. County or Perish, State
CHECK ADDDODDIATE D	0.4.1. TO 11.01.01.01.01.01.01.01.01.01.01.01.01.0	San Juan New Mexico
	OX(s) TO INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other (Note: Rep. Recompleti	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water ort results of multiple completion on Well Completion or on Report and Log form.
Please contact Patty Haefele (303) 83	to abandon the subject well per the attached procedu	re.
	DECEIV Mar - 6 199 OIL CON. D DIST. 3	
14. I hereby certify that the foregoing is true and correct Signed Patty Walkelle	Title Business Ass	ociate Dete 02-22-1995
(This space for Federal or State Office use)		
Approved by Conditions of approval, if any:	Title	APPR@VED FEBZ 1995
Title 18 U.S.C. Section 1001, makes it a crime for any pareon to	brancingly and will the same to the same t	(F)

DISTRICT MANAGER

PXA Procedures Heath Gas Com P #1

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- 3. POOH with 2 3/8" tbg. Run short string CBL to determine TOC. RIH with tbg and cement retainer, set retainer at 6600'. Test casing integrity to 500#. Squeeze perfs at 6656' to 6741' with 209.917 cuft cement. Pull out of retainer and spot cement plug to 5740' with 81.445 cuft cement.
- 4. Depending where TOC is be sure the following formations are covered inside and outside with 100' of cement 50' above the formation to isolate formations:

Mesa Verde at 3918' Charcra at 3277' Pictured Cliffs at 2272' Fruitland at 2063' Ojo Alamo at 1063' and 348' to surface

(estimated 80.371 cuft cement inside casing and 174.00 cuft cement outside casing)

- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

HEATH GAS COM P 001 Location - 31M - 30N - 9W Basin Dakota Orig.Completion - 4/81 LAST FILE UPDATE - 2/90 -371 Ex (1) 1:30 Z BOJ OF 9,625 IN OD CSA 298 EL AT 1990 PC AT 2295 BOT OF 7,0 KING D CSA 2694/535 SKS CHACRA AT 3860 MY AT 3930 GP AT 5790 GRAN DK AT 6630 SPF PERF 6656-6661-FRAC 47M GAL FLUID 139M# SND DK AT 6715 6714-6741-BOT OF 2.375 IN OD TBG AT 6730 6810-6816-FRAC 69M GAL GEL SOM# SND CIBP AT 8800 , 6834-6855-PBTD AT 6859 FT. TOTAL DEPTH 6862 FT. BOT OF 4.5 IN OD CSA 6862 W/460 SK3, K-55 CASING FILENAME: 04523941 LOWER PERFORATIONS 6810-6855 PERFED 7/85