

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

5. Lease Number  
SF-078200-B  
6. If Indian, All. or  
Tribe Name

2. Name of Operator

7. Unit Agreement Name

**BURLINGTON**  
**RESOURCES**

OIL & GAS COMPANY

RECEIVED  
OCT 5 1998

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

Well Name & Number

Riddle B #1R

4. Location of Well, Footage, Sec., T, R, M

6 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM

OIL CON. DIV.  
DIST. 3

9. API Well No.

30-045-26426

10. Field and Pool

Blanco Mesaverde

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - tubing repair

13. Describe Proposed or Completed Operations

It is intended to repair the tubing on the subject well according to the attached procedure.

RECEIVED  
PLM  
93 SEP 24 PM 3:13  
O/O Farmington, NM

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (MEL5) Title Regulatory Administrator Date 9/24/98  
TLW

(This space for Federal or State Office use)

APPROVED BY /s/ Duane W. Spencer Title \_\_\_\_\_ Date OCT - 1 1998

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMCCD

**Riddle B #1R**  
**Mesaverde**  
**1735'FNL, 1775' FEL**  
**Unit G, Section 27, T-30-N, R-10-W**  
**Latitude / Longitude: 36° 47.1359' / 107° 52.1045'**  
**DPNO: 54031A**  
**Tubing Repair Procedure**

CAUTION: THIS WELL PREVIOUSLY HAD H<sub>2</sub>S. CURRENTLY, THE WELL IS BEING TREATED AND H<sub>2</sub>S LEVELS ARE AT ZERO PPM.

1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. **Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS.** Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
3. Mesaverde, 2-3/8", 4.7#, J-55 tubing is set at 5367'. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) PBTD should be at +/- 5414'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
4. If fill, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below perforations, cleaning out with air/mist. **NOTE: When using air/mist, minimum mist rate is 12 bph.** If scale is present, notify Operations Engineer and determine method for removing scale from casing and perforations.
5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then 1/2 of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
6. Land tubing at 5300'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Lutey  
Operations Engineer

Approved: Bruce V. Boyer 9.6.99  
Drilling Superintendent

Operations Engineer: Mary Ellen Lutey  
Office - (599-4052)  
Home - (325-9387)  
Pager - (324-2671)