#### UNITED STATES

# DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED BLM

		<b></b> 1 1	
Sundry	y Notices and Reports on Wells	58 NOV 24 PM 2	
		070 FARMSET PTR3	umber 16-D
Type of Well		. 🔪	All.
GAS		Tribe N	ame
	GE COLOR	7. Unit Ag	reement 1
Name of Operator	WE TO THE STATE OF	3	
BURLINGTON	LEC , DEC ,		
RESOURCES	OIL & GAS COMPANY		
Address & Phone No. of (	Operator	8. Well Name Woodrive	me & Numl er #1R
	n, NM 87499 (505) 326-9700	9. API Wel	
		30-045-	
Location of Well, Footage 1450'FSL 1555'FWL, Sec.		10. <b>Field</b> as Mesavere	
1430 rsu 1333 rwu, sec.	5, 1-30-N, R-3-W, NMEN	11. County	_
		=	n Co, NM
Subsequent Report Final Abandonmen	rt Plugging Back Non Casing Repair Wat	Construction Routine Fracturiner Shut off Version to Injecti	
Final Abandonmer	rt Plugging Back Non Casing Repair Wate nt Altering Casing Con- _X_ Other -	-Routine Fracturin er Shut off	
Final Abandonmer . Describe Proposed or	The completed Operations  Plugging Back Non Casing Repair Wate Altering Casing Con Completed Operations	Routine Fracturing Shut off version to Injecti	on
Final Abandonmer  Describe Proposed or  It is intended to repattached proc	The Casing Repair Water Altering Casing Contact Altering Casing Contact The tubing on the subject well reduce.  The Completed Operations  The table of the tubing on the subject well reduce.  The foregoing is true and correct (MEL5) Title Regulatory Administration of the subject was a subject well reduced to the foregoing is true and correct state (MEL5) Title Regulatory Administration of the subject was a subject well reduced to the foregoing is true and correct state (MEL5) Title Regulatory Administration of the subject well reduced to the foregoing is true and correct state (MEL5) Title Regulatory Administration of the subject well reduced to the foregoing is true and correct state (MEL5) Title Regulatory Administration of the subject well reduced to the subject well reduce	Routine Fracturing Shut off version to Injection to Injection to Injection to the state of the s	.on 

#### Woodriver #1R

## Mesaverde

### 1450'FSL. 1555' FWL

Unit K, Section 5, T-30-N, R-9-W Latitude / Longitude: 36° 50.2303' / 107° 48.4222'

DPNO: 4167A

Tubing Repair Procedure

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required 2 the job can be pumped. If verbal approval is obtained, document approval in DIV.3/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- Caution: This well currently operates with a piston. MOL and RU workover rig. Obtain and 2. record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3/8", 4.7# J-55 tubing is set at 5708'. Release donut, pick up additional joints of 3. tubing and tag bottom. (Record depth.) PBTD should be at +/- 5855'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below 4. perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from easing and perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3 8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally. making short trips for clean up when necessary.
- Land tubing at  $\pm 5708$ °. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: ME. Hatty

Approved:

Bruce N. Bon 10 34.98 Drilling Superintendent

Operations Engineer:

Mary Ellen Lutev

Office - (599-4052) Home - (325-9387)

Pager - (324-2671)