DISTRIBUTI SANTA FE FILE	ION					
	TON					Supersedes Old C-102 and C-103
FILE		NI NI	EW MEXICO OIL CONSE	RVATION COMMISSI	ON	Effective 1-1-65
FILL		-				
U.S.G.S.						5a. Indicate Type of Lease
LAND OFFICE						State Fee X
OPERATOR	2			_		5, State Oil & Gas Lease No.
		<del></del>		100	TIM	
(DO NOT US	SU SE THIS FORM FO	NDRY NOTICES OF PROPOSALS TO DRIL	AND REPORTS ON V	VELLS	TIAFD	
OIL WELL	GAS X			MAR	2 8 1974	7. Unit Agreement Name
d. Name of Operator	г	· · · · · · · · · · · · · · · · · · ·				Farm or Lease Name
Aztec Oi	1 & Gas C	ompany		/ OIL (	ON. COM.	Pandleman
3. Address of Oper						9. Well No.
P. O. Dr	awer 570.	Farmington	New Mexico 874	01		#1
Location of Well		- arming con,	NOW PICKIEG 074	.,1		10. Field and Pool, or Wildcat
-		1750	Couth	1.650		·
UNIT LITTER		FEE	T FROM THE South	LINE AND 1051	FEET FROM	Blanco Mesaverde
117 4		1.7	<b>7.1</b> 11		1	
THE West	LINE, S	SECTION13	township 31 Nor	th RANGE 11 We	St NMPM.	
,,,,,,,,,,,	,,,,,,,,,	mm				
		111111111111111111111111111111111111111	Elevation (Show whether D			12. County
			57	58 GR		San Juan
! f' .	Che	ck Appropriate	Box To Indicate Na	ture of Notice R	enort or Othe	er Data
		F INTENTION T			JBSEQUENT	
	1101102	THE CHILDRE	· · · · · · · · · · · · · · · · · · ·	31	JBSEQUENT	REFORT OF:
					<u></u>	
PERFORM REMEDIAL	=		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANI	<del></del> -			COMMENCE DRILLING OP	<del></del>	PLUG AND ABANDONMENT
PULL OR ALTER CAS	146		CHANGE PLANS	CASING TEST AND CEMEN	apt T	COURT 7FD FY
				OTHER		SQUEEZED
OTHER						
		1.0 (6)	1	<del>,</del>		
	) 0 1 1		riy state ali pentinent detat	is, and give pertinent d		
10. Vectribe Propo work) SEE RUL	sed or Complet LE 1103.	ed Operations (Crear	•		ates, including e	stimuted date of starting any proposed
17, Vectribe Propo work) SEE RUL	sed or Complet LE 1103.	ed Operations (Crear			ates, including e	stimuted date of starting any proposed
work) SEE RUL	L E' 1 103,					
work) SEE RUL	Moved In	& Rigged Up	. Set Choke @ 46	05'. Pulled Tu	hing. Set	Bridge Plug @ 4600'.
work) SEE RUL	Moved In Pressure	& Rigged Up Tested Casin	. Set Choke @ 46 ng To 2500# - He	05'. Pulled Tu ld Ok. Perfora	hing. Set ted Two Sq	Bridge Plug @ 4600'. ueeze Holes @ 4190'.
work) SEE RUL	Moved In Pressure Cemented	& Rigged Up Tested Casin With 200 Sad	. Set Choke @ 46 ng To 2500# - He cks Of Class "A"	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ	hing. Set ted Two Sq eezed Off	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement
work) SEE RUL	Moved In Pressure Cemented Did Not	& Rigged Up Tested Casin With 200 Sac Circulate Arc	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead.	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque	hing. Set ted Two Sq eezed Off eze Holes	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'.
work) SEE RUL	Moved In Pressure Cemented Did Not (	& Rigged Up Tested Casin With 200 Sac Circulate Arc ed Two Squee:	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500'	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#.
3-21-74	Moved In Pressure Cemented Did Not (	& Rigged Up Tested Casin With 200 Sac Circulate Arc ed Two Squee:	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500'	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#.
3-21-74	Moved In Pressure Cemented Did Not (Perforate Cemented Cemented Cemented Move (Cemented Move)	& Rigged Up Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C"	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5 With 3% Chlor	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement
3-21-74	Moved In Pressure Cemented Did Not Perforate Cemented With Add	& Rigged Up Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac itional With	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5 With 3% Chlor	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#.
3-21-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add; Water Flo	& Rigged Up Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac itional With ow Around Bra	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead.	05'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5 With 3% Chlor ss "A" With 3%	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride,	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off
3-21-74 3-22-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add; Water Flo	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From 1	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'.	O5'. Pulled Tu ld Ok. Perfora & 6% Gel. Squ Shot Two Sque . Pumped In 5 With 3% Chlor ss "A" With 3%	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unahl Chloride, d Casing.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off Pumped In @ 500#.
3-21-74 3-22-74 3-23-74	Moved In Pressure Cemented Did Not ( Perforate Cemented With Add: Water Flo Drilled ( Cemented	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Tement From Sac With 100 Sac Tested Took Cement From Sac Tested Test	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A"	O5'. Pulled Tu  Id Ok. Perfora  & 6% Gel. Squ  Shot Two Sque  Pumped In 5  With 3% Chlor  ss "A" With 3%  Pressure Teste  & 3% CaCl. Sq	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unahl Chloride, d Casing. ueezed Off	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off Pumped In @ 500#. With 1500#. WOC.
3-21-74 3-22-74	Moved In Pressure Cemented Did Not ( Perforate Cemented With Add: Water Flo Drilled ( Cemented Drilled (	& Rigged Up. Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac itional With ow Around Bra Cement From 1 With 100 Sac Cement From 1	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'.	O5'. Pulled Tu  Id Ok. Perfora  & 6% Gel. Squ  Shot Two Sque  Pumped In 5  With 3% Chlor  Ss "A" With 3%  Pressure Teste  & 3% CaCl. Sq  Pressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off Pumped In @ 500#. With 1500#. WOC.
3-21-74 3-22-74 3-23-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Floorilled (Cemented Drilled (Drilled (D	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squees With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'.	O5'. Pulled Tu Id Ok. Perfora & 6% Gel. Squ Shot Two Sque Pumped In 5 With 3% Chlor Ss "A" With 3% Pressure Teste & 3% CaCl. Squ Pressure Teste Pressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Ot. Pumped In @ 500#.
3-21-74 3-22-74 3-23-74 3-24-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Drilled (Cemented Drilled (Drilled (Cemented Cemented	Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squees With 125 Sac itional With ow Around Bracement From Edment From Cement From Cement From With 100 Sac	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A"	O5'. Pulled Tu Id Ok. Perfora & 6% Gel. Sque Shot Two Sque Pumped In 5 With 3% Chlor Ss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste Compare Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Ob. Pumped In @ 500#. With 1500#.
3-21-74 3-22-74 3-23-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented (Cem	& Rigged Up Tested Casin With 200 Sac Circulate Arc With 125 Sac itional With ow Around Bracement From Edment From Cement From With 100 Sac Cement From With 100 Sac Cement From Cement Fr	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'.	Pressure Teste  § 3% CaCl. Sque Cache Cach	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pinger)	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To	Pressure Teste & 3% CaCl. Squeressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Ob. Pumped In @ 500#. With 1500#.
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pierrorate) (Perforate) (P	§ Rigged Up. Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac itional With ow Around Bra Cement From With 100 Sac Cement From Substitute 4600'. Swabbed Well	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To	Pressure Teste & 3% CaCl. Squeressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pierrorate) (Perforate) (P	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To	Pressure Teste & 3% CaCl. Squeressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pierrorate) (Perforate) (P	§ Rigged Up. Tested Casin With 200 Sac Circulate Arc ed Two Squee: With 125 Sac itional With ow Around Bra Cement From With 100 Sac Cement From Substitute 4600'. Swabbed Well	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To	Pressure Teste & 3% CaCl. Squeressure Teste	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To	O5'. Pulled Tuld Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Sque Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Pressure Teste & 1900'. Tripped Clean. Rigged	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1 Down.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To ction.	O5'. Pulled Tuld Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Sque Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Pressure Teste & 1900'. Tripped Clean. Rigged	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing. In With 1 Down.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To ction.	O5'. Pulled Tulled Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 1000'. Tripped Clean. Rigged	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing - In With 1 Down.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Ob. Pumped In @ 500#. With 1500#. Held Ok. Drilled 'd' Tubing & Landed
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To ction.	O5'. Pulled Tuld Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Sque Teste & 3% CaCl. Sque Pressure Teste & 3% CaCl. Sque Pressure Teste & 1900'. Tripped Clean. Rigged	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing - In With 1 Down.	Bridge Plug @ 4600'. ueeze Holes @ 4190'. With 1500#. Cement @ 1500'. r Minute @ 1000#. e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#. With 1500#. WOC. to 1500# - Held Oh. Pumped In @ 500#. With 1500#. Held Ok. Drilled
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To ction.	O5'. Pulled Tulled Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 1000'. Tripped Clean. Rigged	hing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing - In With 1 Down.	Bridge Plug @ 4600'.  ueeze Holes @ 4190'.  With 1500#. Cement @ 1500'.  r Minute @ 1000#.  e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#.  With 1500#. WOC.  o 1500# - Held Ob.  Pumped In @ 500#.  With 1500#.  Held Ok. Drilled  '' Tubing & Landed
3-21-74 3-22-74 3-23-74 3-24-74 3-25-74	Moved In Pressure Cemented Did Not (Perforate Cemented With Add: Water Flo Cemented Drilled (Cemented Drilled (Cemented Drilled (Bridge Pilaced Bariage Pilace	& Rigged Up Tested Casin With 200 Sac Circulate Arced Two Squee: With 125 Sac itional With ow Around Bracement From Edment Fro	. Set Choke @ 46 ng To 2500# - He cks Of Class "A" ound Bradenhead. ze Holes @ 1500' cks Of Class "C" 50 Sacks Of Cla adenhead. 1455' To 1500'. cks Of Class "A" 1276' To 1500'. 4100' To 4190'. cks Of Class "A" 3925' To 4190'. Cleaned Out To 1 In. Blowing To ction.	O5'. Pulled Tulled Ok. Perfora & 6% Gel. Sque Shot Two Sque. Pumped In 5 With 3% Chlorss "A" With 3% Pressure Teste & 3% CaCl. Sque Pressure Teste & 1000'. Tripped Clean. Rigged	bing. Set ted Two Sq eezed Off eze Holes Barrels Pe ide. Unabl Chloride, d Casing. ueezed Off d Casing T d Casing. ueezed Off d Casing - In With 1 Down.	Bridge Plug @ 4600'.  ueeze Holes @ 4190'.  With 1500#. Cement @ 1500'.  r Minute @ 1000#.  e To Circulate. Cement 10% Calcium. Shut Off  Pumped In @ 500#.  With 1500#. WOC.  o 1500# - Held Ob.  Pumped In @ 500#.  With 1500#.  Held Ok. Drilled  '' Tubing & Landed