Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUKEAU OF LAND IMANAGE	ZIAI ZIA I	5. LEASE DESIGNATION AND SERIAL NO.
		SF 078146
SUNDRY NOTICES AND REI	PORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Do not use this form for proposals to drill or to dee	• • • • • • • • • • • • • • • • • • • •	
Use "APPLICATION FOR PERMI		
		7. IF UNIT OR CA. AGREEMENT DESIGNATION
SUBMIT IN TRIPLICATE		NEWBERRY LS
TYPE OF WELL		8. WELL NAME AND NO.
OIL WELL GAS WELL OTHER	□.	#5
NAME OF OPERATOR	<u>. </u>	9. API WELL NO.
CONOCO INC.		30-045-110710
ADDRESS AND TELEPHONE NO.		10. FIELD AND POOL, OR EXPLORATORY ARE
10 Desta Drive, Suite. 100W Midland, Texa	ıs 79705-4500 (915) 686-5424	BLANCO MESA VERDE
LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Des		11. COUNTY OR PARISH, STATE
1650' FNL & 1750' FEL, UNIT LETTE		SAN JUAN COUNTY, NM
	TO INDICATE NATURE OF NOTICE,	
		
TYPE OF SUBMISSION	TYPE	OF ACTION
Notice of Intent	Abandonment	Change of Plans
_	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
	, ,	Diamana Watan
	◯ Other: Pay Add	Dispose Water
Describe Proposed or Completed Operations (Clearly state all p directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including est	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is
	pertinent details, and give pertinent dates, including est	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including est	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including est	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
directionally drilled, give subsurface locations and measured an	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
SEE ATTACHED SUMMARY	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
SEE ATTACHED SUMMARY	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
SEE ATTACHED SUMMARY	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on West Comp Recompletion Report and Log Form.) imated date of starting any proposed work. If well is nt to this work.)
SEE ATTACHED SUMMARY Thereby certify that the foregoing is true and correct	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on West Comp. Recompletion Report and Log Form.) imated date of starting any proposed work. If well is not to this work.)
SEE ATTACHED SUMMARY I hereby certify that the foregoing is true and correct SIGNED Sylva Manager (This space for Federal or State office use)	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertined true vertical depths for	(Note: Report results of multiple completion on Well Comp. Recompletion Report and Log Form.) imated date of starting any proposed work. If well is not to this work.) Agent for Conoco Inc. DATE 05/21/98
SEE ATTACHED SUMMARY Thereby certify that the foregoing is true and correct SIGNED Sylva Marson	pertinent details, and give pertinent dates, including estind true vertical depths for all markers and zones pertine	(Note: Report results of multiple completion on Well Comp. Recompletion Report and Log Form.) imated date of starting any proposed work. If well is not to this work.) Agent for Conoco Inc. DATE 05/21/98

* See Instruction on Reverse Side

CONOCO, INC. NEWBERRY LS #5

SEC. 05, T31N, R12W, UNIT LETTER 'G' 1650' FNL & 1750' FEL

04/28/98

MIRU. SICP/TP: 100 psi, ND tree, NUBOP/Blewey tee, RU blewey line, Unseat tbg hanger, POOH & LD, PU 2 jts tbg, RIH & tag for fill, POOH & tally 163 jts 2-3/8", 4.7 ppf, J-55, 8RD EUE tbg, 2-3/8" SN c/w plunger bumper spring & 1 jt. Tbg. (fill tagged @ 4849"), PU & RIH bit, tag liner top @ 4510', POOH & LD XO, PU & RIH, XO, 1 stand 2-3/8" tbg & string float on tbg to 4400'.

04/29/98

RIH, XO on tbg, tag fill @ 4849', POOH & LD XO, RIH, RBP setting/releasing took, 5 jts 2/38" tbg & t-5/8" Retryble pkr. Pkr would not pass thru rector tbg. LD pkr & cont. RIH, set RBP @ 4650' KB. Close pipe rams & press test wellbore & RBP w/ 500 psi, Release test press & open pipe ram, POOH 5 stand, dump 15 gals of sand down tbg on top of RBP & pump 1 bbls 1% KCI H2p, POOH & LD RBP. RIH w/TDT logging tool. Log from RBP to 3800' & 2500' to 1800', POOH.

04/30/98

ND BT/BOP, ND. Take gas readings, 0 gas. Weld 7-5/8", 26.4 ppf, J-55 csg, NU, full-bore

ERC 11", 2M x 7-1/16", 2M tbg head spool. Press test flanges & ring gaskets/seal to 1500 psi, NU BOP, RIH w/ Retrvble pkr & unloader on tbg to 4097'. Set pkr & press test RBP to 2000 psi in 500 psi increments-OK. Release test press, close pipe rams & press test csg/tbg annulus & tbg spool to 500 psi-OK. Release test press, POOH, pkr hung up @ 567', Could not POOH, only RIH, circ., wellbore, Attempt to POOH, pkr still could not be POOH. Found 2-3/8" pin popped out of box. Left pkr & 2 stands 2-3/8" tbg in well, RIH w/ tbg 7 screw into fish, work pkr w/15k, could not POOH, only RIH w/ 10 stands to 1190', work pkr to 900' w/40 k pull on tbg.

05/01/98

Cont. working to free pkr @ 900', could not move POOH, work pkr down to 1200'.

05/02/98

RIH perf gun (2 JSPF 0.32' OD, DP), perf @ \$609-06-4566-63-56-44, total 12 perfs, POOH, RIH (1 JSPF, 0.38" OD,DP) perf @ 4504-4456-53-44-36-30-23-19-11-02-4366-55-36-30-18-13, total 16 perfs. POOH, RIH pkr & unloader to 4100' & set pkr. Test pkr, release test press. Press test lines to 5500 psi-OK. Breakdown perfs from 4313' -4609' as follows: Pump 5 bbls 1% KCI H20, release 18 frac balls, pump 5 bbls 15% HCl, release 18 frac balls, pump 5 bbls 15% HCl, release 16 frac balls, pump 7 bbls 15% HCI & displace w/35 bbls 1% KCI H20 avg.: 3.8 BPM/3000 psi ISIP: 1750 psi, good ball & breakdown action, did not ballout, surge balls off & bled off press. Release pkr @ 4100' & csg to TOL @ 4510', knocking off frac balls, POOH, RIH to 4660', work same to recover frac balls & POOH (recovered 52 frac balls w/19 hits) Changed rams to 3-1/2", RIH pkr & unloader, Tally, RU & RIH frac string, set pkr @ 4117'. Press up w/ rig pump to 500 psi, press test lines to 5500 psi, OK. Frac 4313'-4609' as follows: Pump 238 bbls 15# to low-gel 1% KCl J20 @ 31.3 BPM/3770 psi, 274 bbls 15# lowg4el 1% KCl water w/1.0 PPG 20/40 sand @ 34.3 BPM/3740 psi, 559 bbls 15# low-gel 1% KCI H20 w/2.0 PPG 20/.40 sand tagged w/Iridium 192 @ 33.9 BPM/3700 psi, 228 bbls 15# low-gel 1% KCl H20 w/2.5 PPG 20/40 sand tagged w/Iridium 192 @ 34.3 BPM/3640 psi, 170 bbls 15# low-gel 1% KCl H20 w/2.5 PPG 20/40 SDC sand tagged w/Iridium 192 @ 34.2 BPM/3750 psi, 45 bbls 15# low-gel 1% KCl H20 @ 33.8 - 0 BPM/3770 psi - 1550 psi ISIP: 1550 psi, 1390 psi, 1360 psi, 1350 psi, avg.: 33 BPM/3600 psi. Bled off press on csg/tbg annulus.

CONOCO, INC. NEWBERRY LS #5

SEC. 05, T31N, R12W, UNIT LETTER 'G' 1650' FNL & 1750' FEL

- O5/04/98 Count not blow down well to flare pit or take SITP, no XO from frac valve to 2" flow line. Well did not die. Release pkr, got XO, RU flow-tee, take SITP & flow well to flare pit, well unloading gelled H20 & no sand. Flow decreased & well started slugging H20. Attempt to kill well be reverse circ. 55 bbls, no go. TP built up to 65 psi, flow well to flare pit. Well started to make small amount of flareable gas.
- Cont. flow well to flare pit, well nearly dead, open pkr unloader, well died, release pkr & POOH, change out pipe rams to 2-3/8", RIH w/MS/SN on tbg to 1700'. Unload well w/drill gas. Kill well w/5bbls 1% H20 down tbg & RIH, tag fill @ 4422', POOH to 4299', RIH to 4422' & CO to 4453' w/drill gas. PU to 4422'.
- O5/06/98 Cont. drywatch, shut down compressor, RIH & tag fill @ 4430', CO from 4430' to 4662' w/ drill gas & pumping 3 bbls soapy 1% KCl H20 sweeps @ every connection, circ. well clean, POOH to 4420', RIH & tag fill @ 4650' (12' fill), POOH to 4365', place well on ½" choke.
- 05/07/98 RIH w/ EOT to 4545', csg press built up to 640 psi w/no returns to surface. RIH, hit gas cut fluid @ 2400' & kick well off w/ 2 swab runs. Flow well on ½" choke.
- Flow test: 220 MCFGPD, 0 BOPD & 2 BWPD @ 150 psi FTP & 420 psi SICP thru ¼" choke & 2" flowline to atmosphere. Witnessed by Tellesforo Varela/Mario Sanchez Flint Engineering. RIH & tag fill @ 4642', break circ. CO to RBP @ 4662'. POOH & LD SN/MS, RIH w/ GR-CCL logging tool, run RA tracer log from 4662' to 3800' twice, POOH, RIH w/ RBP on 2-3/8" tbg. Wash down to RBP @ 4662', open RBP equalizer & release RBP. POOH w/ tbg swivel, POOH & LD RBP, RIH w/ Mule shoe, SN & 154 jts 2-3/8", 4.7 ppf, J-55 8RD EUE tbg. (EOT @ 4549.19', SN @ 4547.69'). ND BT/BOP. RDMO.