State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

		Sundry Notices and	Reports on Wells	
1. Type of GAS	Well		API 5.	# (assigned by OCD) 30-045-11128 Lease Number State Oil&Gas Lease #
2. Name of	Operator		_ DECEIVE	E-3150-1-NM Displace Name/Unit Name
RESC	OURCES OIL &	GAS COMPANY	FEB 1 2 1999	San Juan 32-9 Unit Well No.
PO Box	& Phone No. of Operato 4289, Farmington, NM	87 4 99 (505) 326-970	ON. DI	61 Rool Name or Wildcat Blanco Mesaverde
	of Well, Footage, Sec 990'FWL, Sec.36, T-32		10.	Elevation:
Type of	Submission	Type of .	Action	
	Notice of Intent	Abandonment	Change of Pl	ans
		Recompletion	New Construc	
	Subsequent Report	Plugging Back	Non-Routine	
	<u>-</u>	Casing Repair	Water Shut o	-
:	Final Abandonment	Altering Casing X Other -		
	ibe Proposed or Completintended to repair the attached procedure.		ject well accordi	ng to the
SIGNATURE _	say Staine	(MEL5) Regulato	ry Administrator_	_February 10, 1999
(This space	for State Use)			
	OBKERS CONTRACT	50 h		
	ORIGINAL SIGNED BY CHARLIE	T PERRINA	DIL & GAS INSPECTOR, DI	ST #3 FEB 19 1000
Approved by		Title		Date 17 100c

San Juan 32-9 Unit #61

Mesaverde 990'FSL, 990' FWL

Unit M, Section 36, T-32-N, R-9-W

Latitude / Longitude: 36° 56.1923' / 107° 44.2062'

DPNO: 6937301

Tubing Repair Procedure

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Mesaverde, 2-3/8", 4.7# tubing is set at 5993'. Release donut and TOOH with tubing. (PBTD should be at +/-5993'.) Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4 If fill was encountered, TIH with 4-3/4" bit, bit sub and watermelon mill on 2-3/8" tubing and round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally. making short trips for clean up when necessary.
- Land tubing at ±5910°. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: M.E. Autry
Operations Engineer

Approved:

Bruce W. Bong 1.27.99
Drilling Superintendent

Operations Engineer:

Mary Ellen Lutev

Office - (599-4052) Home - (325-9387) Pager - (324-2671)

MEL/klg