

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator El Paso Exploration Company		8. Farm or Lease Name Barnes
3. Address of Operator PO Box 289, Farmington, NM 87401		9. Well No. 6
4. Location of Well UNIT LETTER _____, 990 FEET FROM THE North LINE AND 990 FEET FROM East LINE, SECTION 23 TOWNSHIP 32N RANGE 11W NMPM.		10. Field and Pool, or Wildcat Blanco Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 6262' GL		12. County San Juan

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair Well

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

In order to repair a casing failure and increase production, it is planned to workover and restimulate this well in the following manner:  
Recover parted tubing. If tubing is stuck, cut off approximately 100' below bottom of the 7" casing.  
Set drillable cement retainer near bottom of the 7" casing and squeeze the open hole with approximately 200 sks. of cement.  
Pressure test the 7" casing to 1000 psi. Isolate and squeeze any leaks. If leaks are squeeze near the base of the Ojo Alamo, no additional squeezing of the 7" annulus is planned. If there are no holes near the base of the Ojo Alamo perforate two squeeze holes at the base of the Ojo Alamo, and squeeze the 7" annulus with approximately 125 sks. cement. Clean out cement below 7" casing and gas drill a new sidetracked hole using a knuckle joint. Run a full string of 4 1/2" casing and cement with sufficient volume to fill to the bottom of the 7" casing. Selectively perforate and sandwater fracture the Mesa Verde. Clean out, run tubing and gauge well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frank I. Chavez TITLE Drilling Clerk

DATE March 24, 1980

APPROVED BY Original Signed by FRANK I. CHAVEZ

SUPERVISOR DISTRICT # 3

DATE MAR 24 1980

CONDITIONS OF APPROVAL, IF ANY:

