NO. OF COPIES PECEIVED				Form C-103
DISTRIBUTION				Supersedes Old
SANTAFE	7	NEW MEXICO OIL CONSER	VATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE	1			
U.S.G.S.				5a. Indicate Type of Lease
LAND OFFICE				State Fee X
OPERATOR	3			5, State Oll & Gas Lease No.
			and the second s	to the think the strate state of the state o
(NO NOT USE THIS FOR USE	SUNDRY NOTICE THE FOR PROPOSALS TO DR TAPPLICATION FOR PERM	S AND REPORTS ON WE	TO A DIFFEREN RESERVOIS	
	OTHER-			7. Unit Agreement Name
L. Name of Operator			7	8. Farm or Lease Name
Aztec Oil & Ga	s Company		MAY 3 0 1973	Page
a, alterns of Operator			1	o, Well No.
P. O. Drawer 5	70. Farmington	, New Mexico	OIL CON. COM.	# 2
4. Location of Well			DIST. 3	10. Field and Pool, or Wildcat
UNIT LETTER M	, <u>890</u> ғ	EET FROM THE South	LINE AND 890 FEET FRO	Blanco Mesaverde
Wast	7			Thillillillilli
THE MUSE L	INE, SECTION /	TOWNSHIP 32 Nort	n RANGE 10 West NMP	
		5. Elevation (Show whether DF	RT, GR, etc.)	12. County
		6824		San Juan
16.	Check Appropriate			
	CHECK Appropriation		ure of Notice, Report or C	
			308324051	NT REPORT OF:
PERFORM REMEDIAL WORK	7	PLUG AND ABANDON R	EMEDIAL WORK	ALTERING CASING
TEMPORTULY ABANDON	j .	<u> </u>	OMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OF ALTER CASING	1	[]!	ASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
<u></u>	•		OTHER	
OTHER	• • • • • • • • • • • • • • • • • • • •			
work) SEE RULE 1103.	mpleted Operations (Cla	early state all pertinent details	, and give pertinent dates, includi	ng estimated date of starting any proposed
,				
(i) Pulic	d 2" Tubing. S	et Cement Retainer	@ 5 600!	
		et Cement Retainer With 300 Sacks Cla		
(2) Squee	zed Open Hole	With 300 Sacks Cla	ss "A".	s WAW 121# Cii 4% Col
(2) Squee (3) Set C	zed Open Hole Gement Retainer	With 300 Sacks Cla @ 5338'. Cemented	ss "A". With 150 Sacks Clas	s "A", 12½# Gii, 4% Gel.
(2) Squee (3) Set C Press	zed Open Hole ement Retainer ure Tested Wit	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho	s "A", 12½# Gil, 4% Gel. le @ 1200'. Cemented With
(2) Squee (3) Set C Press 100 S	zed Open Hole ement Retainer ure Tested Wit acks Class "A"	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In	ss "A". With 150 Sacks Clas Ran Packer. Found Ho	s "A", 12½# Gil, 4% Gel. le @ 1200'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille	zed Open Hole ement Retainer ure Tested Wit acks Class "A" d Window From	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In	ss "A". With 150 Sacks Clas Ran Packer. Found Ho	s "A", 12½# Gil, 4% Gcl. le @ 1200'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill	zed Open Hole ement Retainer ure Tested Wit acks Class "A" d Window From ed To 5586'.	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#.	le @ 1200'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill	zed Open Hole ement Retainer ure Tested Wit acks Class "A" d Window From ed To 5586'. ed From 5586'-	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain	le @ 1200'. Cemented With er @ 5250'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S	zed Open Hole ement Retainer ure Tested Wit acks Class "A" d Window From ed To 5586'. ed From 5586'- acks Class "A'	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. '5630'. Hole Got We ', 12½# Gil Per Sac	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain	le @ 1200'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe	zed Open Hole ement Retainer ure Tested Wit lacks Class "A" d Window From ed To 5586'. ed From 5586'- lacks Class "A' ed Off @ 3736'.	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. '5630'. Hole Got We ', 12½# Gil Per Sac	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott	zed Open Hole ement Retainer ure Tested Wit acks Class "A" ed Window From ed To 5586'. ed From 5586'- acks Class "A' ed Off @ 3736'. ed First Plug	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug	le @ 1200'. Cemented With er @ 5250'. Cemented With
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott	zed Open Hole ement Retainer ure Tested Wit acks Class "A" ed Window From ed To 5586'. ed From 5586'- acks Class "A' ed Off @ 3736'. ed First Plug	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. '5630'. Hole Got We ', 12½# Gil Per Sac	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott	zed Open Hole ement Retainer ure Tested Wit acks Class "A" ed Window From ed To 5586'. ed From 5586'- acks Class "A' ed Off @ 3736'. ed First Plug	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole ement Retainer ure Tested Wit acks Class "A" ed Window From ed To 5586'. ed From 5586'- acks Class "A' ed Off @ 3736'. ed First Plug	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott	zed Open Hole ement Retainer ure Tested Wit acks Class "A" ed Window From ed To 5586'. ed From 5586'- acks Class "A' ed Off @ 3736'. ed First Plug	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. '5630'. Hole Got We', ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r.	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'.	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r.	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer.
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r.	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer. From 2017'-1970'. Spotted
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r.	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer. From 2017'-1970'. Spotted
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r. y knowledge and belief. rict Superintendent	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer. From 2017'-1970'. Spotted
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit acks Class "A" ad Window From ed To 5586'. ed From 5586'-backs Class "A' ad Off @ 3736'. ed First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Fressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r.	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer. From 2017'-1970'. Spotted
(2) Squee (3) Set C Press 100 S (4) Mille (5) Drill (6) Drill 150 S (7) Backe (8) Spott Plug	zed Open Hole dement Retainer ure Tested Wit lacks Class "A" d Window From ed To 5586'. dd From 5586'. dd Off @ 3736'. led First Plug On Top. Instal	With 300 Sacks Cla @ 5338'. Cemented h 2000#. Held Ok. ', 3% CaCl. Shut In 5573'-5578'. 5630'. Hole Got We ', 12½# Gil Per Sac From 3560'-3460'. led Dry Hole Marke e and complete to the best of m	ss "A". With 150 Sacks Clas Ran Packer. Found Ho Pressure 1000#. t. Set Cement Retain k, 4% Gel. Unable To Spotted Second Plug r. y knowledge and belief. rict Superintendent	le @ 1200'. Cemented With er @ 5250'. Cemented With Pull Out Of Retainer. From 2017'-1970'. Spotted

NEW MEXICO OIL CONSERVATION COMMISSION 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO June 25, 1973

Aztec Oil & Gas Company Drawer 570 Farmington, New Mexico 87401

Re: Plugging Reports Gentlemen: Form C-103, Notice of Intention to Plug, your_ M-7-32N-11N was approved June 15, 1973
S-T-R Your subsequent notice of plugging cannot be approved until a commission representative has made an inspection of the location to see: (1) all pits have been filled and leveled; (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker; (3) the location shall be cleared and cleaned of all junk; (4) the dead man wires must be cut. The above are the minimum requirements. Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location. OIL CONSERVATION COMMISSION K Kentriele Fill in below and return: is ready for your inspection and Lease Well No. Unit approval. susperted 10.36-73 Operator

Name and title