
.rm 3160-5 Gvember 1983) ormerly 9-331)	UNITED ST. DEPARTMENT OF THE BUREAU OF LAND ME	HE INTERIO	SUBMIT IN TRIP (Other (astruction rerse side)	LICATE S LEAS	orm approved.  deget Bureau No  xpires August  20-604-19  NOIAN, ALLOTTEE C	1985 D BREAL NO.	
SUND	A NID	DEDODTS OF	N WELLS k to a different reserve		<del>ajo</del> um	<u> </u>	
SUNDRY NOTICES AND REPORTS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  (Do not use this form for proposals.)  OIL					Horseshoe Gallup Unit 3. FARM OR LEVER NAME Horseshoe Gallup Unit 2. WELL NO.		
At surface Unit	" C ",			Hors	eshoe Gal	Lup E. AND	
	FNL & 3245' FEL,		тан Викани фетанция	Sec	.28-31N-1	6W	
NO API NO. AS	IS. BURVATIONS	(Show whether of,	NT. CR. PLA	Ψ	OURTY OR PARISE	N.M.	
		5750 <b>'</b>			an Juan	N . M .	
3. No	Check Appropriate Box	t To Indicate No	ature of Notice, Re	port, or Other E	POST OF:		
TEST WATER SEUT-OFF FRACTURE TREAT SHOUT OR ACIDIZE REPAIR WELL	PULL OR ALTER C MULTIPLE COMPL ABANDON® CHANGE PLANS	: 1 1	WATER SECT-OFF PRACTURE TREAT SECOTING OR AC (Other)	MENT	ESPAIRING TO ALTERING CA ABANDONMEN ABANDONMEN	aind	
nems to this work.	completed operations (Clearly well is directionally drilled, so						
HSGU We Natural from th operate was pro on this	ll #147 was original for the second control of the well well well with the site. We do not ble again in the	ginally control as an Update to the power of	mpleted 3-23 pper Gallup oint where i n 1-31-77. There is pr	producer. t became At that t cesently n	e El Paso Product: uneconomic ime, this o pumping well bec	ion cal to well unit oming	
pluggin	g and abandonme	nt.	lua thic we	11			
Attache	ed is a P&A Proc	edure to p	SEP 141		SEP 1 (		
			OIL CON	. DIV.	Durange,	Color <b>ado</b>	
13. I hereby certify that	t the foregoing is true and con	TITLE D:	\ DIST.		· DATE Augu	ıst 20, .19	
APPROVED B		int mare	day due	7.1	DATE	l 2 1984	

## Horseshoe Gallup Unit Producing Wells Plugging and Abandonment Procedure

- 1) Move pumping unit off location.
- 2) MIRU. Pull rods and downhole pumping equipment.
- 3) RIH below the bottom perforation w/tbg. open ended. Pump sufficient cement inside casing to cover top perforation by 50'.
- 4) POH w/tbg. GIH w/wireline and perforate casing 150' above top of cement. Number of shots should be sufficient to allow cement squeeze. POH w/wireline. GIH w/tbg. open ended. Squeeze cement to provide 100' plug outside casing. Leave 100' plug inside casing as well. If squeeze is unsuccessful leave a 100' plug inside casing.
- 5) POH w/tbg. GIH w/wireline and perforate casing 50' below surface casing shoe. Number of shots should be sufficient to allow cement squeeze. POH w/wireline.
- 6) RIH w/tbg. open ended and perform bradenhead squeeze through the perforations. Amount of cement should be sufficient for a 100' cement column behind the casing, and for a 100' cement plug inside the casing.
- 7) POH w/tbg. Cut casing foot below ground level, place a 30' cement plug inside casing. Weld a blind flange to casing, and weld a dry hole marker on blind flange. Fill hole and move off.
- 8) Rehabilitate location and access road using stipulations supplied by the Bureau of Land Management.

NOTE: BOP's will not be needed in most cases due to the very low pressure expected in the Gallup in the abandonment area. (Estimated at less than 250 - 300 psi bottom-hole) If pressure does register in any of these wells, bleed it off, install BOP's if needed, and commence with above procedure.



A PROPOSED CONVERSION

BRAFTED BY E.L.

0475 \_8/30/8