

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Federal  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator <b>El Paso Natural Gas Company</b> 3. Address of Operator <b>Box 990, Farmington, New Mexico</b> 4. Location of Well UNIT LETTER <b>H</b> <b>1800</b> FEET FROM THE <b>North</b> LINE AND <b>800</b> FEET FROM THE <b>East</b> LINE, SECTION <b>1</b> TOWNSHIP <b>31N</b> RANGE <b>11W</b> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name <b>Mudge</b> 9. Well No. <b>4</b> 10. Field and Pool, or Wildcat <b>Blanco Mesa Verde</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>5991' GL</b>	12. County <b>San Juan</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER _____ <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER _____ <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> _____ <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> _____ <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Because of a casing failure which makes a successful workover doubtful, it is intended to Plug and Abandon this well in the following manner:

Move in workover rig and pump water down the tubing to assure that it is open. Spot 50 sack cement plug on bottom and displace with water and rubber plug.

Pull tubing so that bottom is approximately 100' below casing shoe (about 4450'). If tubing is stuck, cut off at 4450' w/jet cutter. Spot 100 sack plug through tubing.

Pull tubing. Perforate 4 squeeze holes at base of Ojo Alamo (2120'). Run a cast iron retainer on tubing, set about 2050' and circulate or squeeze behind 7" casing w/150 sacks.

If bradenhead is not dead after squeezing, pump 50 sacks cement down bradenhead.

Recover wellhead and place 25 sack cement plug and dry hole marker at surface.

Clean and level location.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **Petroleum Engineer** DATE **11-17-66**

APPROVED BY *Cecilia E. ...* TITLE *Sup Dist III* DATE *11-18-66*

CONDITIONS OF APPROVAL, IF ANY: