TEST WATER SHUT-O	NOTICE OF INTENTION TO: OFF PULL OR ALTER CASI	NG NG	WATER SHUT-OFF	SUBŞEQUEN	T REPORT OF: REPAIRING V	VELL
16.	Check Appropriate Box T	o Indicate Natu	•	-		
	6356 GL	., 6369 KB	-		San Juan	New Mexico
14. PERMIT NO.	15. ELEVATIONS (S	Show whether DF, RT,	GR, etc.)		12. COUNTY OR PARISH	
NW SE Section 33-T31N-R9W (1710' FSL, 1580' FEL)					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 33-T31N-R9W	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface					Blanco Mesaverde Field	
Suite 1122, 1860 Lincoln Street, Denver, Colorado 80203					4 A	
Union Texas Petroleum, A Division of Allied Chemical Corporation 3. ADDRESS OF OPERATOR					9. WELL NO.	
2. NAME OF OPERATOR					8. FARM OR LEASE NAME Johnston-Federal	
OIL GAS WELL WELL	OTHER				. UNIT AGREEMENT NA	SI
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)					6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(.ay 1963)	DEPARTMENT OF TH	IE INTERIOF	SUBMIT IN TRIPLICATE* OR (Other instructions on re- verse side)			u No. 42-R1424.
F´ n 9-331	UNITED STA	TEC	aupum IN mama		Form approve	ъđ.

(Other)

(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.)

17. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Completion

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Rig up Dwinell Bros. rig 3-7-75. Cut off 4-1/2" liner at 3982'. Recovered liner hanger and 792' of 4-1/2" casing. Ran packer and set at 3243' in 7" casing.

Squeezed open hole interval w/150 sx cement plus 6-1/4# Gilsonite and 100 sx cement w/ 10# sand/sack. Squeezed to 2000 psi. Dressed off cement plug to 3433'. Randomly deviated hole w/knuckle joint and drilled to total depth of 5610'. Ran 4-1/2'' OD 10.5# K-55 ST&C new casing, and set liner from 3208 to 5608'. Cemented w/265 sx cement. Shut down for bad weather 3-13 to 3-18-75.

Tested casing and BOP to 3000 psi 3-18-75. Perforated Point Lookout 5468-5437, 5412-5402. Frac w/50,000 gal. treated fresh water, 2% sand, 40,000# 20-40 sand, 10,000# 10-20 sand. Set CIBP at 5060'. Tested to 3000 psi, held 0.K. Perforated Cliffhouse 5022-5013, 5008-4974, 4965, 4956-4952, 4933-4914. Frac w/50,000 gal. treated fresh water, 2% sand, 40,000# 20-40 sand, 10,000# 10-20 sand. Drill out BP and clean out to 5547'. Ran 2-1/16'' tubing and set at 5468'. Shut in waiting on pipeline 3-21-75.

		RICE 8 1975
18. I hereby certify that the foregoing is true and confect SIGNED	TITLE Assistant Dist. Prod.	Manager APR 4-3075 3
(This space for Federal or State office use)		OIL DIST
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE TO I
**		APR 7 1975

*See Instructions on Reverse Side

MPR 1 1973

ALTERING CASING

ABANDONMENT

J. S. CEGIACACT CHIVEY