## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on	Wells
1. Type of Well GAS	<ul><li>5. Lease Number SF-078604</li><li>6. If Indian, All.or Tribe Name</li></ul>
2. Name of Operator Meridian Oil Inc.	7. Unit Agreement Name
3. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505)326-9700	<ul><li>8. Well Name &amp; Number</li><li>Scott #7A</li><li>9. API Well No.</li></ul>
4. Location of Well, Footage, Sec, T, R, M. 2210'N, 1085'W Sec.3, T-31-N, R-10W, NMPM	10.Field and Pool Blanco Mesa Verde 11.County and State San Juan County, NM
X Notice of Intent Abandonment Recompletion	Action Change of Plans New Construction Non-Routine Fracturing
	Conversion to Injection
A casing repair is proposed per the attached prodiagram.  MAY 0 4 1990  OIL CON. DIV.)  DIST. 3	
14. I hereby certify that the foregoing is true Signed Man Manh (JS) Title Regulatory	
(This space for Federal or State office use)  APPROVED BY TITLE  CONDITION OF APPROVAL, IF ANY:	DATE

Commence of the second , \*s. the service week

I

## Scott #7A Recommended Workover Procedure

- 1. Move in blow tank for wellbore fluids. Install and test anchors as necessary.
- 2. MOL and RU workover rig equipped with power swivel, pump and steel pit. Hold safety meeting and comply with all BLM, NMOCD and MOI regulations.
- 3. RU return line to blow tank, record casing, tubing and bradenhead pressures. Blow well down and kill as required with 1% KCL water. NU BOP.
- 4. TOOH with 178 joints of 2 3/8" tubing. Visually inspect and replace bad joints.
- 5. TIH with bit and 7" casing scrapper on 2 3/8" tubing, clean out to 2850' (liner hanger @ 2886').
- 6. TIH with 7" Retrievable Bridge Plug on 2 3/8" tubing. Set RBP at 2800'. Spot sand on top of RBP. TOOH.
- 7. Load hole with water. Pressure test casing and RBP to 1,000 PSI for 15 minutes.
- 8. RU wireline and run GR-CBL-CCL from 1,000' to surface. If top of cement is not found, locate cement top and log to surface.
- 9. Perforate squeeze holes at TOC. Insure that hole is full prior to firing.
- 10. Pump sufficient amount of cement to circulate to surface.
- 12. TIH with bit and drill out cement below squeeze. Pressure test casing to 700 PSI. Re-Squeeze if necessary.
- 13. TIH and clean out with nitrogen to RBP. Latch RBP and TOOH.
- 14. TIH and clean out to total depth.
- 15. TIH, land tubing. Return well to production.

