

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

799'FSL, 1780'FEL, Sec.16, T-31-N, R-11-W, NMPM, San Juan County, NM

API # (assigned by OCD)

30-045-23575

5. Lease Number

6. State Oil&Gas Lease #

E-11017-31

7. Lease Name/Unit Name

Brookhaven Com B

8. Well No.

#3A

9. Pool Name or Wildcat

Blanco Mesaverde

10. Elevation:

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other - Plugging Procedure

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to plug the Cliffhouse Interval of the subject well according to the Attached procedure.

**RECEIVED**  
JUN 15 1999  
**OIL CON. DIV.**  
DIST. 3

SIGNATURE *Reggie Shadwick* Regulatory Administrator June 14, 1999

trc

(This space for State Use)

ORIGINAL SIGNED BY CHARLIE T. PERRIN

DEPUTY OIL & GAS INSPECTOR, DIST. #8

JUN 15 1999

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

**Brookhaven Com B #3A**  
**Mesaverde**  
**790' FSL, 1780' FEL**  
**Unit O, Section 16, T-31-N, R-11-W**  
**Latitude / Longitude: 36° 53.6014' / 107° 59.5724'**  
**DPNO: 4893101**  
**Plug Cliffhouse Interval Procedure**

**CAUTION: This well produces H2S.**

1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
3. Mesaverde, 2-3/8", 4.7# tubing is set at 4575'. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) COTD should be at + 4615'. (A CIBP is set at 4615'.) TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
4. TIH with 4-1/2" cement retainer on 2-3/8" tubing and set at + 4160'.
5. RU cement company. PU tubing to test position on the retainer. Pressure test tubing to 2500 psi. Set down on tubing to open check and establish an injection rate with water.
6. Squeeze below retainer into Cliffhouse/Menefee perforations to 1000 psi with 90 sx of Class B cement (with .3% fluid loss). Displace cement with 15 Bbls of water (under displace by 1 Bbl.). Sting out of retainer and TOOH with 2-3/8" tubing. WOC for a minimum of 18 hours.
7. TIH with 3-7/8" bit, 3-1/8" drill collars (if necessary) and 2-3/8" tubing. Drill out retainer and cement. Pressure test squeeze to 500 psi for 15 minutes. If test is not successful, note leak off rate and contact Operations Engineer.
8. CO to CIBP set at 4615'. Drill CIBP and push to bottom, cleaning out with air/mist. **NOTE: When using air/mist, minimum mist rate is 12 bph.** If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
9. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then 1/2 of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBDT with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
10. Land tubing at ±5150'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended:

M.E. Lutey  
Operations Engineer

Approved:

Bruce W. Boyer 6-4-99  
Drilling Superintendent

Operations Engineer:

Mary Ellen Lutey  
Office - (599-4052)  
Home - (325-9387)  
Pager - (324-2671)