State of New Mexico Form C-103 Submit 3 Copies **Revised 1-1-89** Energy, Minerals and Natural Resources Department to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO P.O.Box 2088 3004524825 Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Vil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Keys Gas Com "A" 1. Type of Well: OIL WELL OTHER 8. Well No. Attention: 2. Name of Operator Amoco Production Company Patty Haefele 3. Address of Operator 9. Pool name or Wildcat (303) 830-4988 80201 Basin Dakota Colorado P.O. Box 800 Denver 4. Well Location 1770 1660 North Feet From The Line Feet From The Unit Letter San Juan 32N 10W **NMPM** County 27 Range Township Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5947' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. TEMPORARILY ABANDON **CHANGE PLANS** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company intends to plug and abandon the subject well per the attached procedure. If you have any questions, please contact Patty Haefele at (303) 830-4988.

OIL CON. DIV.

I hereby certify that the information	above is true and complete to the bes	t of my knowledge	and belief.	- x		•
SIGNATURE Patty	Staefele	тпle	Business Ass	sociate —	DATE	1-05-1995
TYPE OR PRINT NAME	V Patty Haefele				TELEPHONE NO.	(303) 830-4988

(This space for State Use)

APPROVED BY Johnny Robusson

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JAN 1 0 1995

CONDITIONS OF APPROVAL, IF ANY:

* Notify in time to withous

PXA Procedures Keys Com A #2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. Run CBL to determine TOC. RIH with tbg and cement retainer. Set retainer 7250'. Test casing integrity to 500#. Squeeze perfs at 7294' to 7409' with 45.193 cuft cement. Pull out of retainer and spot cement plug to 6395' with 78.916 cuft cement.
- 4. Depending where TOC is be sure the following formations are covered inside and outside with 100' of cement:

Mesa Verde at 4313'
Pictured Cliffs at 2773'
Fruitland Coal at 2312'
Ojo Alamo at 872'
and 350' to surface

Estimated 69.76 cuft cement inside casing and 153.9 outside casing.

- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

