

LEASE Mudge Com B

WELL NO. 1E

9-5/8 "OD, 36 LB, K-55 CSG.W/ 285 SX

TOC @ surface

7 "OD, 23 LB, K-55 CSG.W/ 243/490SX

TOC @ Surface. Bradenhead w/208 sx. DB @2922'

4-1/2 "OD. 10.5/11.6 LB, K-55 CSG.W/ SX

TOC @

294'

DETAILED PROCEDURE:

1. MIRUSU. Blow well dn. Kill tbg. NUBOPE.
2. Tag bottom & tally out of hole w/tbg. Set RBP on WL @2000'. Dump 2 sx sd on top. Load hole w/2% KCL water. PT RBP to 2500 psi.
3. Perf 4 holes from 1000-1004'. RIH w/tbg & Model C fullbore retrievable cementer packer. Set pkr @800'. PT BS to 1000 psi.
4. Establish rate in perfs w/2% KCl.
5. Cement w/250 sx Class "B" w/2% CaCl₂ & 6-1/4#/sx gilsonite. If unable to get squeeze, overdisplace by 5 bbls & resqueeze in 4 hrs.
6. Release pkr, reverse out excess cement, POOH 2 stands & reset packer. WOC overnight.
7. POOH w/pkr. RIH w/6-1/4" bit & scraper. DO cmt. PT csg to 2000 psi. POOH.
8. RIH w/retrieving head. Circ sd off RBP. Roll hole w/2% KCl. Release RBP & POOH.
9. RIH w/tbg, SN & pump out plug. CO if necessary. Land @Dakota B. NUWH.
10. Kick well around w/N₂. FTCU.

DV @2922'

TOC @4562'

4802'

7151'