STATE OF NEW MEXICO ENERGY AND MINIERALS DEPARTMENT

	↓	,		
DISTRIBUTION	-			
SANTA FE	Ĭ			
FILE	Ì.			
U.S.G.S.		ĺ		
LAND OFFICE	Ī			
CREBATOR	ī	i		

CONSERVATION DIVISION

DISTRI	8UT10M _	P. O. BOX 2088		Farm C-193 Revised 19-1-7		
SANTA PE		SANTA FE, N	EW MEXICO 87501	nevises is i		
U.S.G.S.				Sa. Indicate Type of Lease		
LAND OFF	ICE			State Fee X		
OPERATOR				5. State Oil & Gas Lease No.		
				- Amminimi		
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROBALS TO SAILL ON TO SELECTED OF SLUG BACK TO A DIFFERENT RESERVOIR. 1155 "PAPPLICATION FOR PERMIT TO FORM SUICE PROPOSALS."						
**************************************	GAS WELL X OTH	CA-		7. Unit Agreement Name		
2. Name of Operator			8. Form or Lease Hame			
Southland Royalty Company 3. Address of Operator				Moore		
P. O. Drawer 570, Farmington, New Mexico 87499				1E		
Location of #e		on, non nextor o	. 133	10. Fleid and Pool, or Wildcar		
.1 1620 South				Basin Dakota		
THE East	,	35 TOWNSHIP		— HMPM.		
		IS. Elevation (Show when	her DF, RT, GR, etc.)	12. County San Juan		
6.	Check Approx		e Nature of Notice, Repo			
	NOTICE OF INTENT		•	EQUENT REPORT OF:		
PERFORM REMEDIA		PLUE AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABA	=	, and the second	COMMENCE DRILLING DANS.	PLUG AND ABANDONMENT		
PULL OR ALTER CA	~	CHANGE PLANS	CASING TEST AND CEMENT JOS			
		_	Sidetrack Sidetrack	& 4-1/2" casing Report X		
OTHER			_			
		(Clearly state all pertinent	details, and give pertinent dates.	including estimated date of starting any proposes		
work) SEE RU			4 - (0)			
1-10-84	miru Dwinnell Bro casing at 5510'.	MIRU Dwinnell Brothers. Ran free point on $4-1/2$ " casing, free at 5525'. Cut off casing at 5510'.				
1-11-84	Set 7" retainer at 4998'. Tested annulus to 2000 psi, OK.					
1-12-84	Establish rate down tubing 5 BPM at 1100 psi. Squeezed with 130 sacks of Class "B" with 4% gel and $12-1/2\#$ gilsonite per sack, followed with 70 sacks of Class "B" with 10% sand and 2% CaCl $_2$. Good walking squeeze to 3000 psi with 12 barrels displacement. WOC 12 hours.					
1-13-84	bit inside, 4" kr (5128'). Survey	nuckle joint on 2 @ 5126' - 6 deg,	o 5108'. Picked up 4 -7/8" drill pipe. Tr @ 5090' - 1 deg. Tr rat hole. Survey @	-3/4" core head with 3-1/8" ripped in hole, made 20' ripped out of hole. Ran 5126' - 4 deg. Tripped		
	CONTINUED OTH	ER SIDE	i gang Bu ta			
				WAY 62 1904		
				HI CON. DIV.		
			est of my unowiedge and belief.	eac + 2% − 7° − 2° j		
.B. I hereby certif	y that the information above i	s true and complete to the bo $rac{r}{r}$		DIST. 3		
8. I hereby certif	y that the information above i	s true and complete to the ba	District Engineer	Dibl. 3 		

- 1-14-84 Drilled 10' with 4-3/4" bit, survey at 5138' 8 deg. Tripped out of hole. Run 6-1/4" hole opener full length of rat hole. Survey @ 5136' 8 deg. Tripped out of hole. Picked up 10 4-3/4" drill collars, 6-1/4" bottom reamer.and 6-1/4" bit. Worked reamer and bit through rat hole. Drilled 20', survey @ 5156' 2 -1/2 deg. Drilled 40', survey @ 5197' 3 deg. Drilled 62', survey @ 5259' 4 deg.
- 1-15-84 Drilled to 5348', survey @ 5348 2 deg. Blow well to dry up.
- 1-16-84 Dried up hole. Drilled to 5524'.
- 1-17-84 Drying up hole.
- 1-18-84 Drilling at 6415'. Deviations: 2 deg @ 5535', 1-1/2 deg @ 5711', 4-1/4 deg @ 6203' and 5-3/4 deg @ 6358'.
- 1-19-84 Drilling at 7140'. Deviations: 5-3/4 deg @ 6491', 7 deg @ 6669', 6 deg at 6800' and 6 deg @ 7070'.
- 1-20-84 Drilling at 7460'. Deviation: 5-1/4 deg @ 7390'.
- 1-21-84 Deviation: 6-1/2 deg @ 7620'. TD hole 7620' at 9:00 AM 1-21-84. Ran IEL and CDL logs from 7626'-5106'. Ran 18 joints of 4-1/2'', 11.6# (840.02')and 41 joints of 4-1/2'', 10.5# (1808.56') K-55 casing.
- 1-22-84 Set 4-1/2" casing from 4963.17' to 7620.25'. Float collar at 7571.41'. Cemented as follows: 28 bbls chemical wash ahead, followed with 300 sacks (387 cu.ft.) of Class "B" 50/50 Poz with 10% salt, .6% Halad 9 and 1/4# flocele per sack, tailed in with 70 sacks (83 cu.ft.) of Class "B" with .6% Halad 9. Dropped plug, pumped 65 bbls displacement did not bump plug. Shut down float held. Started to circulate cement off liner, liner failed. Layed down drill pipe.