

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By OCD District 1 at 7:55 am, Aug 18, 2015

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA Inc.	Contact: Nick Hampton	
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No.: wk: 575-704-3143 cell: 985-502-2342	
Facility Name: West Dollarhide Drinkard Unit Battery	Facility Type: Battery	
Surface Owner: State surface	Mineral Owner (QLS-091040 – State of New Mexico B-9613 LSE)	API No.: N/A

LOCATION OF RELEASE

Unit Letter D	Section 32	Township 24-S	Range 38E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	-------------------------	---------------------	----------------------	-------------------------	----------------------	-----------------------	----------------------

Latitude: 32 deg 9.788 minutes north / Longitude: -103 deg 5.218 minutes west

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 64.71 bbls total fluid	Volume Recovered: 30 bbls total fluid
Source of Release: Fiberglass trunk line	Date and Hour of Occurrence 08/10/15 1:00PM	Date and Hour of Discovery 08/10/15 1:00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones	
By Whom? Nick Hampton	Date and Hour: 08/10/15 3:04PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

APPROVED

By OCD District 1 at 7:55 am, Aug 18, 2015


Describe Cause of Problem and Remedial Action Taken.*

Dresser sleeve failure due to end flange corrosion caused 60.25 bbls of produced water and 4.46 bbls of oil to leak to ground.

Describe Area Affected and Cleanup Action Taken.*

Caliche pad and field outside of battery affected. After all contaminated soil is hauled to Sundance, area will be sampled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Nick Hampton		OIL CONSERVATION DIVISION	
Printed Name: Nick Hampton		Approved by Environmental Specialist: 	
Title: HE Specialist		Approval Date: 08/18/2015	Expiration Date: 10/18/2015
E-mail Address: cikb@chevron.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 08/17/2015 Phone: 985-502-2342		Attached <input type="checkbox"/> 1RP 3805	

* Attach Additional Sheets If Necessary

Geotagged photos of remediation required.

nJXK1523028211

pJXK1523028406