<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Final Report

Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Address PO Box 3418, Midland, TX 79702 Telephone No. (432) 686-0847					
Surface Owner Merchant Livestock Co. Mineral Owner State of New Mexico API No. 30-025-33069 LOCATION OF RELEASE Unit Letter Section 170 myship L 2011 South South Line Feet from the South South Feet from the Political Politic					
County C					
Unit Letter L Section 31 Township 721S R33E Feet from the 2011 South South Line South South Line 660 West County Lea Latitude 32.4336791944° Longitude -103.6179688099° NAD83					
Unit Letter L Section 31 Township 721S R33E Feet from the 2011 South South Line South South Line 660 West County Lea Latitude 32.4336791944° Longitude -103.6179688099° NAD83					
Latitude 32.4336791944° Longitude -103.6179688099° NAD83 NATURE OF RELEASE Type of Release Brine Volume of Release Unknown Volume Recovered 0 bbls Source of Release Valve tree gauge on wellhead Date and Hour of Occurrence Less than 14 hours of discovery July 17, 2017 at 6:30 am Was Immediate Notice Given? If YES, To Whom? Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
Type of Release Brine Volume of Release Unknown Volume Recovered 0 bbls Source of Release Valve tree gauge on wellhead Date and Hour of Occurrence Less than 14 hours of discovery July 17, 2017 at 6:30 am Was Immediate Notice Given? If YES, To Whom? Was a Watercourse Reached? Tyes No Not Required If YES, Volume Impacting the Watercourse. RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
Type of Release Brine Volume of Release Unknown Volume Recovered 0 bbls Source of Release Valve tree gauge on wellhead Date and Hour of Occurrence Less than 14 hours of discovery July 17, 2017 at 6:30 am If YES, To Whom? By Whom? Date and Hour If YES, To Whom? Date and Hour If YES, Volume Impacting the Watercourse. RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
Source of Release Valve tree gauge on wellhead Date and Hour of Occurrence Less than 14 hours of discovery July 17, 2017 at 6:30 am Was Immediate Notice Given? If YES, To Whom? By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
Was Immediate Notice Given? Yes No Not Required By Whom? Date and Hour If YES, Volume Impacting the Watercourse. RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Less than 14 hours of discovery If YES, To Whom? Page 18 No RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.*					
Was Immediate Notice Given? Yes No Not Required If YES, To Whom? Date and Hour					
By Whom? Was a Watercourse Reached? The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Date and Hour If YES, Volume Impacting the Watercourse. RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
Was a Watercourse Reached? If a Watercourse was Impacted, Describe Fully.* RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
If a Watercourse was Impacted, Describe Fully.* RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
If a Watercourse was Impacted, Describe Fully.* RECEIVED By Olivia Yu at 4:16 pm, Aug 07, 2017 Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
Describe Cause of Problem and Remedial Action Taken.* The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced. Describe Area Affected and Cleanup Action Taken.*					
The injection pump partially failed, causing a vibration at the wellhead, which resulted in a pressure gauge on the valve tree to be broken off. The release was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
was from the gauge needle valve. The pump was repaired and the gauge replaced Describe Area Affected and Cleanup Action Taken.*					
Because the ground was rain-saturated, brine from the release covered the west side of the well pad and flowed into the adjacent areas to the west and					
south, then along the edge of two lease roads. The brine killed some of the vegetation located in the deep soil on the west side of the well pad. Once the flow entered the roadway no additional vegetation was affected.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.					
OIL CONSERVATION DIVISION					
Signature: Wilkiam Q. Inings					
Printed Name: William Savage Approved by Environmental Specialist:					
8/7/2017					
Title: President, AMTEX Energy, Inc. Approval Date: Expiration Date:					
E-mail Address: bsavage@amtexenergy.com Conditions of Approval:					

1RP-4778

nOY1721958769

pOY1721959089

Operator/Responsible Party,

The OCD has received the form C-141 you provided on _8/3/2017_ regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number _1RP-4778__ has been assigned. Please refer to this case number in all future correspondence.

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete <u>division-approved corrective action</u> for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District _1_ office in __Hobbs____ on or before _9/7/2017_. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- •Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.
- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.
- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief 1220 South St. Francis Drive Santa Fe, New Mexico 87505 505-476-3465 jim.griswold@state.nm.us
 From:
 Pair, Randal

 To:
 Yu, Olivia, EMNRD

 Cc:
 Yolanda Jordan

 Subject
 Pair, Randal

Subject: Re: FW: Tomahawk SWD

Date: Friday, August 25, 2017 1:03:53 PM

Ms Yu - BLM records also show Lot 3 of Sec 31, T21S R33E, to be fee land (privately owned). The whole section has been either private or state for a long time. None of the minerals in that section are federally owned.

Might you perhaps have been looking at Sec 31 of T21S R32E?? It is easy when working on maps, and you are near the dividing line between townships, to look-up stuff in the wrong township. Sec 31 in R32E is federal surface and all minerals are federal.

Randal "Randy" Pair

Envir. Protection Specialist - Realty Compliance

office: 575.234.6240 cell: 575.361.0062 email: rpair@blm.gov

On Fri, Aug 25, 2017 at 9:02 AM, Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us > wrote:

Good morning Mr. Pair:

Could you please assist? According to NMOCD database for the PLSS, BLM is shown as the surface owner. I have attached the C-141 in question.

For future questions such as this, please direct me to the appropriate person and/or website for verification.

Thanks much,

Olivia

From: Jennie Mastin [mailto: jenniemastin@amtexenergy.com]

Sent: Wednesday, August 23, 2017 1:46 PM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us >

Subject: Tomahawk SWD

Olivia,

Please find attached the Lea Co. Tax Office records. This should help clear up the "surface owner" on the C-141. Can you please send me a copy of the new C-141 that shows Merchant as the "surface" owner?

Thank you,

Jennie J. Mastin, CPL

Jennie J. Mastin, CPL

Amtex Energy, Inc.

P.O. Box 93983

Southlake, TX 76092

(817) 996-3738

 From:
 Yu, Olivia, EMNRD

 To:
 "Jennie Mastin"

 Cc:
 "Pair, Randal"

 Subject:
 RE: Tomahawk SWD

Date: Friday, August 25, 2017 1:22:00 PM

Attachments: revised_surface1RP4778.pdf

Ms. Mastin:

BLM has confirmed that the surface ownership is Fee. Please see the attachment for your records. All information remained the same except for the removal of the BLM annotation.

Olivia

From: Jennie Mastin [mailto:jenniemastin@amtexenergy.com]

Sent: Wednesday, August 23, 2017 1:46 PM **To:** Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>

Subject: Tomahawk SWD

Olivia,

Please find attached the Lea Co. Tax Office records. This should help clear up the "surface owner" on the C-141. Can you please send me a copy of the new C-141 that shows Merchant as the "surface" owner?

Thank you,

Jennie J. Mastin, CPL
Jennie J. Mastin, CPL
Amtex Energy, Inc.
P.O. Box 93983

Southlake, TX 76092

(817) 996-3738

From: Yu, Olivia, EMNRD

To: <u>"Patrick"</u>

Cc: "Clabe Pearson"; Herrmann, Keith, EMNRD

Subject: RE: 1RP-4778

Date: Friday, August 25, 2017 1:24:00 PM

Attachments: Amtex_OCD Permitting.pdf

Mr. McMahon:

NMOCD is not contesting surface ownership. NMOCD's database indicates BLM surface ownership, hence the notation. Please see the attachment as a record.

Regardless, I have inquired with BLM, and they have confirmed that this C-141 is indeed on Fee surface. Ms. Mastin with Amtex has the revised 1RP-4778.

Olivia

From: Patrick [mailto:hsncpbm@leaco.net]
Sent: Friday, August 25, 2017 11:28 AM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>

Cc: 'Clabe Pearson' <cjpj@leaco.net>; Herrmann, Keith, EMNRD <Keith.Herrmann@state.nm.us>

Subject: 1RP-4778

Dear Ms. Yu:

This firm represents Merchant Livestock Company, Inc. in regard to the above referenced matter. A copy of the Form C-141 is attached hereto for your review as well as a copy of a USGS map covering Township 21S, Range 33E, N.M.P.M.

My understanding of the NMOCD unit designations is that Unit L would be the NW/4 of the SW/4. A review of my client's property records and the USGS map shows that Unit L is located on deeded lands. Those deeded lands are owned by Merchant.

Would you please advise as to why the C-141 shows this surface as BLM and not Merchant? If you agree with my positon that Unit L is deeded land owned by Merchant, would you please make the necessary corrections. I look forward to hearing from you.

Patrick B. McMahon Heidel, Samberson, Cox & McMahon 311 North First

P.O. Drawer 1599

Lovington, New Mexico 88260

OCD Permitting

Home Land Searches Land Details

Section: 31-21S-33E Wells Operator Data OCD Review OCD Only Administration

Type: Normal
Total Acres: 625.08

County: Lea (25)

D (1)	R *	C (C)	R *	B (B)	R *	A (A)	R *	
State ¹		State ¹		State ¹		State ¹		
State ²		State ²		State ²		State ²		
(25)	36.17	(25)	40	(25)	40	(25)	40	
E (2)	R *	F (F)	R *	G (G)	R *	H (H)	R *	
State ¹		State ¹		State ¹		State ¹		
Sta	te ²	State	e 2	State ²		State ²		
(25)	36.24	(25)	40	(25)	40	(25)	40	
L (3)	R *	K (K)	R *	J (J)	R *	I (I)	R *	
Federal ¹		Fee ¹		Fee ¹		Fee ¹		
Sta	State ²		State ²		State ²		State ²	
(25)	36.3	(25)	40	(25)	40	(25)	40	
M (4)	R *	N (N)	R *	O (O)	R *	P (P)		
State ¹		State ¹		State ¹		State ¹		
State ²		State ²		State ²		State ²		
(25)	36.37	(25)	40	(25)	40	(25)	40	

Note * = Restriction Code(s)

Note ¹ = Surface Owner Rights

Note ² = Sub-Surface Mineral Rights

Land Restrictio	ns	
31-21S-33E A (A)	POT - Drilling Restricted Due to Potash	
31-21S-33E B (B)	POT - Drilling Restricted Due to Potash	
31-21S-33E C (C)	POT - Drilling Restricted Due to Potash	
31-21S-33E D (1)	POT - Drilling Restricted Due to Potash	
31-21S-33E E (2)	POT - Drilling Restricted Due to Potash	
31-21S-33E F (F)	POT - Drilling Restricted Due to Potash	
31-21S-33E G (G)	POT - Drilling Restricted Due to Potash	
31-21S-33E H (H)	POT - Drilling Restricted Due to Potash	
31-21S-33E I (I)	POT - Drilling Restricted Due to Potash	
31-21S-33E J (J)	POT - Drilling Restricted Due to Potash	
31-21S-33E K (K)	POT - Drilling Restricted Due to Potash	
31-21S-33E L (3)	POT - Drilling Restricted Due to Potash	



Lea County

GIS INTERNET REPORT



Page 1 of 3

Assessment Information


OWNER NUMBER: 50189

PARCEL NUMBER: 4000501890011

Owner Information		
Owner:	MERCHANT LIVESTOCK	
Mailing Address:	PO BOX 1105 EUNICE NM 88231	
Property Address:		

Subdivision Information		
Name:		
Unit:		
Block		
Lot:		

Legal Information				
156.30 AC LOC N2S2				







Lea County

GIS INTERNET REPORT



Page 2 of 3

Other Information				
Taxable Value:	\$5,571.00	Deed Book:		
Exempt Value:	\$0.00	Deed Page:	0	
Net Value	\$5,571.00	District:	080	
Livestock Value:	\$0.00	Section:	31	
Manufactured Home Value:	\$0.00	Township:	21	
Personal Property:	\$0.00	Range:	33	
Land Value:	\$16,083.00	Date Filed:		
Improvement Value:	\$630.00	Most Current Tax:	\$188.56	
Full Value:	\$16,713.00	Year Recorded:		

Square Foot and Year Built listed only to be used for comparative purposes, NOT to be used for commerce.



Lea County GIS INTERNET REPORT



Page 3 of 3