Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103		
District 1 – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 HOBBS O <u>District III</u> – (505) 334-6178	CD	30-025-37984		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			
811 S. First St., Artesia, NM 88210 (C) <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe. NM	$\frac{20051220}{5}$	STATE FEE		
District IV – (505) 476-3460 MPN - 1220 S. St. Francis Dr., Santa Fe, NM	Santa I C, IVIVI 07505	6. State Oil & Gas Lease No. A0-1543-0001		
87505				
SUNDRY NOTIGES	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATIO	North Monument G/SA Unit (302708)			
PROPOSALS.) 1. Type of Well: Oil Well 🖌 Gas	8. Well Number 342			
2. Name of Operator /	9. OGRID Number			
Apache Corporation		873		
3. Address of Operator	10. Pool name or Wildcat			
303 Veterans Airpark Lane, Suite 3000	Eunice Monument; G-SA (23000)			
4. Well Location				
Unit Letter 1 : 2000		feet from the Eastline		
Section 36	Township 19S Range 36E	NMPM County Lea		
	. Elevation (Show whether DR, RKB, RT, GR, etc., 84' GL			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK 🕢 PLUG AND ABANDON		REMEDIAL WORK 🛛 ALTERING CASING 🗌				
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS. P AND A				
PULL OR ALTER CASING 🛛 MULTIPLE COMPL		CASING/CEMENT JOB				
DOWNHOLE COMMINGLE						
OTHER:		OTHER:				
12 Describe prepared or completed exercising. (Clearly state all partiant details, and give partiant dates including estimated date						

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache intends to DO CICR @ 3720', perforate and acidize the Grayburg and RTP, per the attached procedure.

Spud Date:	7/28/2006		Rig Release Date:	8/5/2006	
I hereby certif	y that the informa	tion above is true and c	omplete to the best of	f my knowledge and belief.	
SIGNATURE	Klesa	Holland	TITLE Sr. Staff Re	g Tech	DATE3/13/2013
Type or print For State Use	name <u>Reesa Holl</u>	and	_ E-mail address: _Re	eesa.Holland@apachecorp.com	PHONE: <u>432/818-1062</u>
APPROVED Conditions of	BY: Approval (if any)	mala	TITLE	st. MGE	_DATE <u>3-20-20/3</u>
				MAR 2	2013

NMGSAU #342 API # 30-025-37984 Sec 36, T19S, R36E Elevation: 3596' KB, 3584' GL TD: 4,034' PBTD: 3,619' Casing Record: 8-5/8" @ 397' w/ 280 sxs 5-1/2" @ 4,035' w/ 491 N2 foamed sxs. TOC @ 3,490'

Perfs: Grayburg: 3684-90; 3698-3704; 3708-12; 3715-20; 3728-40; 3760-71; 3794-99; 3811-15; 3840-48; 3876-84; 3896-3906 w/ 2 jspf (158 holes). Squeezed w/ 300 sxs.

Objective: D/O CICR to 3720', perforate and acidize Grayburg and return to production.

AFE: PA-13-3470

- 1. MIRU unit. Check pressure on well.
- 2. ND WH. NU BOP. POOH w/ tubing. Unload and rack extra 2-7/8" tubing to be used as WS.
- 3. PU 4-3/4" bit, drill collars on 2-7/8" tubing and RIH to CICR. RU reverse unit. Break circulation and drill out CICR and cement to ~3720. Record PBTD. Circulate hole clean. POOH.
- MIRU WL. RIH w/ perforating gun and perforate the Grayburg from 3573-77; 3585-89; 3607-13; 3620-24; 3635-42; 3653-58; 3680-83; 3684-90 w/ 2 jspf 60° phasing Connex BH charges (78 holes). Correlate to Halliburton Dual-Spaced Neutron Collar Locator date 9/12/2006. POOH w/ WL. RDMO WL.
- 5. PU PKR and RIH w/ SN+PKR on 2-7/8" production tubing to bottom perfs at 3690. Spot 500 gal 15% NEFE acid across perforations from 3573-3690. TOH and set PKR above new perforations at ~3,520'.
- 6. MIRU acid services. Acidize down 2-7/8" J-55 tubing w/ 3000 gals of 15% NEFE HCL w/ additives using 120 ball sealers to divert evenly spaced through the job. Max treating pressure not to exceed 3000 psi or at the specifications of the Monument team. Displace to bottom perf with 25 BBLs of flush. Surge balls.
- 7. Release PKR and TIH to knock balls off perforations. TOH and set PRK at ~3,520.
- 8. RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 9. Kill well if necessary. Release PKR and TOH.
- 10. RIH w/ production tubing and rods as per the Monument office specification.
- 11. RDMOPU.
- 12. Set transfer pumping unit and install electrical services.
- 13. Return well to production and place into test for 10 days.



