

Submit 1 Copy To Appropriate District Office  
District I -- (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II -- (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III -- (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV -- (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-36832 ✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EAST HOBBS SAN ANDRES UNIT ✓
8. Well Number: 505 ✓
9. OGRID Number 269324
10. Pool name or Wildcat HOBBS; SAN ANDRES, EAST

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
LINN OPERATING, INC.

3. Address of Operator  
600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002

4. Well Location  
Unit Letter J 1720 feet from the S line and 2340 feet from the E line  
Section 30 Township 18S Range 39E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3604' DF Elevation

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Project Scope: RIH w/ RBP, Swab P2 zone individually, determine P2 potential, either RTP or TA with CIBP above top perf.

Please see attached well procedure.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE: Regulatory Compliance Specialist III DATE August 29, 2013

Type or print name TERRY CALLAHAN

E-mail address tcallahan@linnenergy.com

PHONE: 281-840-4272

For State Use Only

APPROVED BY:

TITLE

Petroleum Engineer

DATE

SEP 18 2013

Conditions of Approval (if any):

SEP 18 2013



# EHSAU 505

LEA COUNTY, NM

30-025-36832

08/26/2013

---

**Project Scope:** RIH w/ RBP, Swab P2 zone individually, determine P2 potential, either RTP or TA with CIBP above top perf.

---

**Well Procedure:**

1. Test anchors to at least 2200# prior to rigging up
2. MIRU WO Rig and record casing and tubing pressure.
3. Bleed pressure off of well. If well is flowing, flow back to frac tank or vac truck. Contact engineer if pressure does not die and well needs to be killed.
4. POOH w/ rods and pump. Visually inspect rods for corrosion and pitting and make notes of depths.
5. ND WH, screw on flange w/ O-ring seal or long thread connection w/ no seal. Tubing hanger either bowl w/ slips or flange.
6. NU 5000# BOP.
7. POOH w/ 2 7/8" tubing. Visually inspect for corrosion and pitting and make notes of depths. Do not pull more than 70,000#.
8. RIH w/ 4 3/4" bit and 5 1/2" casing scraper to bottom.
9. POOH w/ bit and scraper.
10. RIH w/ 5 1/2" Lok-set RBP and 2 7/8" x 5 1/2" CST compression packer and SN.
11. Set Lok-set RBP @ 4525'. Turn to the right and move downhole slowly to set. Hold left hand torque on the tubing to release on/off tool w/ J-Latch.
12. PU to 4475. Set CST packer @ 4475'. Turn to the left and put weight on packer to set.
13. RU 2 cup swab equipment w/ 7260# lubricator and hydraulic oil saver. Keep replacement cups on site.
14. Swab test production results. Discuss results with engineer.
15. Engineer to evaluate P2 economics and relay next steps to field.
16. RD swab equipment.
17. Unset CST packer. PU, equalize pressure between tubing and casing and turn to the right to unset.
18. Latch onto on/off tool w/ J-Latch and unset RBP. PU w/ 5000# over weight of tubing, equalize pressure and turn to the right.
19. POOH with RBP, packer and tubing. Rack back tubing in derrick. LD packer and RBP.
20. RU Gray wireline.
21. RIH with CCL and 5 1/2" premium CIBP. Correlate depths w/ existing GR.

**Contact Information:**

Matt Lake – Asset Engineer  
Cell – 713-263-4933  
Office – 281-840-4088

Jess Hayes - Foreman  
Cell – 575-602-3283

22. If P2 considered uneconomic by engineer:

- a. Set CIBP @ 4450'. Set w/ hydraulic setting tool on WL truck. Must be w/in 50' of perms.
- b. Dump bail 35' Class C cmt on top.
- c. RD Wireline.
- d. Conduct MIT, pressure up to 540# for 30 minutes.
- e. TA well.
- f. RDMO.

23. If P2 considered economic by engineer:

- a. Set CIBP @ 4525'. Set w/ hydraulic setting tool on WL truck.
- b. RIH with 2 7/8" 6.4# J55 tubing, TAC. Set tubing @ 4515'.
- c. ND BOP
- d. NU WH
- e. RIH w/ rods and pump. Space out pump 13". L&T tubing with no more than 26 bbls of fluid.
- f. RDMO.
- g. Reduce SPM on pumping unit to 7 SPM.
- h. RTP.

Contact Information:

Matt Lake – Asset Engineer  
Cell – 713-263-4933  
Office – 281-840-4088

Jess Hayes - Foreman  
Cell – 575-602-3283