Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II  HORBS OCD	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-041-20940
District III 1000 Rio Brazos Rd., Aztec, NM 87410 AUG 3 0 20131220 South St. Francis Dr.	5. Indicate Type of Lease STATE  FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	PEP 36 STATE
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well  Gas Well  Other	2
2. Name of Operator	9. OGRID Number
Armstrong Energy Corporation	1092
3. Address of Operator	10. Pool name or Wildcat 29783
P.O. Box 1973, Roswell, NM 88202-1973	Wildca+ 6.04 S033335m; P
4. Well Location	
Unit Letter M: 330 feet from the South line and	330 feet from the West line
Section 36 Township 05S Range 33E	NMPM Roosevelt County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
Fig. 10 and 10 a	Proceedings of the second seco
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check Appropriate Dox to indicate Nature of Notice,	report of Other Bata
NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII	<del>-</del>
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT	<del>_</del>
DOWNHOLE COMMINGLE	30b
DOVINHOLE COMMINGLE	
·	
OTHER: OTHER: Re	e-completion
OTHER:  OTHER:  OTHER:  Re  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details)	
	ent dates, including estimated date of starting any
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore	ent dates, including estimated date of starting any diagram of proposed completion or recompletion.
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore</li> <li>PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump</li> </ol>	ent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore</li> <li>PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai</li> </ol>	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls,
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls,
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'.	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls,
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey.	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls,
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg.	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three more constant of the start	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tais squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'.</li> <li>08-07-13 Run Gyro Survey.</li> <li>08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg.</li> <li>08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON</li> </ol>	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'.</li> <li>08-07-13 Run Gyro Survey.</li> <li>08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg.</li> <li>08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three new indow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit.</li> </ol>	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tais squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'.</li> <li>08-07-13 Run Gyro Survey.</li> <li>08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg.</li> <li>08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON</li> </ol>	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit.	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tais squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three movindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tais squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tais squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three movindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through evaluation.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertine proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through evaluation.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date: Rig Release Date:	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through evaluation.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three mindow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through evaluation.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date: Rig Release Date:	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  mills outside casing, worked mills through evaluation.  ge and belief.  Tations DATE 08-28-13
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three new indow, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE  TITLE Vice President - Ope	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  mills outside casing, worked mills through evaluation.  ge and belief.  Tations DATE 08-28-13
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give perting proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date: Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledges SIGNATURE  TITLE Vice President - Ope Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongener	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  mills outside casing, worked mills through evaluation.  ge and belief.  rations DATE 08-28-13  gycorp.com PHONE: (575) 625-2222
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertir proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date: Rig Release Date:  Title Vice President - Ope Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongener	nent dates, including estimated date of starting any diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  nills outside casing, worked mills through evaluation.  ge and belief.  rations DATE 08-28-13  gycorp.com PHONE: (575) 625-2222
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give perting proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore 08-02-13 PU 5-1/2" Squeeze Retainer and Setting Tool, TIH, set retainer @ 7582', pump 250 gals Flo-Chek A, 5 bbls FW Spacer, 100 sx HalCem w/ .5% Halad-322, tai squeezed to 5336 psi, 75 sx in formation. Sting out and reverse out cement. PC 08-05-13 Tested @ 1000 psi. Clean out to 7768'. 08-07-13 Run Gyro Survey. 08-08-13 Set CIBP @ 7707' and whipstock to 10.65 deg. 08-09-13 Start milling window, 1-2 pts on starting mill, made 10' of new hole, all three n window, no drag, circ hole w/ two volumes, POH. SDON 08-16-13 TD 7831', recovering pea size Shale, some pieces hanging Bit. 08-19-13 Cleaning out fill, unable to keep hole clean, rigging down. SD pending further ATTACHMENT: Pathfinder Directional Survey Report  Spud Date: Rig Release Date:  TITLE Vice President - Ope Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongener	diagram of proposed completion or recompletion.  10 bbls and establish rate @ 2.5 BPM. Pump l-in w/ 50 sx HalCem-H displaced w/ 36.6 bbls, DH w/ tbg and setting tool. SDON  mills outside casing, worked mills through evaluation.  ge and belief.  rations DATE 08-28-13  gycorp.com PHONE: (575) 625-2222