Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-01110 5. Indicate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.		STATE FEE S	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6 State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM		HOBBS OC	D	
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEPEN OR I	PLUGBANK TO A ZUIT	7. Lease Traine of Onit	Agreement Name
DIFFERENT RESERVOIR. USE AFFE	ICATION FOR PERMIT" (FORM C-101)	FOR SUCH RECEIVED	ZIMMERMAN A	4
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	MEORY	8. Well Number 1	
2. Name of Operator	Sub Well State		9. OGRID Number	
LEGACY RESERVES OPERATING LP ✓		240974		
3. Address of Operator		10. Pool name or Wildcat		
	848, MIDLAND, TX 79702		CAPROCK; QUEEN	1
4. Well Location				
Unit Letter N	: <u>660</u> feet from the <u>SOU</u>	<u>TTH</u> line and <u>19</u>	feet from the	<u>WEST</u> line
Section <u>21</u>	Township 14S	Range 31E	NMPM	County CHAVES
ment and the state of the state of	11. Elevation (Show whether D	OR, RKB, RT, GR, etc.)	t + 4 . 4 4	Carried to the
	4237' GL			
12 (1 1	A	NI CNI C	D . O.I D .	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF II	NTENTION TO:			
PERFORM REMEDIAL WORK		REN INT TO	DA NAA	
TEMPORARILY ABANDON	_	COL	CONT.	
PULL OR ALTER CASING	MULTIPLE COMPL	CAS P&A NE		·
DOWNHOLE COMMINGLE		RBDMS	IA _	
CLOSED-LOOP SYSTEM	1	0.71		
OTHER:	ploted aparations (Clearly state a	OTHER:	Laiva nortinant datas inc	aluding actimated data
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
See attached proposed P&A procedure along with current and proposed wellbore diagrams.				
NOTIFY OCD 24 HOURS PRIOR TO BEGINNING				
PLUGGING OPERATIONS				
Spud Date:	Rig Release	Date:		
I hereby certify that the information	above is true and complete to the	best of my knowledge	and belief.	
1 (/				
CICNATURE // 11 H	A TITLE	ODED ATIONS ENGIN	NEED DATE O	1/07/0016
SIGNATURE 17	TITLE	OPERATIONS ENGI	NEEKDATE_0	01/27/2016
Type or print nameJOHN	N SAENZ E-mail add	lress: jsaenz@legacy	lp.com PHONE	: 432-689-5200
For State Use Only	C man add		- I HOND	102 007 0200
V /	PIII DI	I E C	1.1.	12/1-
APPROVED BY: Warher	Motarca TITLE Tetr	roleum Engr. S	pecialist DATE	12/01/2016
Conditions of Approval (if any):		U		

FEB 0 1 2016

GN

Zimmerman A #1 API: 30-005-01110 Chavez County, New Mexico 1/25/2016




Note: shallow casing leak in production casing


Proposed P&A Procedure

1. MIRU. POH with tubing and packer.

- 255X
- 2. RIH and tag cement top @ 2810'. Cap cement with 50' of cement.
- 3. Circulate minimum 9.5 ppg P&A mud to 1000'. Pressure test csq.
- 4. TOOH. Perforate at 2130'.
- 5. RIH with PKR to 2000'. Pump into perf @ 2130' w/ minimum 50 sx cement. WOC, POOH w/packer, RIH w/ opened ended tubing and tag TOC at/above 2030'.
- 6. TOOH. Perforate at 1200'.
- 7. RIH with PKR to 1050'. Pump into perf @ 1200' w/ minimum 50 sx cement. WOC, POOH w/packer, RIH w/ opened ended tubing and tag TOC at/above 1100'. Circulate P&A mud to surface.
- 8. TOOH Perforate at 215'.
- 9. Circulate cement from 215' to surface inside and out.
- 10. WOC, top off casing, remove WH, set P&A marker, clean and reclaim location.

John Saenz





PBTD -TD - 2933'