Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-005-61333 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr. 5. Indicate Type of Lease 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 STATE FEE District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 6. State Oil & Gas Lease No. 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Twin Lakes San Andres Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number 112 1. Type of Well: Oil Well Gas Well Other INJECTION 2. Name of Operator 9. OGRID Number State of New Mexico formerly Canyon E&P Company 26986 3. Address of Operator 10. Pool name or Wildcat 811 South 1st Street Artesia, NM 88210 Twin Lakes; San Andres (Assoc) 4. Well Location Unit Letter 990 feet from the South West line line and 1650 feet from the Township 98 Section 7 Range 29E **NMPM** Chaves County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION --SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING | INT TO PA P AND A COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON** P&A NR PULL OR ALTER CASING CASING/CEMENT JOB P&AR DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. SEE ATTACHED I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE DATE Type or print name E-mail address:

For State Use Only

APPROVED BY:

Conditions of Approval (if any):

m

TITLE Petroleum Engr. Specialist DATE 03/14/2016

## Plugging Report TLSAU #112

3/2/2016 Worked on road and cleared location. Had to put temporary anchor on the SE corner. Moved equipment and rigged up. Had to heat well head cap to remove. Got cap, slips and 1 joint of tubing out of the well. Could not get the bowl out of the well head. Removed well head and replaced with one from the rig. Installed BOP. Moved in pipe from the #119 well. Could not get gauge ring past 1250'. Picked up scraper and bit. RIH to 2523'. POOH with scrapper and SION.

3/3/2016 RIH and set 4 ½" CIBP at 2504'. Attempted to circulate. Pumped 50 bbls. No circulation and no blow to the pit. POOH with setting tool. RIH with packer and set at 1193'. Could pump down tubing with 300# at 4.5 bbls/min. Attempted to load backside. Could not catch fluid but had fair blow to the pit from the surface casing. Released packer and reset at 1695'. Pumped 40 sx cement with CaCl below packer and displaced to 1907'. WOC and opened tubing. Pressured up to 500# and held. Estimated TOC @1900'. Released packer. Tested casing and found holes from 1130' to surface. Laid down packer and RIH open ended to 1130' and spotted 40 sx cement with CaCl. POOH and SION.

3/4/2016 RIH and tagged @ 1059'. Gained 71'. Spotted 50 sx cement with 100# of CaCl. WOC and tagged at 1013'. Gained 46'. Mixed 15 bbl slug of brine and drilling paper. Pumped down well with tubing at 1013'. Then spotted 50 sx cement with 100# CaCl at 1013'. Shut down for weekend.

3/7/2016 RIH and tagged at 1005'. Pumped 8 bbls brine with paper ahead of 50 sx with CaCl at 1005'. WOC and tagged cement at 997'. Mixed another 50 sx cement with CaCl and spotted at 997'. WOC and tagged cement at 997'. POOH to 502' as per OCD. Pumped 8 bbls brine with paper ahead of 50 sx cement with CaCl. SION. Never got fluid to surface while pumping today. Fluid level shows to be 75' from surface.

RIH and tagged cement at 432'. Established good circulation and pumped cement down 4 ½" casing to holes at 188' and up annulus to surface. Took 70 sx to get good cement to surface. Rigged down. Cut off well head and filled up both string of casing with 1 sack of cement. Installed marker and cut off anchors. Cleaned the pit and cleared the location.