

Submit 1 Copy To Appropriate District Office

State of New Mexico

Form C-103

District I - (575) 393-6161

**HOBBS OGD**

Minerals and Natural Resources

Revised July 18, 2013

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

APR 15 2019

RECEIVED

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. 30-025-42119
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1839-1
7. Lease Name or Unit Agreement Name East Vacuum GB-SA Unit Tract 2739
8. Well Number 526
9. OGRID Number 217817
10. Pool name or Wildcat Vacuum; GB-SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3936' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator

ConocoPhillips Company

3. Address of Operator

P. O. Box 51810, Midland TX 79710

4. Well Location

Unit Letter K : 1736 feet from the South line and 1452 feet from the West line  
Section 27 Township 17S Range 35E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- DOWNHOLE COMMINGLE
- CLOSED-LOOP SYSTEM
- OTHER: Add plug & Pay to SA

SUBSEQUENT REPORT OF:

- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPL
- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING/CEMENT JOB
- ALTERING CASING
- P AND A
- OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

ConocoPhillips Company would like to set plug above existing perms and add perms to the upper San Andres per attached procedure.  
Attached is a current/proposed wellbore schematic.

Spud Date:

[Empty box for Spud Date]

Rig Release Date:

[Empty box for Rig Release Date]

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rhonda Rogers TITLE Regulatory Tech DATE 4/9/2019

Type or print name Rhonda Rogers E-mail address: rogerrs@conocophillips.com PHONE: 432-688-9174

For State Use Only

APPROVED BY: Kerry Fortner TITLE Compliance Office A DATE 4-22-19

Conditions of Approval (if any):

**EVGSAU 2739-526  
Plug Set Pay Add  
API #30-025-42119**

**Project Scope**

**Background and Justification:**

EVGSAU 2739-526 is a new drill well planned for recompletion higher up in the TZROZ and San Andres main pay. A plug will be set above existing perforations and 8 new perf intervals will be added.  
10/2017 Initial completion and ESP installation

**Downhole Configuration**

Type	Top	Bottom
Perforations	4700'	4,910'
PBTD (float collar)		5,112'
TD		5,155'

**Well Service Procedure:**

**Before rigging up conduct safety meeting & review JSA**

1. NDWH, NUBOP and test.
2. RU cable & CT spoolers. TOOH & stand back 142 jts tubing and LD Schlumberger ESP assembly. RD spoolers.
  - Send ESP to Schlumberger for testing/prep for rerun. Send cable in for testing and any necessary repairs.
  - If tubing/pump comes out with paraffin/asphaltenes/scale, contact NalcoChampion to take a sample.
3. MI & PU additional ~5 tubing joints for bit & scraper run.
4. PU & RIH with bit and scraper sized for 7", 23# casing. Clean out down to ~4,710' (just below proposed CIBP set depth).
5. RU tubing scanner. POOH scanning tubing and stand back yellow joints. LD bit & scraper.
6. MIRU wireline services. NU 5000 psi lubricator.
  - Note: lubricator shop tested to 2,000 psi is acceptable.
  - Note: Correlate w/gamma ray from Schlumberger Spectral GR-CCL log dated 8/10/2017.
7. PU & RIH with CIBP for 7", 23# casing and set at ~4,695'.
8. CUH one stand and pressure test CIBP to 3000 psi. COOH
9. Load wellbore prior to running in hole with guns.
10. PU & RIH w/guns to perforate using 4" Titan Slick Gun w/super deep penetrating charges [ch-40g, eh-0.52", pen - 52.13 (or equivalent)] dressed for 2SPF w/120° phasing. Conduct any repeat gun runs as necessary to perforate as follows:
  - Perforate from 4,660'-4,694' (34' net, 2 SPF, 120 degree phasing)
  - Perforate from 4,601'-4,617' (16' net, 2 SPF, 120 degree phasing)
11. Pull fired guns into lubricator, bleed lubricator, & remove spent guns. Verify all shots fired.

**EVGSAU 2739-526  
Plug Set Pay Add  
API #30-025-42119**

12. PU 2-7/8" tubing and packer and RIH. Hydrotest to 5000 psi.
13. RU acid services.
14. Spot acid across perfs (3 bbls/126 gals), set packer @ +/- 4550' and establish rate.
15. Prep to pump stage 1. Utilize remote ball launcher. Record treating pressure, rate, diverter action if any, ISIP & pressures at 5 min, 10 min, and 15 min.
16. Pump job as follows: break down perfs with 15% NEFE HCL and drop 1.1 SG, 7/8" biodegradable ball sealers for diversion (adjust diameter as necessary based on perf guns procured). Minimum of 7,500 gals of acid (~180 bbls) will be required for both stages, as well as a frac tank with 85 bbls (3570 of biocide treated fresh water).

**Target rate for the stage is 12 bbls/min.**

Step	2739-526 Stage #1	
1	Acid	Pump ~19 bbls (780 gals) 15% NEFE HCL
2	Acid + Ball sealers	Pump ~19 bbls (780 gals) 15% NEFE HCL, dropping 75 balls
3	Acid	Pump ~19 bbls (780 gals) 15% NEFE HCL
4	Acid + Ball sealers	Pump ~19 bbls (780 gals) 15% NEFE HCL, dropping 75 balls
5	Acid	Pump ~19 bbls (780 gals) 15% NEFE HCL
6	Flush	Pump 40 bbls (1680 gals) of treated fresh water as flush

*Note: If ball out occurs, SD & surge perfs 3 times.*

<b>TREATING LINE TEST PRESSURE: A minimum 500 psig over MAWP. Acceptable test will be no more than 300 psi leak off in 5 minutes, with no more than 1% leak off in last minute, AND NO VISIBLE LEAKS.</b>	<b>6,550</b>	<b>PSIG</b>
<b>MAXIMUM ALLOWABLE WORKING PRESSURE: Based on weakest component in system</b>	<b>6,050</b>	<b>PSIG</b>
<b>MAX SURFACE PRESSURE:</b>	<b>5,085</b>	<b>PSIG</b>

17. POOH w/tbg
18. RIH with RBP on wireline and set RBP at ~4,590'. COOH.
19. Pressure test RBP to 3000 psi
20. Load wellbore prior to running in hole with perforating guns; confirm that well is loaded and RBP is holding.
21. PU & RIH w/guns to perforate second stage using 4" Titan Slick Gun w/super deep penetrating charges [ch-40g, eh-0.52", pen - 52.13 (or equivalent)] dressed for 2SPF w/120° phasing. Conduct any repeat gun runs as necessary to perforate as follows:
  - Perforate from 4,562'-4,566' (4' net, 2 SPF, 120 degree phasing)
  - Perforate from 4,519'-4,539' (20' net, 2 SPF, 120 degree phasing)

**EVGSAU 2739-526**

**Plug Set Pay Add**

**API #30-025-42119**

- Perforate from 4,497'-4,505' (8' net, 2 SPF, 120 degree phasing)
- Perforate from 4,472'-4,478' (6' net, 2 SPF, 120 degree phasing)
- Perforate from 4,455'-4,460' (5' net, 2 SPF, 120 degree phasing)
- Perforate from 4,402'-4,407' (5' net, 2 SPF, 120 degree phasing)

22. Pull fired guns into lubricator, bleed lubricator, & remove spent guns. Verify all shots fired. Record in WellView. ND/LD lubricator and guns. RDMO wireline service provider.
23. RIH w/tbg string including retrieving head. Spot acid across perfs (3 bbls/126 gals), set packer @ +/- 4350' and establish rate.
24. Prep acid services to pump stage 2. Once again, utilize remote ball launcher. Record treating pressure, rate, diverter action, ISIP & pressures at 5 min, 10 min, and 15min.

Step	2739-526 Stage #2	
1	Acid	Pump ~17 bbls (720 gals) 15% NEFE HCL
2	Acid + Ball sealers	Pump ~17 bbls (720 gals) 15% NEFE HCL, dropping 75 balls
3	Acid	Pump ~17 bbls (720 gals) 15% NEFE HCL
4	Acid + Ball sealers	Pump ~17 bbls (720 gals) 15% NEFE HCL, dropping 75 balls
5	Acid	Pump ~17 bbls (720 gals) 15% NEFE HCL
6	Flush	Pump 45 bbls (1890 gals) of treated fresh water as flush

*Note: If ball out occurs, SD & surge perfs 3 times.*

25. RDMO acid services
26. Let well sit overnight
27. Unset packer, and circulate to remove any balls that have not degraded
28. Retrieve RBP at ~4,590' and POOH
29. RU cable and CT spoolers. PU & RIH w/ Schlumberger D3500N/MGH ESP assembly, cables, and tubing.
- ESP will be installed with a pressure discharge line running from the sensor to above the top pump.
  - The CT line should be terminated at or below the sensor.
  - Run any replacement tubing joints on bottom of string.
  - Position bottom of the ESP assembly @ ~4,370'.
30. Have SLB tech measure cable to length, splice, and install lower pigtail into hanger.
31. Land tubing in hanger. NDBOP, NUWH, connect upper pigtail.
32. Startup ESP @ 45 hz unless otherwise instructed. Adjust pump speed per downhole conditions. Ensure well pumps up before RD.
33. Notify MSO to sign off.
34. RDMO, clean location, release all ancillary rental equipment.



# Current Tubing Configuration EAST VACUUM GBSA UNIT 2739-526 3002542119

