

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMNM15091
2. Name of Operator BTA OIL PRODUCERS /		6. If Indian, Allottee or Tribe Name
Contact: PAM INSKEEP E-Mail: pinskeep@btaoil.com		7. If Unit or CA/Agreement, Name and/or No
3a. Address 104 S. PECOS MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-682-3753 Ext: 139 Fx: 432-683-0325	8. Well Name and No ROJO, 7811 JV-P 1 /
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 27 T25S R33E NWNW 660FNL 660FWL /		9. API Well No. 30-025-26188 /
		10. Field and Pool, or Exploratory RED HILLS, DEVONIAN (GAS) /
		11. County or Parish, and State LEA COUNTY COUNTY, NM /


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attachment

RECEIVED
JUN 27 2008
HOBBS OCD



14. I hereby certify that the foregoing is true and correct. Electronic Submission #60932 verified by the BLM Well Information System For BTA OIL PRODUCERS, sent to the Hobbs	
Name (Printed/Typed) BOB STUCKLEY	Title IT MANAGER
Signature (Electronic Submission)	Date 06/17/2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title _____	Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office _____

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****

Attachment to 3160-5
06/17/2008

BTA Oil Producers
7811 JV-P Rojo # 1
30-025-26188

Procedure to Plug Back and Test Additional Potential in Well
Red Hills (Devonian) Field
Lea County, New Mexico

<u>Well Data:</u>	TD 17525' BP 17522'	<u>Elevations:</u>	3369' KB 3339' GL 30' Diff
Casing:	20" 94# H-40 CSA 909' w/ 1650 Sx (Cmt Circ) 13-3/8" 68 & 73# K-55,N-80 & S-80 CSA 4941' w/ 3400 Sx (Cmt Circ) 9-5/8" 47 & 53.5# SOO-95 CSA 12992' w/ 2 Stages; 1 st Stg 1900 Sx, 2 nd Stg 400 Sx; DV Tool @ 7193' (TOC @ 4890' By Temp Survey)		
Liner:	7-3/4" 46.1# P-110 Liner from 12594' to 16960' w/ 450 Sx 5" 23.2# C-75 Liner from 16547' to 17524' w/ 200 Sx		
Packer:	5" Baker Model DB @ 17,320' w/ EOT @ 17,408'		
Tubing:	1 jt – 3-1/2" f12.95# C-75 Ph6 (31.65'); 1 – double pin sub (0.49'); 384 jts – 3-1/2" 10.3# C-75 CS Hydril (12803.14'); XO sub 3-1/2" to 2-7/8" (.9); 137 jts – 2-7/8" L-80 CS Hydril (4515.56'); Baker Seal Assembly (Size40-26) 10.78'		
Perfs:	Devonian – 17,420'; 17,428'; 17,452'; 17,454'; 17,458'; 17,460'; 17,462'; 17,466'; 17,469'; 17,471'; 17,475'; 17,477'; 17,481'; 17,483'; 17,485'; 17,489'; 17,491'; 17,496'; 17,498'; 17,502'; 17,506'; 17513'		

Procedure:

- 1) Clean location and set anchors. Move in and rig up tanks. Move in and rig up hydrogen sulfide safety company monitors and breathing masks. Move in and rig up pulling unit.
- 2) ND WH. NU BOP. Pick up on tubing to check weight.
- 3) RU Wireline truck. Run in hole with gauge ring for 2-7/8" tubing. Run to packer at 17,320' if possible.
- 4) Run free point tool to determine where tubing is free.
- 5) Depending on depth of free point follow steps below:
 - a) Attempt to pullout of packer with seal assembly. If can pull out of packer, POH with tubing and run CIBP 5" 23.2# casing to 17,300', set and cap with 40' of cement.

- b) If free point is above packer and below 16,000', set CIBP in 2-7/8" tubing below 16,000', cut tubing and pull out of hole.
- c) If free point is above 16,000', back off tubing above free point and pull out of hole. Wash over tubing to get top of fish below 16,000'.
- 6) Rig up wireline truck. Run in hole with CIBP for 7-3/4" 46.1# casing to +/- 16,000', set and cap with 40' cement.
- 7) Run in hole with tubing and scraper for 7-3/4" 46.1# casing. Load hole with 10# brine water.
- 8) Pull out of hole with tubing. Lay down tubing and send to yard.
- 9) Rig up Wireline truck and run casing inspection log from PBTD to surface. Depending on log evaluation additional program will follow.
- 10) Pick up Arrowset 1 fullbore packer for 7-3/4" 46.1# casing with wireline entry sub on bottom, pick up 2 7/8" 6.5# AB Mod tubing and run in hole to 15,856'.
- 11) Spot 400 gallons 7-1/2% Morrow Sand acid weighted to 10# per gallon.

- 12) Raise packer to 15,600'. Pump 2 bbls down casing. Set packer at 15,600'.
- 13) ND BOP. NU WH.
- 14) Move in and rig up test equipment. Pressure test wellhead and flow line to 8000 psi.
- 15) Rig up wireline truck with 10,000 psi lubricator. RIH w/ 2-1/8" decentralized hollow carrier Gamma Gun with premium charges with 2 JSPF. Correlate to Schlumberger Compensated Neutron Formation Density log dated 5/18/09. Perforate Morrow "B" zone at 15,692 – 694' and Morrow "C" zone at 15,853 – 856'. Could be 3536 psi under-balanced after perfring.
- 16) RD wireline truck and lubricator.
- 17) If no pressure is noted, rig up pump truck and break down perfs and displace acid. If well shows pressure after perfring prepare to flow back.
- 18) Flow test, report rates pressures to Midland Office. Catch fluid and gas samples before shutting well in.
- 19) If Morrow B & C zones are none productive go to Step 20.
- 20) Load tubing with 10# brine.
- 21) ND WH. NU BOP.
- 22) Release packer and pull out of hole.
- 23) Rig up Wireline truck. Run in hole with CIBP for 7-3/4" 46.1# casing. Set CIBP at +/- 15650'. Cap with 40' cement.
- 24) Run in hole with Arrowset 1 fullbore packer for 7-3/4" 46.1# casing with wireline entry sub on bottom, on 2 7/8" 6.5# AB Mod tubing to 15,285'.
- 25) Spot 200 gallons 7-1/2% Morrow Sand acid weighted to 10# per gallon.
- 26) Raise packer to 15,000'. Pump 2 bbls down casing. Set packer at 15,000'.
- 27) ND BOP. NU WH.
- 28) Pressure test wellhead and flow line to 8000 psi.
- 29) Rig up wireline truck with 10,000 psi lubricator. RIH w/ 2-1/8" decentralized hollow carrier Gamma Gun with premium charges with 2 JSPF. Correlate to Schlumberger Compensated Neutron Formation Density log dated 5/18/09. Perforate Morrow "EO" zone at 15,280 – 285'. Could be 3400 psi under-balanced after perfring.
- 30) RD wireline truck and lubricator.
- 31) If no pressure is noted, rig up pump truck and break down perfs and displace acid. If well shows pressure after perfring prepare to flow back.
- 32) Flow test, report rates pressures to Midland Office. Catch fluid and gas samples before shutting well in.
- 33) If Morrow EO zone is none productive go to Step 34.
- 34) Load tubing with 10# brine.
- 35) ND WH. NU BOP.
- 36) Release packer and pull out of hole.
- 37) Rig up Wireline truck. Run in hole with CIBP for 7-3/4" 46.1# casing. Set CIBP at +/- 15240'. Cap with 40' cement.
- 38) Run in hole with Arrowset 1 fullbore packer for 7-3/4" 46.1# casing with wireline entry sub on bottom, on 2 7/8" 6.5# AB Mod tubing to 15,050'.
- 39) Spot 200 gallons 7-1/2% Morrow Sand acid weighted to 10# per gallon.
- 40) Raise packer to 14,800'. Pump 2 bbls down casing. Set packer at 14,800'.
- 41) ND BOP. NU WH.
- 42) Pressure test wellhead and flow line to 8000 psi.
- 43) Rig up wireline truck with 10,000 psi lubricator. RIH w/ 2-1/8" decentralized hollow carrier Gamma Gun with premium charges with 2 JSPF. Correlate to Schlumberger Compensated Neutron Formation Density log dated 5/18/09.

- balanced after perfling.
- 44) RD wireline truck and lubricator.
 - 45) If no pressure is noted, rig up pump truck and break down perfs and displace acid. If well shows pressure after perfling prepare to flow back.
 - 46) Flow test, report rates pressures to Midland Office. Catch fluid and gas samples before shutting well in.
 - 47) If Morrow "Clastic" zone is none productive go to Step 48.
 - 48) Load tubing with 10# brine.
 - 49) ND WH. NU BOP.
 - 50) Release packer and pull out of hole.
 - 51) Rig up Wireline truck. Run in hole with CIBP for 7-3/4" 46.1# casing. Set CIBP at +/- 15000'. Cap with 40' cement.

- 52) Run in hole with Arrowset 1 fullbore packer for 7-3/4" 46.1# casing with wireline entry sub on bottom, on 2 7/8" 6.5# AB Mod tubing to 14,355'.
- 53) Spot 200 gallons 7-1/2% Morrow Sand acid weighted to 10# per gallon.
- 54) Raise packer to 14,100'. Pump 2 bbls down casing. Set packer at 14,100'.
- 55) ND BOP. NU WH.
- 56) Pressure test wellhead and flow line to 8000 psi.
- 57) Rig up wireline truck with 10,000 psi lubricator. RIH w/ 2-1/8" decentralized hollow carrier Gamma Gun with premium charges with 2 JSPF. Correlate to Schlumberger Compensated Neutron Formation Density log dated 5/18/09. Perforate Atoka Sand zone at 14,346 – 355'. Could be 3200 psi under-balanced after perfin.
- 58) RD wireline truck and lubricator.
- 59) If no pressure is noted, rig up pump truck and break down perfs and displace acid. If well shows pressure after perfin prepare to flow back.
- 60) Flow test, report rates pressures to Midland Office. Catch fluid and gas samples before shutting well in.

Estimated Cost: \$ 993,500

Payout: If oil and gas rates 50 BOPD and 2500 MCFD are obtained payout will be 1.8 months with \$85.02/BO and \$7.74/MCF gas.

5/27/08

____ / ____ / ____