

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-041-20493 ✓
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	NA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Devon Energy Corporation (Nevada)
3. Address of Operator 20 North Broadway Suite 1500 Oklahoma City, OK 73102

7. Lease Name or Unit Agreement Name Tucker
8. Well No. #1
9. Pool name or Wildcat Tucker Ranch (Bough C)

4. Well Location
Unit Letter J : 1980 Feet From The south Line and 1980 Feet From The east Line
Section 9 Township T7S Range R33E NMPM Roosevelt County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4401.1 G. L.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NOTE: Jerry Sexton verbally approved this procedure on 2/4/93.

Devon plans to plug and abandon this well as follows:

- Run in the hole with 2 3/8" open ended tubing to 6620'+ and plug off the casing from collapse point to the perms with 300 sks cement. Let cement fall to perms then pressure up on the plug. Pump additional cement if the 1st plug doesn't hold pressure.
- Position 50 sk cement plug at the collapse point (6620'+). Pull the tubing.
- Shoot off and pull the 4 1/2" casing at the base of the 8 5/8" casing. Spot a 50 sk+ plug from inside the 4 1/2" casing stub to 100' inside the 8 5/8" casing.
- Position 30 sk (100') plug in the 8 5/8" casing above the salt at 1900'+. Circulate 10 sk plug from 40' to surface.
- Cut off and remove all wellhead equipment. Weld on dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charles W. Horsman TITLE District Engineer DATE 4/8/93

TYPE OR PRINT NAME Charles W. Horsman TELEPHONE NO. 405-552-4508

(This space for State Use)
ORIGINAL SENT BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 13 1993

THE COMPLETION DATE BE NOTIFIED BY
THE OPERATOR TO THE DISTRICT SUPERVISOR
BY THE OPERATOR TO THE DISTRICT SUPERVISOR