

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A	5. LEASE DESIGNATION AND SERIAL NO. NM0174830 A
2. NAME OF OPERATOR Atlantic Richfield Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEL (Unit letter G)	8. FARM OR LEASE NAME Mona Federal
14. PERMIT NO.	9. WELL NO. 5
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4414' DF	10. FIELD AND POOL, OR WILDCAT Chaveroo San Andres
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 17-T8S-R33E
	12. COUNTY OR PARISH Chaves
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐Plug & Abandon ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Present well status: TD 9040', PBD 4331'.

13-3/8" OD csg @ 392' cmtd to surface.

8-5/8" OD csg @ 3569' cmtd w/585 sx. TOC @ 2300' from surface.

5-1/2" OD csg @ 9035' cmtd w/400 sx.

Well was P&A 4/27/65 in following manner:

CIBP set @ 8860' w/15' cmt on top.

Cut 5 1/2" csg @ 4509' & pulled. 40 sx cmt from 4560-4509'.

Well was re-entered 5/8/66. Set 4356' of 4 1/2" OD csg cmtd w/250 sx. TOC @ 3640'.

Present perforations 4234-86'.

24 Sacks Propose to P&A as follows:

Set 20 sk cmt plug 4066-4282' (218')

Cut 4 1/2" OD csg @ 3600' & pull.

Set 40 sk cmt plug across 4 1/2" csg stub @ 3600' and 8-5/8" OD csg shoe @ 3569' (3500-3670)

Pull 8-5/8" OD csg from free point @ approx 2200'. Set 90 sk cmt plug across 8-5/8" csg stub. Set 90 sk cmt plug across 13-3/8" csg shoe 350-454'. Set 10 sk cmt plug

@ surface. Spot heavy mud-laden material between all plugs. Install regulation marker, level & clean location.

NOTIFY USGS IN TIME TO
WITNESS PLUGGING OPERATIONS

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Drlg. Supv.

DATE

6/18/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side