Submit 3 Copies to Appropriate District Office

State of New Mexico

Form C-103 Revised 1-1-89

Energy, Minerals and Natural Resources Department

	P.O. Box 2088	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		30 025 28631
		5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICA" (FORM C-101) FOR SUCH PRO	ATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL OT		Saunders State
2. Name of Operator	HER	
Tamarack Petroleum Company, Inc.		8. Well No.
3. Address of Operator		9. Pool name or Wildcat
500 W. Texas, Suite 1485, Midland, TX 79701		Saunders (Permo Upper Penn)
4. Well Location	1.22 73701	badilders (rermo opper remi)
Unit Letter 0 : 330 Feet From The	South Line and 16	Feet From The East Line
Section 9 Township 14.5	South Range 33 East	NMPM Lea County
	a (Show whether DF, RKB, RT, GR, etc.)	V/////////////////////////////////////
	4221 GR	
11. Check Appropriate Box	to Indicate Nature of Notice, F	Report, or Other Data
NOTICE OF INTENTION TO:		SEQUENT REPORT OF
PERFORM REMEDIAL WORK PLUG AND ABA		X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	S COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND C	EMENT JOB
OTHER:	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all per		
Describe i represent of Completed Operations (Clearly state all per	riment delaus, and give pertinent dates, incli	iding estimated date of starting any proposed
work) SEE RULE 1103.		
<pre>work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p</pre>	oump, install BOP, start	pulling tubing.
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca	oump, install BOP, start asing 1 hole per foot as	pulling tubing. follows: 9806-9810', 9814-982
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868',	oump, install BOP, start asing 1 hole per foot as	pulling tubing. follows: 9806-9810', 9814-982
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p.	oump, install BOP, start asing 1 hole per foot as , 9871-9873', 9888-9890'	pulling tubing. follows: 9806-9810', 9814-9823, 9980-9983', 9989-9996', Wirel
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959	oump, install BOP, start asing 1 hole per foot as , 9871-9873', 9888-9890' 9', acidize perforations	pulling tubing. follows: 9806-9810', 9814-982; , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p. 93 Finish pulling tubing. Perforate ca. 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959. at 36#. ISIP O#. Set RBP at 9965' &	oump, install BOP, start asing 1 hole per foot as , 9871-9873', 9888-9890' O', acidize perforations & packer at 9775'. Acidi	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirels w/1750 gals. 15% NEFE, 4-1/2 BPR ze perforations w/3000 gals. 15%
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & pulling tubing. Perforate can 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin	oump, install BOP, start asing 1 hole per foot as , 9871-9873', 9888-9890' O', acidize perforations & packer at 9775'. Acidi and perforations 9915'-9	pulling tubing. follows: 9806-9810', 9814-9823, 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPR ze perforations w/3000 gals. 15% 940').
 work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & 	oump, install BOP, start asing 1 hole per foot as , 9871-9873', 9888-9890' O', acidize perforations & packer at 9775'. Acidi and perforations 9915'-9 ce, recover 3 bbls. flui	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPR ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9955 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin 93 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9 re, recover 3 bbls. flui lay down. Start running	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing.
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin 93 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and 93 Run balance of tubing, rods, & pump pump 2-1/2" x 1-1/2" x 26'.	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9e, recover 3 bbls. fluit lay down. Start running, bottom of tubing 9963	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing.
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin 93 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and 93 Run balance of tubing, rods, & pump	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9e, recover 3 bbls. fluit lay down. Start running, bottom of tubing 9963	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing.
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p 93 Finish pulling tubing. Perforate ca 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin 93 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and 93 Run balance of tubing, rods, & pump pump 2-1/2" x 1-1/2" x 26'.	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9e, recover 3 bbls. fluit lay down. Start running, bottom of tubing 9963	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing.
work) SEE RULE 1103. 93 Move in pulling unit, pull rods & p. 93 Finish pulling tubing. Perforate ca. 9830-9838', 9858-9860', 9866-9868', PBTD 9997'. 93 GIH w/tubing and set packer at 9959. at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origin 93 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and 93 Run balance of tubing, rods, & pump pump 2-1/2" x 1-1/2" x 26'.	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9e, recover 3 bbls. flui lay down. Start running, bottom of tubing 9963 water in 24 hours.	pulling tubing. follows: 9806-9810', 9814-9823 , 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPN ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing.
Work) SEE RULE 1103. 93 Move in pulling unit, pull rods & pulling tubing. Perforate cays 3 Finish pulling tubing. Perforate cays 3 GIH w/tubing and set packer at 9959 at 36#. ISIP 0#. Set RBP at 9965' & NEFE and ball sealers. (Well origing 3 TP-380#, CP - 16#, bled off pressur at 9775'. Unset RBP and packer and Run balance of tubing, rods, & pump pump 2-1/2" x 1-1/2" x 26'. 93 Well pumped 39 bbls. oil, 5 bbls. Well pumped 39 bbls.	oump, install BOP, start asing 1 hole per foot as 9871-9873', 9888-9890' O', acidize perforations packer at 9775'. Acidinal perforations 9915'-9e, recover 3 bbls. flui lay down. Start running, bottom of tubing 9963 water in 24 hours.	pulling tubing. follows: 9806-9810', 9814-9823, 9980-9983', 9989-9996', Wirel: w/1750 gals. 15% NEFE, 4-1/2 BPR ze perforations w/3000 gals. 15% 940'). d. Swab well from seating nipple g production tubing. ', seating nipple 9929', rod

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

-- TITLE --

JUL 06 1993

SEE OF THE SERVICE OF