

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

DATE RECEIVED	
DATE SUBMITTED	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-2894

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
Name of Operator	Lovington San Andres Unit
Texaco Producing Inc.	8. Farm or Lease Name
Address of Operator	9. Well No.
P. O. Box 728, Hobbs, NM 88240	9
Location of Well	10. Field and Pool, or VHDcat
UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 16S RANGE 36E NMPM.	Lovington San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3842 DF	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

INFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
REPAIR OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	
OTHER ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Pull rods & pump.
- 2) Install BOP. Pull tubing and packer.
- 3) GIH w/6 1/4" bit on 2 7/8" workstring. Tag TD. Clean out to 5100', if necessary.
- 4) GIH w/RBP and packer. Test csg to 500#. Repair if necessary.
- 5) Run GR-CNL-CAL-CCL 5100'-2500'.
- 6) GIH w/pkr to +4600'. Load backside.
- 7) Acidize San Andres OH 4645-5100' w/10,000 gal gelled 15% NEFE in 3 stages w/+1000# rocksalt in gelled brine between each stage as a block. Mix 2 drums scale inhibitor in acid (12 BPM, 6000#).
- 8) Flow back load.
- 9) GIH q/RBP to +4620'
- 10) Perforate Grayburg w/2 JSPI w/4" csg. gun. (Estimate 11 int, 22 holes).
- 11) GIH w/pkr to +4400'.
- 12) Acidize Grayburg perms w/5000 gal gelled 15% NEFE and ball sealers. Mix 1 drum scale inhibitor in the acid. (5BPM, 4000#).
- 13) Flow back load.
- 14) Retrieve RBP.
- 15) Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE District Admin. Supervisor DATE 09/12/86

ORIGINAL SIGNED BY JERRY SEXTON

PROVED BY DISTRICT 1 SUPERVISOR

TITLE _____

DATE SEP 29 1986

INDICATIONS OF APPROVAL, IF ANY: