

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☐ gas well ☐ other

2. NAME OF OPERATOR
Pennzoil Company

3. ADDRESS OF OPERATOR
P.O. Drawer 1828, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FNL, 2310' FEL, Sec 33, T17, R33
AT TOP PROD. INTERVAL: 4414'
AT TOTAL DEPTH: 4490'

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

APR 14 1980

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

5. LEASE
Phillips Federal NM801

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Phillips Federal

9. WELL NO.
4

10. FIELD OR WILDCAT NAME
Maljamar Grayburg/SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 33, T-17-S, R-33-E

12. COUNTY OR PARISH: 13. STATE
Lea New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
4133' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

REASON FOR ABANDONMENT: Well has produced nothing but water since completion.


SEE ATTACHED PLUG & ABANDONMENT PROCEDURE

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. V. Bulling TITLE Operations Engineer DATE April 11, 1980

(This space for Federal or State office use.)



TITLE _____ DATE _____
AS AMENDED
gdk

*See Instructions on Reverse Side

PHILLIPS FEDERAL NO. 4
MALJAMAR AREA
SEC 33, T-17-S, R-35-E
LEA COUNTY, NEW MEXICO

PLUG & ABANDON PROCEDURE

WELL DATA

Casing: 12-3/4" set @ 355' w/475 sx (circ 15 sx)
5-1/2" 15.5 17# set @ 4490' w/1200 sx
(DV Tool @ 1410', Circ 118 sx to surf)

KB: 12.85'

PBTD: 4481'

Perfs: 4414-32, 4442-60, 4472-79

Tubing: 2-3/8"

Top of Salt Section: ~~1800'~~ 1385'?

PROCEDURE

1. MI&RU plugging unit.
2. POH w/2-3/8" tubing.
3. RIH w/5-1/2" CIBP on W.L. Set plug @ ±4375' & dump ^{100'}~~35'~~ cmt on top.
4. RIH w/open ended 2-3/8" tbg & circ hole w/salt gel.
5. Spot 100' cmt plug (20 sx) from ~~1800'~~ (top of salt) to ~~1700'~~. 1350' To 1450'
6. Spot 10 sx at surf and set marker.

JVD/afb
4/11/80