

**Proposed Plugging Procedure  
State A-17 #7**

Surface casing: 7-5/8" 24# @ 355', cmt'd w/ 200 sx  
Production csg: 4½" 9.5# H40 @ 3,688' cmt'd w/ 350 sx, TOC 2,200' by T.S.  
Openhole: 3,688 – 4,006' sqz'd w/ 100 sx  
Perforations: Grayburg 3,892 – 3,978'.  
Last Work: Amerada Hess 7/11/94 thru 7/27/94, isolated and squeezed holes in casing 353 - 943', unable to obtain MIT. Conoco had repaired leaks in same interval in 1978 & 1986. Amerada Hess TA'd w/ CIBP& cmt set @ 3,859'.

1. Set steel pit and flow well down as needed.
2. MIRU plugging equipment. NU BOP. RIH w/ workstring to PBTD @ 3,923'.
3. RU cementer and circulate hole w/ plugging mud.
4. POOH w/ tubing to 2,651' and pump 25 sx C cmt 2,651 – 2,450'. **base of salt plug**
5. Perforate 4½" casing @ 1,460'. POOH w/ wireline.
6. RIH w/ packer to 1,000'. Load hole, set packer, and establish rate into perforations @ 1,460'. If rate is established, squeeze 40 sx C cmt w/ 2% CaCl<sub>2</sub> under packer, displacing to 1,250'. If unable to establish rate at 1,500 psi or less, POOH w/ packer and pump 25 sx C cmt w/ 2% CaCl<sub>2</sub> balanced plug @ 1,510'. WOC & TAG minimum 100' plug. **top of salt**
7. RIH w/ tubing to 405' and pump 30 sx C cmt 405' to surface. **surface casing shoe**
8. ND BOP and NU wellhead.
9. Cut off wellhead and install dryhole marker. Cut off anchors and level location.