

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 031695(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR

Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 1980' FEL OF SEC. 29

7. UNIT AGREEMENT NAME

WARREN UNIT

8. FARM OR LEASE NAME

WARREN UNIT McKEE

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

WARREN McKEE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 29, T. 20S, R. 38E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3534' DF

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☒MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Sand problems in this open hole completion make it desirable to install a slotted liner & gravel-slurry pack the open hole by the following method: Clean out w/ foam to 9006'. Go in hole w/ 5' blank 3 1/2" OD tubing w/ bottom bull-plugged, then 90' of 3 1/2" OD slotted & ribbed liner w/ 0.012" screen, then 30' blank 3 1/2" OD tubing. Otis cross-over tool, Otis permatrieve pkr., suc. seal unit & circ. device (Slurry pack eqpt.), then 2 3/8" OD tubing to sk. Centralize all 3 1/2" tubing @ every jt. Set pkr. Load annulus w/ gelled 2% KCL wtr. Mix slurry of 75 cu. ft. 20-40 mesh sd. in 500 gals. gelled 2% KCL wtr. Pump 7 bbls. gelled 2% KCL wtr., 20-40 mesh slurry & 3 bbls gelled 2% KCL wtr., displace w/ 2% KCL wtr. If no sand out occurs, mix & pump another batch of slurry. Pull service seal units & leave pkr. in well. Run prod. eqpt. & return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE

SR. ANALYST

DATE

5-2-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

USGS/5, NMEN-J, File