

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
 State Fee

5. State Oil & Gas Lease No.
 - - - - -

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name - - - - -
2. Name of Operator Skally Oil Company		8. Farm or Lease Name Baker "A"
3. Address of Operator P. O. Box 1351, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER D , 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 22S RANGE 37E NMPM.		10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3340' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER Eliminate waterflow behind 5" OD casing. <input checked="" type="checkbox"/>		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in workover rig. Pull rods and tubing.
- 2) Set retrievable bridge plug at 5000' and cap with 2 sacks sand.
- 3) Perforate 5" OD casing at 4375'.
- 4) Cement behind 5" OD casing with 200 sacks cement to eliminate waterflow.
- 5) WOC 36 hours. Test squeezed 5" OD casing perfs. and resqueeze, if necessary.
- 6) Pull retrievable bridge plug and clean out.
- 7) Return well to producing status pumping Drinkard perfs. 6380-6413'.

NOTE: Interval behind 5" OD casing to be cemented will be 3370-4407'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) D. R. Crow TITLE Lead Clerk DATE 12-13-74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: