

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions
reverse side)

CATE
JD re

Form approved. **W**
Budget Bureau No. 1004-0112
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

030139 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lynn

9. WELL NO.

2 (A)

10. SECTION, TOWNSHIP, OR RANGE

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 28 - T23S- R36E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Tenison Oil Company

3. ADDRESS OF OPERATOR

8140 Walnut Hill Lane, Ste. 601, Dallas, TX. 75231

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

990' from south line & 330' from E. line

Sec. 28 T23S R36E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3445 GL

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Estimated beginning of work - June 17, 1991

Workover Procedure

1. Pull rods, pump & tubing

2. Set retrievable bridge plug at 3170'.

3. Perforate as follows:

3163-65 - 4 shots

3150-55 - 10 shots

3142-44 - 4 shots

3130-32 - 4 shots

3116-21 - 10 shots

4. Run in hole with squeeze tool on tubing. Set tool at about 3090'.

5. Acidize above perforations with 1500 gallons of 15% acid.

6. Shut well in for one hour.

7. Swab test well.

8. Pull squeeze tool.

9. Retrieve bridge plug.

10. Run tubing, pump & rods. Put well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. S. Mach

TITLE Operations Manager

DATE June 6, 1990

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 6-26-91