

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|--|--|
| <p>1. OIL WELL <input checked="" type="checkbox"/> CAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. NAME OF OPERATOR Conoco Inc.</p> <p>3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240</p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL - Unit Letter B</p> | <p>5. LEASE DESIGNATION AND SERIAL NO. LC-030168B</p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME Eaves B-1</p> <p>9. WELL NO. 6</p> <p>10. FIELD AND POOL, OR WILDCAT Scarborough Yates 7 Rvs</p> <p>11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 31-26S-37E</p> <p>12. COUNTY OR PARISH 13. STATE Lea NM</p> |
| <p>14. PERMIT NO. 30-025-12088</p> | <p>15. ELEVATIONS (Show whether DF, RT, CR, etc.)</p> |

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|---|---|--|--|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> | WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> | FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> | SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input checked="" type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | (Other) _____ | |
| (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) | | | |

17. **DESCRIBE PROPOSED OR COMPLETED OPERATIONS** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and tools per-

PLUGGING RECORD: Bled down well. RU unit. Installed BOP. POH w/20 jts of 2-7/8" tbg. Made bit & scraper run w/7" scraper. RU WL. Ran 7" CIBP to 2900' & set. POH w/WL. GIH to 2900' & tagged CIBP. Mixed mud & circ hole clean. Press tst csg & CIBP & 500 psi for 15 min - held. Spotted 40 sx cmt on top of CIBP. Pulled 25 stds & WOC. GIH w/3-1/4" cone buster mill, 1 3-1/8" DC, 3-7/8" string mill, 7 3-1/8" DCS, & 2-7/8" WS to 468". Install stripperhead & power swivel. Est circ. GIH & start getting torque at 473.5'. Mill out to 476' in 4 hrs. Returns of redbed formation w/little cmt & few metal shavings. Stopped making hole at 476' - milled for 1 hr - lost torque. Circ clean. Remove power swivel & stripperhead. POH. String mill looked good. Cone buster mill was worn on btm & on btm edge. Order out & GIH w/new 3-1/4" concave mill w/rough OD, 1 3-1/8" DC, 3-7/8" string mill, 7 3-1/8" DCS, & 2-7/8" WS to 310'. GIH w/mill to 476'. Install stripperhead & power swivel. Est circ. Mill out fr 476'-478' in 3 hrs. Had good metal returns w/cmt & redbed. Fell thru at 478'. Circ clean. GIH w/mill to 491' & tag up. Returns changed to redbed. Circ hole clean. Remove power swivel & stripperhead. POH. GIH w/new 3-1/4" concave mill, 1 3-1/8" DC, 3-7/8" string mill, & 7 3-1/8" DCS on 2-7/8" WS. Install stripperhead & power swivel. Est circ. GIH & mill out fr 468'-479' w/600# - 700# torque. Returns of redbed, cmt & a little metal shavings. Circ hole clean. Remove power swivel & stripperhead. POH w/mill to 310'. POH & LD DCS & tools. GIH w/2-7/8" OE WS to 462'. MIRU Western. Circ hole w/5 BBL of FW. Mix & pmp 47 sx of Class "C" Neat cmt through 2-7/8" WS to surf. POH & LD 2-7/8" WS> ND BOP & tbg head. Mix & pmp 10 sx of cmt down 4-1/2" csg to refill to surf. RD cmt services & pulling unit. Dig out & around & cut 7-5/8" & 4-1/2" csg off 3' below ground level. Install BSA marker 4-1/2" csg & weld 1/4" plate to 4-1/2" & 7-5/8" pipe. Put deadman anchors off 1' below ground level & gack fill ground csg.

RECEIVED
 JUL 26 11 25 AM '88
 CARLSBAD AREA OFFICE

I hereby certify that the foregoing is true and correct

SIGNED: Cecil O. Scarborough TITLE: Administrative Supervisor DATE: July 22, 1988

(This space for a Federal or State office use)

APPROVED BY: _____ TITLE: _____ DATE: 7-28-88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side