

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)Form appd
Budget Bureau 12-11424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 18644	
2. NAME OF OPERATOR HNG Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 2267, Midland, TX 79702		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2140' FSL & 1787' FEL, Sec 8, T26S, R36E		8. FARM OR LEASE NAME Wilson 8 Federal	
14. PERMIT NO.		9. WELL NO. 5	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2971' GL		10. FIELD AND POOL, OR WILDCAT Sioux Tansill Yates Seven Rivers	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 8, T26S, R36E	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in well service unit. Nipple down pumping tee. Nipple up BOP. Pull 143 3/4" rods & insert pump. Pull 111 jts 2-3/8" 4.7# J-55 8rd EUE tbgs @ 3578'.
2. Pick up 5-1/2" cement retainer & trip in hole and set the retainer @ 3100'±. Pump 12 bbls 10 ppg brine into formation. Pull out of the retainer and circulate the hole with 10 ppg brine containing 25 sx gel/100 BW. Sting into the retainer and squeeze perms @ 3201-3562' with 90 sx class H cement. Pull out of retainer and leave 25' cement on top of retainer
3. Trip out of hole to 1460'. Spot 25 sx class H 2% CaCl from 1460-1360'. Trip out of hole to 90'. Spot 15 sx class H 2% CaCl from 90' to surface. Check top of plug-visual inspection.
4. Nipple down BOP and tubing spool, cut off head, weld on plate and dry hole marker, cut off anchors. Rig down well service unit.
5. Clean up location.

RECEIVED
JUN 1 1982

18. I hereby certify that the foregoing is true and correct

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

SIGNED

Bill Com

TITLE

Completion Engineer

DATE

5-27-82

(This space for Federal or State Office use)

APPROVED BY (Sig. Sgd.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 3 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side