Submit 1 Copy To Appropriate District Office	State of New 1		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 20-025-07623
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	TICES AND REPORTS ON WEL	LS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other: Injector		8. Well Number: 40	
2. Name of Operator		9. OGRID Number: 157984	
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		10. Fool name of whideat Hobbs (G/SA)	
4. Well Location			
	1980feet from theSouth	line and 1980	feet from the West line
Section 5	Township 19		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3629' (KB)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
			_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
	1		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or re	completion.		
1. MIRU PU and RU. Kill well, NDWH, NUBOP, pull injection packer. During this procedure we plan to u			
2. Set CIBP at 4050' (inside 4.5" partial liner) and bring cement to 50' above liner th			the closed-loop system with a steel
top (3813') and tag cement. tank and haul contents to the requi			
3. Circulate plugging mud from 3813' to 2800' d. Perforate 6.5/8" casing at 2750' squeeze compart for Vates/10.3/4" shoe disposal per ODC Rule 19.15.17			
 Perforate 6-5/8" casing at 2750' squeeze cement for Yates/10-3/4" shoe. Bring cement to 2650' inside 6-5/8" and tag TOC. 			
 Circulate plug mud to 1600' and perforate casing for Rustler plug. 			
7. Squeeze at 1600' and attempt to circulate cement to surface on both strings.			
8. Circulate plug mud to surface and perforate at 150'.			
9. Squeeze cement and verify cement to surface on all strings.			
 Rig down pulling unit, cut off wellhead and install marker, 4" diameter and 4' tall. Remove anchors and debris 			
11. Remove anchors and debris			
Spud Date:	Rig Release	e Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby courty and the final above is the and complete to the best of my knowledge and bench.			
Int			
SIGNATURE			
Type or print name <u>Jake Perry</u> E-mail address: <u>Jake Perry@oxy.com</u> PHONE: <u>713-215-7546</u>			
For State Use Orly			
<u>rereturt</u>		ry@oxy.com	_ PHONE: <u>/13-215-/546</u>
APPROVED BY: William V.	William V. Jones	<u>ry@oxy.com</u> Engineer	_ PHONE: <u>/13-215-/546</u>

Conditions of Approval (if any):



