

Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-33873
5. Indicate Type of Lease STATE [X] FEE [ ]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name JACKSON UNIT SWD
8. Well Number 0005
9. OGRID Number 372043
10. Pool name or Wildcat SWD; BELL CANYON-CHERRY CANYON
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3619' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [ ] Gas Well [ ] Other [X]
2. Name of Operator TAP ROCK OPERATING, LLC
3. Address of Operator 523 PARK POINT DR, SUITE 200, GOLDEN, CO 80401
4. Well Location Unit Letter H, 1980 feet from the NORTH line and 660 feet from the EAST line. Section 16, Township 24S, Range 33E, NMPM, County LEA.

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [X]
TEMPORARILY ABANDON [ ] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ] MULTIPLE COMPL [ ]
DOWNHOLE COMMINGLE [ ]
CLOSED-LOOP SYSTEM [ ]
OTHER: [ ]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS. [ ] P AND A [ ]
CASING/CEMENT JOB [ ]
OTHER: [ ]

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Tap Rock Operating is requesting to permanently plug and abandon the Jackson Unit 5 SWD well. This P&A job will meet NMOCD standards and be adjusted to fit NMOCD conditions of approval. Please see the attached procedure, current wellbore schematic, and proposed plugging schematic for more detail.

4" Diameter 4' Tall above Ground marker

See Attached Conditions of Approval

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Regulatory Analyst DATE 3/1/2021

Type or print name Bill Ramsey E-mail address: bramsey@taprk.com PHONE: 720-238-2787

For State Use Only

APPROVED BY: [Signature] TITLE Compliance Officer A DATE 3/4/21
Conditions of Approval (if any):

## Jackson Unit #5

API: 30-025-33873

Sec 16-T24S-R33E

Lea County, NM

### Basic Wellbore Construction Data:

Casing Data			
Size O.D.	Weight	Depth	TOC
13.375"	72 ppf	490'	Surface
9.625"	47 ppf	5,287'	Surface'
7"	29 ppf	12,620'	5,225'
Tubing Data			
3.5"	9.3 ppf	5,400'	
Open Perforations			
5,516'-7,325'			
Plugged Perforations			
13,213' – 13,781' - WC			

### Objective:

Plug and Abandon well per NMOCD specifications. **Regulatory office (Hobbs) does require a 24 hr notice prior to commencing plugging operations.**

### Safety:

All Personnel MUST wear hard hats, steel toed boots, and safety glasses.

No smoking inside rig anchors.

Hold a job safety meeting each morning, and as needed before specific job tasks.

### Procedure:

- 1) MIRU PU.
- 2) Bleed off any well head pressures. Kill well if necessary.
- 3) ND WH & NU BOP.
- 4) POOH w/Tbg, pkr and LD.
- 5) Set CIBP at 5,500' w/50' cmt on top, WOC
- 6) Set bal. plug 5,100' **P&S 100 Sx Class C 5100 will be combined with Step 7**
- 7) Perf & squeeze @ 5,000', add +50' cmt on top, WOC
- 8) CIBP set @ 2,500' w/+30' cmt, WOC **P&S 50 sx Class C 1200' Top of salt**
- 9) Perf & squeeze @ 250', pump cmt until seen on surf, WOC
- 10) Cut off wellhead, verify cement in annulus, and install "FLAT" dry hole marker, per NMOCD requirements. **4" Diameter 4' tall above ground marker**
- 11) RDMO PU, and aux equipment. Clean location of all debris, and prep location to initiate final reclamation procedures per NMOCD.

RP 3/1/2021

**Tap Rock Production**

**Current Configuration**

Wellbore Sketch by: Rakesh Patel 1/26/2021

**Jackson Unit #5**

S16 T24S R33E  
Lea County, NM  
API 30-025-33873

Lat. 32.2194672, Long. -103.5708466  
Spud Date: May 17, 1997

Surf. csg 13.375" 72. lb/ft J-55 set @ 490' to Surf  
Cmt'd w/490 sx with Class C. TOC @ Surface  
17.5" Hole size

GR: 3619'

Int. 9.625" 47#/ft set @ 5,287'  
Cmt'd w/1,575 sx with Class C. TOC @ surf  
12.25" Hole size

Prod. 7" 29#/ft P-110 set @ 12,620'  
Cmt'd w/1,060 sx with Class. TOC @ 5,225'  
8.625" Hole size

TBG 3.5" 9.3#/ft J-55 Plastic Lined

Packer type and set ~5,466'

Perfs: 5,516' - 7,325' Cherry

CIBP set @ 7,460' w/+35' cmt

Bal. plug 9,078' - 9,178'

Bal. plug 12,166' - 12,670'

CIBP @ 13,200' w/+35' cmt

Perfs: 13,213' - 13,781' Wolfcamp

PBTD 13,870'  
TD 13,908'  
Not to Scale

Tap Rock Production


Proposed Configuration

Wellbore Sketch by: Rakesh Patel 1/26/2021

Jackson Unit #5

S16 T24S R33E  
Lea County, NM  
API 30-025-33873

Lat. 32.2194672, Long. -103.5708466 Spud  
Date: May 17, 1997



**CONDITIONS OF APPROVAL  
FOR PLUGGING AND ABANDONMENT  
OCD - Southern District**

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at **(575)-263-6633** at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

**Company representative will be on location during plugging procedures.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water will not be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - I) Glorieta
  - J) Yates.
  - K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

**DRY HOLE MARKER REQ.UIRMENTS**

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least 1/4" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

**SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS**

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

**SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION**

## Jackson Unit #5

API: 30-025-33873

Sec 16-T24S-R33E

Lea County, NM

### Basic Wellbore Construction Data:

Casing Data			
Size O.D.	Weight	Depth	TOC
13.375"	72 ppf	490'	Surface
9.625"	47 ppf	5,287'	Surface'
7"	29 ppf	12,620'	5,225'
Tubing Data			
3.5"	9.3 ppf	5,400'	
Open Perforations			
5,516'-7,325'			
Plugged Perforations			
13,213' – 13,781' - WC			

### Objective:

Plug and Abandon well per NMOCD specifications. **Regulatory office (Hobbs) does require a 24 hr notice prior to commencing plugging operations.**

### Safety:

All Personnel MUST wear hard hats, steel toed boots, and safety glasses.

No smoking inside rig anchors.

Hold a job safety meeting each morning, and as needed before specific job tasks.

### Procedure:

- 1) MIRU PU.
- 2) Bleed off any well head pressures. Kill well if necessary.
- 3) ND WH & NU BOP.
- 4) POOH w/Tbg, pkr and LD.
- 5) Set CIBP at 5,500' w/50' cmt on top, WOC
- 6) Set bal. plug 5,100'
- 7) Perf & squeeze @ 5,000', add +50' cmt on top, WOC
- 8) CIBP set @ 2,500' w/+30' cmt, WOC
- 9) Perf & squeeze @ 250', pump cmt until seen on surf, WOC
- 10) Cut off wellhead, verify cement in annulus, and install "FLAT" dry hole marker, per NMOCD requirements.
- 11) RDMO PU, and aux equipment. Clean location of all debris, and prep location to initiate final reclamation procedures per NMOCD.

RP 3/1/2021

**Tap Rock Production**

**Current Configuration**

Wellbore Sketch by: Rakesh Patel 1/26/2021

**Jackson Unit #5**

S16 T24S R33E  
Lea County, NM  
API 30-025-33873

Lat. 32.2194672, Long. -103.5708466  
Spud Date: May 17, 1997

Surf. csg 13.375" 72. lb/ft J-55 set @ 490' to Surf  
Cmt'd w/490 sx with Class C. TOC @ Surface  
17.5" Hole size

GR: 3619'

Int. 9.625" 47#/ft set @ 5,287'  
Cmt'd w/1,575 sx with Class C. TOC @ surf  
12.25" Hole size

Prod. 7" 29#/ft P-110 set @ 12,620'  
Cmt'd w/1,060 sx with Class. TOC @ 5,225'  
8.625" Hole size

TBG 3.5" 9.3#/ft J-55 Plastic Lined

Packer type and set ~5,466'

Perfs: 5,516' - 7,325' Cherry

CIBP set @ 7,460' w/+35' cmt

Bal. plug 9,078' - 9,178'

Bal. plug 12,166' - 12,670'

CIBP @ 13,200' w/+35' cmt

Perfs: 13,213' - 13,781' Wolfcamp

PBTD 13,870'  
TD 13,908'  
Not to Scale

### Tap Rock Production

### Jackson Unit #5


S16 T24S R33E  
Lea County, NM  
API 30-025-33873

### Proposed Configuration

Wellbore Sketch by: Rakesh Patel 1/26/2021

Lat. 32.2194672, Long. -103.5708466 Spud

Date: May 17, 1997



**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

COMMENTS

Action 19247

**COMMENTS**

Operator: TAP ROCK OPERATING, LLC Suite 200 Golden, CO80401	523 Park Point Drive	OGRID: 372043	Action Number: 19247	Action Type: C-103F
---	----------------------	------------------	-------------------------	------------------------

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	03/04/2021

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 19247

**CONDITIONS OF APPROVAL**

Operator: TAP ROCK OPERATING, LLC      523 Park Point Drive Suite 200      Golden, CO80401		OGRID: 372043	Action Number: 19247	Action Type: C-103F
OCD Reviewer kfortner	Condition See attached conditions of approval Note changes to procedure			