Energy, Minerals and Natural Resources Revited July 18, 2013	Received by OCL	o Appropriate Bistill		State of New M			Form C-103 ¹ of 9		
SILE TEN S. Amesia, SM 8210 Diance III - 2003 54-1078 1078 Santa Fe, NM 87505 SINDRY NOTICES AND REPORTS ON WILLS SUNDRY NOTICES AND REPORTS ON WILLS SURDRY NOTICES AND REPORTS ON WILLS Address of Operator America energy resources, LLC: 3. Address of Operator America energy resources, LLC: 3. Address of Operator America energy resources, LLC: 4. Well Location Unit Letter H; 1980	District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION				WELL API NO.	Revised July 18, 2013			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion reversity and bleed of the University Scrippin hole with 27/8" ms. joint on tested 27.8" work string. Clear bore hole to top of pared 2-3/8" tubing at 2625" Children and pared to this proposed to completion or secondpletion or second proposed completion or secondpletion or secondpletion or secondpletion or second proposed completion or secondpletion or secondpletion or second proposed completion or second proposed completion or second proposed completion or second proposed completion or second proposed second seco						f Lease			
12.0 S. Francis Dr., Surar Fr. NM System Sundry Notifices And Reports on Wells Sundry Notifices And Reports on Wells Sundry Notifices	1000 Rio Brazos	Rd., Aztec, NM 874				STATE x	FEE		
SUNDRY NOTICES AND REPORTS ON WELLS	<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/505 1220 S. St. Francis Dr., Santa Fe, NM				6. State Oil & Gas	s Lease No.			
V 1. Type of Well: Oil Well	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					Unit Agreement Name			
3. Address of Operator 7575 San Felipe, Suite 200. Houston, TX 77063 10. Pool name or Wildcat 4. Well Location Unit Letter H : 1980		ype of Well: Oil	Well 🛛 Gas	Well Other		8. Well Number 2	1-1		
4. Well Location Unit Letter_H_: 1980feet from the _North line and760'feet from the	2. Name of C	Operator Americo	energy resources,	LLC		9. OGRID Numbe	9. OGRID Number		
Unit Letter H : 1980 feet from the North line and 760' feet from the East line Section 21 Township 20S Range 25E NMPM County Eddy 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3461' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON GHANGE PLANS COMMENCE DRILLING OPNS. PAND A DOWNHOLE COMMINGE CLOSED-LOOP SYSTEM OWLED OF COMMINGE CLOSED-LOOP SYSTEM OTHER: DOWNHOLE COMMINGE OTHER: DOWNHOLE COMMINGE OTHER: DOWNHOLE OF COMMINGE OTHER: DOWNHOLE OT	3. Address of	f Operator 7575	San Felipe, Suite 2	00. Houston, TX 770	063	10. Pool name or	Wildcat		
East line Section 21 Township 208 Range 25E NMPM County Eddy	4. Well Loca	tion							
Section 21 Township 20S Range 25E NMPM County Eddy			:1980	feet from the _N	North line	and760'	feet from the		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3461' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHAMGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB Notify OCD 24 hrs. prior to any work done OWNHOLE COMMINGLE CHAMGE PLANS OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent datals, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and sall water out of wellbore, Pools with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560" above 2-3/8" parted tubing. 9- Mix, pump and squeeze X 4ks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560" to 2130°, pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560" to 2130°, pull in clear and wait on cement 5 hours to set 10-perforated 8-5/8" casing for squeeze at 1450'! 11-Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380° 11-Mix pump and squeeze 60 sks class "C" cement from 1450' to 1380° 11-Mix pump and squeeze 60				Township 20S	Range 25	E NMPM	County Eddy		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			11. Elevatio	n (Show whether DF					
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A DOWNHOLE COMMINGLE CASING/CEMENT JOB Notify OCD 24 hrs. prior to any work OTHER: P/A 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9-Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and sct plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and sct plug from 2500' to 2130', pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450! 11- Mix, pump and squeeze of 0 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze of 0 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze of 0 sks class "C" cement from 1450' to 1380' 11- Mix pump and squeeze of 0 sks class "C" cement from 1450' to 1380' 11- Mix pump and squeeze of 0 sks class "C" cement from 1450' to 1380' 11- Mix pump and squeeze of 0 sks class "C" cemen			34	61'					
PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: P/A 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 22-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3R Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 11- Mix, pump and squeeze 80 sks class "C" cement from 1450' to 1380' 12- Wait on cement - Rig down workover rig and P/A equipment 13- excavate & dig around the wellbead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Must be plugged by 8/8/2022		12. Che	ck Appropriate	Box to Indicate N	Nature of Not	ice, Report or Other 1	Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: P/A 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 22-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3R Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 11- Mix, pump and squeeze 80 sks class "C" cement from 1450' to 1380' 12- Wait on cement - Rig down workover rig and P/A equipment 13- excavate & dig around the wellbead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Must be plugged by 8/8/2022		NOTICE OF	FINTENTION	TO:		UBSEQUENT REF	PORT OF:		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB Notify OCD 24 hrs. prior to any work done OTHER: PIA OTHER	PERFORM R		_	_					
Notify OCD 24 hrs. prior to any work done CloseD-LOOP SYSTEM						-			
OTHER: P/A 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 7-7/8" ms, joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9-Mix, pump and squeeze \(\frac{1}{2} \) sin \(\frac{1}{2} \) cement and distplace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear and wait on cement 5 hours to set 10-perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 12- Wait on cement - Rig down workover rig and P/A equipment 13-excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date: Wust be plugged by 8/3/2022			_	COMPL					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 1510 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 13							or to any work		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-Inform Oil Conservation Division before moving a rig to the well location 2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8° ms. joint on tested 2-7/8° work string. Clear bore hole to top of parted 2-3/8° tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8° inflatable packer on work string. Set packer at 2560' above 2-3/8° parted tubing. 9- Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 1210 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8° casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze both search of teaks 12- Wait on cement - Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date: Must be plugged by 8/3/2022	OTHER: P/A		_		OTHER:	done			
2-Move in and rig up workover rig to the well. Spot reverse unit and fill up the pit with 10 ppg drilling mud 3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze \(\frac{1}{2} \) sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" ceme	of star	rting any propose	ed work). SEE RUI						
3-Open well, read and record pressures 4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze (2) sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C cmt set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze for ske class "C" cement from 1450' to 1380' 12- Wait on cement - Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Must be plugged by 8/3/2022	1-Inform Oil C	Conservation Divi	sion before moving	g a rig to the well loc	cation				
4-Flow and bleed off well pressure and fluid into the rig tank slowly 5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze for strip from 15' to ground surface 12- Wait on cement — Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: Must be plugged by 8/3/2022				ot reverse unit and fi	ill up the pit wit	h 10 ppg drilling mud			
5-Nipple down wellhead and install 3K Blowout preventer. Test BOP stack 200 psi and 1000 psi 6-Trip in hole with 2-7/8" ms. joint on tested 2-7/8" work string. Clear bore hole to top of parted 2-3/8" tubing at 2625 ' 7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze ¼ sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date: Must be plugged by 8/3/2022				he rig tank slowly					
7-Cirulate wellbore with 9.5 ppg drilling mud to remove oil, gas and salt water out of wellbore, Pooh with work string 8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9-Mix, pump and squeeze \$\frac{2}{2}\$ sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C cmt set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and sot plug from 15' to ground aurface 12- Wait on cement - Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: Must be plugged by 8/3/2022	5-Nipple down	wellhead and ins	stall 3K Blowout p	reventer. Test BOP s					
8-Trip in hole with 7-7/8" inflatable packer on work string. Set packer at 2560' above 2-3/8" parted tubing. 9- Mix, pump and squeeze									
9- Mix, pump and squeeze X sks "C" cement and displace below the packer. Pull in clear and wait on cement 10-Tag and record cement depth 8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C cmt set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and sat plug from 15' to ground surface 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Rig Release Date: Must be plugged by 8/3/2022 Must be plugged by 8/3/2022							. string		
8-Mix and pump 130 sks "C" cement and set plug from 2560' to 2130', pull in clear 9-Mix and pump 130 sks "C cmt set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and set plug from 15' to ground surface 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: Alix pump and squeeze 60 sks class "C" cement from 1450' to 1380' COA #16	9- Mix, pump a	and squeeze 💥 sl	ks "C" cement and				Be prepared to pump 2x volume		
9-Mix and pump 130 sks "C cmt set plug from 2130 to 1705' pull in clear and wait on cement 5 hours to set 10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and set plug from 15' to ground surface 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Rig Release Date: WOC & Tag - check for leaks COA #16 WOC & Tag - check for leaks COA #16 Perf @ 400' & attempt to circ 130 sx cmt to surf				r from 2560° to 2130)' null in clear				
10- perforated 8-5/8" casing for squeeze at 1450'! 11- Mix, pump and squeeze 60 sks class "C" cement from 1450' to 1380' 11- Mix, pump and set plug from 15' to ground surface 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: Available COA #16 COA #16						on cement 5 hours to set	WOC & Tag - check for leaks		
11- Mix, pump and set plug frem 15' to ground surface 12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date: Must be plugged by 8/3/2022				. 6 14500	WOC & Tag	- check for leaks			
12- Wait on cement – Rig down workover rig and P/A equipment 13- excavate & dig around the wellhead using backhoe 14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date:						0' & attempt to circ 130 sx cm	ut to surf		
14- Cut, and remove all casing strings at 4 feet below the surface ground and cap off 15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date:	12- Wait on ce	ment – Rig down	workover rig and	P/A equipment					
15- Install a well ID pipe as required by OCD and fill up voids with clean soil/cement and level off location 16- Clear, and Clean up location and move off Spud Date: 3/15/2022 Rig Release Date: ****SEE ATTACHED COA's**** Must be plugged by 8/3/2022					nd and aan off				
Spud Date: 3/15/2022 Rig Release Date:						and level off location			
****SEE ATTACHED COA's**** Must be plugged by 8/3/2022	16- Clear, and	Clean up location	n and move off						
****SEE ATTACHED COA's**** Must be plugged by 8/3/2022	г			٦			\neg		
	Spud Date:	3/15/2022		Rig Release D	rate:				
	D olomo de la				Must be p	olugged by 8/3/2022			

SIGNATURE_	ndi Sodraha	TITLE	Petroleum Engineer	_DATE	2/1/2022
Type or print name	Mehdi Sadeghi	E-mail address:	mehdi.sadeghi@americoenergy.com	PHONE: 7	713-984-9700
For State Use Only					
APPROVED BY:Conditions of Approval (i		>_TITLE	Staff Manager	_DATE_	2/3/2022

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K)Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S - R 30E

Sec 1 – Sec 36

T 21S - R 31E

Sec 1 – Sec 36

T 22S - R 28E

Sec 36 Unit A,H,I,P.

T 22S - R 29E

Sec 1. Sec 2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S - R 30E

Sec 1 – Sec 36

T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S - R 28E

Sec 1 Unit A

T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

Stiletto '21' Federal Com #1

API # 30-015-33096

Spud 1/17/2004

Current Wellbore

13-3/8", 48#, H-40, ST&C @ 358' w/ 425 sx Poz Class "C" to Surf

8-5/8", 24#, J-55, LT&C @ 1525' w/ 875 sx Poz Class "C" to Surf

Top of 4-1/2" casing fish at 2673', Top of 2-3/8" @ 2625 (corroded away)

4-1/2" CSG Patch @ 3618'

AS1X 10K Packer @ 9197'

Upper Marrow- 9356'-9415'


plug @ 9430'

Marrow- 9461'-9630'

4-1/2", 11.6#, N-80, LT&C @ 9800' w/ 850 sx Poz Class "H" to 6700'

PBTD: 9756' MD'

TD: 9800' MD'



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 77537

CONDITIONS

Operator:	OGRID:
AMERICO ENERGY RESOURCES LLC	228051
7575 San Felipe	Action Number:
Houston, TX 77063	77537
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Cr	eated By	Condition	Condition Date	
g	cordero	None	2/3/2022	