

Office
 District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM
 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator		6. State Oil & Gas Lease No.
3. Address of Operator		7. Lease Name or Unit Agreement Name
4. Well Location Unit Letter _____: _____ feet from the _____ line and _____ feet from the _____ line Section _____ Township _____ Range _____ NMPM _____ County _____		8. Well Number
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**Condition of Approval: notify
 OCD Hobbs office 24 hours
 prior of running MIT Test & Chart**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE alicia fulton TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 3/2/22

Conditions of Approval (see rule 19.15.7.14 NMAC)



Date: November 8, 2021
From: Wyatt Brennan
Subject: NMGSAU #605W HIC Repair

Summary

The purpose of this procedure is to POOH w/injection string, isolate and squeeze HIC, and RWTI.

Procedure

1. Hold JSA and safety meeting. (Every Morning or at change of operations.)
2. RU WSU and pump truck loaded with 10# brine. Pump TBG capacity +10% of Brine. If well is still not dead shut in well and take note of TBG and CSG pressures. Consult with workover engineer.
3. ND WH, NU BOP to pull TBG. Release Packer and pump CSG capacity of 10# brine.
4. POOH with injection string and LD packer.
5. PU 2-3/8" workstring and RIH with plug and packer. Set RBP no lower than previous packer depth. PU one joint and set packer. Pump down TBG and test to 500#. If RBP holds, load and test backside. If no test, work to isolate leak.
6. Once leak is isolated, pump in and try to establish rate. Take note of rate and pressure, call workover engineer to discuss.
7. TIH to RBP and dump 20' sand on top of plug and TOOH.
8. RU WL and RIH with 7" CICR and set 100' above top of leak. POOH w/WL and RDMO.
9. Make-up stinger and RIH with workstring. Circulate hole with water to ensure wellbore is full.
10. RU cement and mix cement for squeeze, sting into retainer and pump squeeze. Make sure to not go above 1,500# TBG while pumping. Call workover engineer if pump in pressures are above 1,000#.

- a. When cement pressure 'locks up' shut in pumps and wait 1-2 minutes.
 - b. Roll pumps until 'lock-up' and repeat step 9a until formation doesn't take anymore cement. (Call engineering if hesitations exceed 2 cycles.)
 - c. Sting out and reverse circulate TBG until returns are clear of cement.
 - d. POOH and let cement sit overnight.
11. Make-up bit and sub BHA and RIH to top of retainer to drill out.
 - a. RU reverse unit and set down 1-2 points over string weight to drill out.
 - b. Monitor returns for plug parts and make drill out adjustments as needed.
 - i. If metal shavings are coming back through returns, pick up, circulate, and call workover engineer for steps forward.
12. Once drilled through retainer and cement, TIH a couple stands and circulate one bottoms up or until returns are clean.
13. Close BOP pipe rams and test casing to 500#. If good test, resume ops as per procedure.
If no test, call workover engineer for steps forward
14. TOOH with workstring and break out bit. Make-up RBP retrieving tool and TIH to RBP.
15. Wash sand from top of plug and circulate brine water in the wellbore. Retrieve RBP and TOOH.
16. RU TBG tester and RIH testing to 5000# with same TBG design.
17. ND BOP, NU WH and turn over to production to RWTP.

Spud Date:
2/2/1936

Apache Corporation – NMGSAU #605 W

Wellbore Diagram – Current Status

Date : 9/19/2016

API: 30-025-05654

Surface Location K. Grisham



1980' FNL & 660' FWL, Unit E
Sec 20, T19S, R37E, Lea County, NM

Surface Casing
12-1/2" 40# @ 190' w/ 150 sx to surface

Intermediate Casing
9-5/8" 32# @ 2476' w/ 500 sx to surface

Hole Size
=17-1/2"

Hole Size
=11"

5/36: Original completion. Acidized w/ 4000 gals acid.
5/67: String shot 300 & 500 grains/ ft over OH fr/ 3853-3988'. Acidized OH fr/ 3851-3996' w/ 1000 gals 15% NE acid.
6/83: Tagged fill @ 3971'. CO fr/ 3971-3996'. String shot OH fr/ 3870-3983' w/ 400 gm/ ft. Perf OH w/ 80 gm @ 3870', 3872', 3874', 3890', 3892', .914', 3916', 3928', 3938', 3940', 3952', 3954', 3960', 3970', 3975' & 3821. Acidized OH fr/ 3851-3996' w/ 2500 gals 15% NEFE.
5/93: Tagged fill @ 3965' (31' of fill). CO well. Located leak between surf - 2448'. 7" csg 100% free to 2550'. Shoot holes @ 2487', cmt sqz csg w/ 450 sxs, circ out 9-5/8" csg. Tag fill @ 3964', CO to TD 3996'.
8/96: String shot OH w/ 400 grain/ft fr/ 3854-3988'. CO to TD. Perf fr/ 3796-3850' w/ 2 jspf (109 holes). Acidize perfs & OH w/ 5000 gals 15% NEFE. RIH w/ injection equipment. Well converted to injection.
3/01: CO fill fr/ 3984' to TD @ 3996'.

Hole Size
=8-3/4"

Hole Size
=6-1/4"

Production Casing
7" 24# @ 3851' w/ 100 sxs

TD =3996'

Spud Date:
2/2/1936

Apache Corporation – NMGSAU #605 W

Wellbore Diagram – Current Status

Date : 9/19/2016

API: 30-025-05654

Surface Location K. Grisham



1980' FNL & 660' FWL, Unit E
Sec 20, T19S, R37E, Lea County, NM

Surface Casing
12-1/2" 40# @ 190' w/ 150 sx to surface

Intermediate Casing
9-5/8" 32# @ 2476' w/ 500 sx to surface

Hole Size
=17-1/2"

Hole Size
=11"

5/36: Original completion. Acidized w/ 4000 gals acid.
5/67: String shot 300 & 500 grains/ ft over OH fr/ 3853-3988'. Acidized OH fr/ 3851-3996' w/ 1000 gals 15% NE acid.
6/83: Tagged fill @ 3971'. CO fr/ 3971-3996'. String shot OH fr/ 3870-3983' w/ 400 gm/ ft. Perf OH w/ 80 gm @ 3870', 3872', 3874', 3890', 3892', .914', 3916', 3928', 3938', 3940', 3952', 3954', 3960', 3970', 3975' & 3821. Acidized OH fr/ 3851-3996' w/ 2500 gals 15% NEFE.
5/93: Tagged fill @ 3965' (31' of fill). CO well. Located leak between surf - 2448'. 7" csg 100% free to 2550'. Shoot holes @ 2487', cmt sqz csg w/ 450 sxs, circ out 9-5/8" csg. Tag fill @ 3964', CO to TD 3996'.
8/96: String shot OH w/ 400 grain/ft fr/ 3854-3988'. CO to TD. Perf fr/ 3796-3850' w/ 2 jspf (109 holes). Acidize perfs & OH w/ 5000 gals 15% NEFE. RIH w/ injection equipment. Well converted to injection.
3/01: CO fill fr/ 3984' to TD @ 3996'.

Hole Size
=8-3/4"

Hole Size
=6-1/4"

Production Casing
7" 24# @ 3851' w/ 100 sxs

TD =3996'



Date: November 8, 2021
From: Wyatt Brennan
Subject: NMGSAU #605W HIC Repair

Summary

The purpose of this procedure is to POOH w/injection string, isolate and squeeze HIC, and RWTI.

Procedure

1. Hold JSA and safety meeting. (Every Morning or at change of operations.)
2. RU WSU and pump truck loaded with 10# brine. Pump TBG capacity +10% of Brine. If well is still not dead shut in well and take note of TBG and CSG pressures. Consult with workover engineer.
3. ND WH, NU BOP to pull TBG. Release Packer and pump CSG capacity of 10# brine.
4. POOH with injection string and LD packer.
5. PU 2-3/8" workstring and RIH with plug and packer. Set RBP no lower than previous packer depth. PU one joint and set packer. Pump down TBG and test to 500#. If RBP holds, load and test backside. If no test, work to isolate leak.
6. Once leak is isolated, pump in and try to establish rate. Take note of rate and pressure, call workover engineer to discuss.
7. TIH to RBP and dump 20' sand on top of plug and TOOH.
8. RU WL and RIH with 7" CICR and set 100' above top of leak. POOH w/WL and RDMO.
9. Make-up stinger and RIH with workstring. Circulate hole with water to ensure wellbore is full.
10. RU cement and mix cement for squeeze, sting into retainer and pump squeeze. Make sure to not go above 1,500# TBG while pumping. Call workover engineer if pump in pressures are above 1,000#.

- a. When cement pressure 'locks up' shut in pumps and wait 1-2 minutes.
 - b. Roll pumps until 'lock-up' and repeat step 9a until formation doesn't take anymore cement. (Call engineering if hesitations exceed 2 cycles.)
 - c. Sting out and reverse circulate TBG until returns are clear of cement.
 - d. POOH and let cement sit overnight.
11. Make-up bit and sub BHA and RIH to top of retainer to drill out.
- a. RU reverse unit and set down 1-2 points over string weight to drill out.
 - b. Monitor returns for plug parts and make drill out adjustments as needed.
 - i. If metal shavings are coming back through returns, pick up, circulate, and call workover engineer for steps forward.
12. Once drilled through retainer and cement, TIH a couple stands and circulate one bottoms up or until returns are clean.
13. Close BOP pipe rams and test casing to 500#. If good test, resume ops as per procedure.
- If no test, call workover engineer for steps forward
14. TOOH with workstring and break out bit. Make-up RBP retrieving tool and TIH to RBP.
15. Wash sand from top of plug and circulate brine water in the wellbore. Retrieve RBP and TOOH.
16. RU TBG tester and RIH testing to 5000# with same TBG design.
17. ND BOP, NU WH and turn over to production to RWTP.

Spud Date:
2/2/1936

Apache Corporation – NMGSAU #605 W

Wellbore Diagram – Current Status

Date : 9/19/2016

API: 30-025-05654


Surface Location K. Grisham



1980' FNL & 660' FWL, Unit E
Sec 20, T19S, R37E, Lea County, NM

Surface Casing
12-1/2" 40# @ 190' w/ 150 sx to surface

Intermediate Casing
9-5/8" 32# @ 2476' w/ 500 sx to surface



5/36: Original completion. Acidized w/ 4000 gals acid.
5/67: String shot 300 & 500 grains/ ft over OH fr/ 3853-3988'. Acidized OH fr/ 3851-3996' w/ 1000 gals 15% NE acid.
6/83: Tagged fill @ 3971'. CO fr/ 3971-3996'. String shot OH fr/ 3870-3983' w/ 400 gm/ ft. Perf OH w/ 80 gm @ 3870', 3872', 3874', 3890', 3892', .914', 3916', 3928', 3938', 3940', 3952', 3954', 3960', 3970', 3975' & 3821. Acidized OH fr/ 3851-3996' w/ 2500 gals 15% NEFE.
5/93: Tagged fill @ 3965' (31' of fill). CO well. Located leak between surf - 2448'. 7" csg 100% free to 2550'. Shoot holes @ 2487', cmt sqz csg w/ 450 sxs, circ out 9-5/8" csg. Tag fill @ 3964', CO to TD 3996'.
8/96: String shot OH w/ 400 grain/ft fr/ 3854-3988'. CO to TD. Perf fr/ 3796-3850' w/ 2 jspf (109 holes). Acidize perfs & OH w/ 5000 gals 15% NEFE. RIH w/ injection equipment. Well converted to injection.
3/01: CO fill fr/ 3984' to TD @ 3996'.

Production Casing
7" 24# @ 3851' w/ 100 sxs

Spud Date:
2/2/1936

Apache Corporation – NMGSAU #605 W

Wellbore Diagram – Current Status

Date : 9/19/2016

API: 30-025-05654

Surface Location K. Grisham



1980' FNL & 660' FWL, Unit E
Sec 20, T19S, R37E, Lea County, NM

Surface Casing
12-1/2" 40# @ 190' w/ 150 sx to surface

Intermediate Casing
9-5/8" 32# @ 2476' w/ 500 sx to surface

Hole Size
=17-1/2"

Hole Size
=11"

5/36: Original completion. Acidized w/ 4000 gals acid.
5/67: String shot 300 & 500 grains/ ft over OH fr/ 3853-3988'. Acidized OH fr/ 3851-3996' w/ 1000 gals 15% NE acid.
6/83: Tagged fill @ 3971'. CO fr/ 3971-3996'. String shot OH fr/ 3870-3983' w/ 400 gm/ ft. Perf OH w/ 80 gm @ 3870', 3872', 3874', 3890', 3892', .914', 3916', 3928', 3938', 3940', 3952', 3954', 3960', 3970', 3975' & 3821. Acidized OH fr/ 3851-3996' w/ 2500 gals 15% NEFE.
5/93: Tagged fill @ 3965' (31' of fill). CO well. Located leak between surf - 2448'. 7" csg 100% free to 2550'. Shoot holes @ 2487', cmt sqz csg w/ 450 sxs, circ out 9-5/8" csg. Tag fill @ 3964', CO to TD 3996'.
8/96: String shot OH w/ 400 grain/ft fr/ 3854-3988'. CO to TD. Perf fr/ 3796-3850' w/ 2 jspf (109 holes). Acidize perfs & OH w/ 5000 gals 15% NEFE. RIH w/ injection equipment. Well converted to injection.
3/01: CO fill fr/ 3984' to TD @ 3996'.

Hole Size
=8-3/4"

Hole Size
=6-1/4"

Production Casing
7" 24# @ 3851' w/ 100 sxs

TD =3996'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 80418

CONDITIONS

Operator: APACHE CORPORATION 303 Veterans Airpark Ln Midland, TX 79705	OGRID: 873
	Action Number: 80418
	Action Type: [C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Run Post Workover MIT test	3/2/2022